

Consumer Alert: Subaru Issues Do Not Drive, Recall on Select MY21 Impreza Vehicles

Affected owners advised not to drive vehicles until recall repair is completed

Share:

September 1, 2021

Subaru of America has issued a do not drive notice and recall on select Model Year 2021 Impreza vehicles. This notice and recall involves 802 Model Year 2021 Impreza vehicles.

A lower control arm weld on the front driver's side may fail on affected vehicles. If this happens, the tire could contact the wheel well, resulting in a loss of control and increasing the risk of a crash.

Vehicle owners can visit [NHTSA.gov/recalls](https://www.nhtsa.gov/recalls) or call NHTSA's Vehicle Safety Hotline at [888-327-4236](tel:888-327-4236) and enter their 17-digit vehicle identification number to see if their vehicle is under recall. If it is, the owner should not drive the vehicle until the recall repair is completed. Owners may also contact Subaru's customer service at [844-373-6614](tel:844-373-6614).

NHTSA encourages everyone to download the [SaferCar app](#) to stay informed on current recalls.

Contact:

NHTSA

NHTSA Media NHTSAmmedia@dot.gov [202-366-9550](tel:202-366-9550)