#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 22V-018

**Manufacturer Name:** Heartland Recreational Vehicles, LLC

NHTSA Recall No.: 22V-018

Manufacturer Recall No.: TBD



## **Manufacturer Information:**

Manufacturer Name: Heartland Recreational Vehicles, LLC

Address: 1001 All Pro Drive

Elkhart IN 46514

Company phone: 8772628032

## **Population:**

 $Number\ of\ potentially\ involved: 2,363$ 

Estimated percentage with defect : 50 %

## **Vehicle Information:**

Vehicle 1: 2021-2022 Heartland Cyclone

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: The population was determined by when recalled tires were shipped to the plants to

when it was discovered and tire usage was stopped.

Production Dates: JUN 01, 2020 - NOV 16, 2021

VIN Range 1: Begin: 5SFCG4637ME441079 End: 5SFCG4539NE492702 ✓ Not sequential

Vehicle 2: 2021-2022 Heartland Fuel

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Population was determined by when recalled tires were shipped to the plants to

when it was discovered and tire usage was stopped.

Production Dates: JUN 03, 2020 - NOV 05, 2021

VIN Range 1: Begin: 5SFCG4425ME441835 End: 5SFCG4421NE492928 ✓ Not sequential

Vehicle 3: 2021-2022 Heartland Gravity

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Population was determined by when recalled tires were shipped to the plants to

when it was discovered and tire usage was stopped.

Production Dates: JUN 01, 2020 - NOV 09, 2021

VIN Range 1: Begin: 5SFCG4223ME441075 End: 5SFCG4122NE493137 ✓ Not sequential

Vehicle 4: 2021-2022 Heartland Road Warrior

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: The population was determined by when recalled tires were shipped to the plants to

when it was discovered and tire usage was stopped.

Production Dates: JUN 11, 2020 - NOV 16, 2021

VIN Range 1: Begin: 5SFCG453XME442700 End: 5SFCG4637NE493152 ✓ Not sequential

## **Description of Defect:**

Description of the Defect: The Sailun ST tires associated with this recall have a design change that could

contribute to a tread belt separation or tread delamination.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The Sailun tires associated with this recall could delaminate or lose tread.

This could lead to an increased risk of crash and personal injury.

Description of the Cause: Tires manufactured at Sailun's Vietnam plant may have a manufacturing defect

that could cause the tire to delaminate.

Identification of Any Warning Sailun ST235/80R16 and ST235/85R16 tires with a DOT date range identified

that can Occur: by factory code 1YJ and the last four digits of the DOT code as 2020-4120.

## **Involved Components:**

Component Name 1: Sailun Tires

Component Description: ST235/80R16 and ST 23585R16 Tires with DOT factory code 1YJ and DOT date

cod of 2020-4120

Component Part Number: DOT factory code 1YJ and DOT date cod of 2020-4120

## **Supplier Identification:**

## **Component Manufacturer**

Name: Sailun Tires America

Address: 4300 TBC Way

Palm Beach Gardens Florida 33410-4248

Country: United States

## **Chronology:**

1/4 - received letter recall Letter from Tredit. 1/6 called tredit for help on scope. 1/12 received a call back from tredit. 1/13 received a scope of possible tire shipments from tredit. 1/14 working on scope for vin for recall. 1/18 sent safety committee email.

## **Description of Remedy:**

Description of Remedy Program: The remedy will be to inspect your tires for a DOT date range identified by

factory code 1YJ and the last four digits of the DOT code as 2020-4120. If you own any of the above-listed tires please visit the closest Sailun Tire dealer or call Sailun at 1-844-281-9696. The Tires will be replaced at no cost to the owner. All reimbursements will be covered by Sailun Tire

America.

How Remedy Component Differs The remedy component would have the affected tires to be replaced with

from Recalled Component: the same or substantially similar brand at no cost.

The remedy component would have the affected tires to be replaced.

Identify How/When Recall Condition Once notified by the supplier, we took any affected tire out of production. was Corrected in Production :

## **Recall Schedule:**

Description of Recall Schedule: Heartland will begin notifying owners/dealers once letters are approved

Planned Dealer Notification Date : MAR 18, 2022 - MAR 18, 2022 Planned Owner Notification Date : MAR 18, 2022 - MAR 18, 2022

<sup>\*</sup> NR - Not Reported