

Part 573 Safety Recall Report

22V-341

Manufacturer Name : Shyft Group

Submission Date : MAY 16, 2022

NHTSA Recall No. : 22V-341

Manufacturer Recall No. : 22-01



Manufacturer Information :

Manufacturer Name : Shyft Group

Address : 1541 Reynolds Road
Charlotte MI 48813

Company phone : 517-543-6400

Population :

Number of potentially involved : 1,826

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2022-2022 Utilmaster Walk-In Vans

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : Vehicles subject to this recall are final stage vehicles built on incomplete vehicles supplied by Mercedes on which there was a tire size change that was not communicated to Shyft.

Production Dates : JAN 25, 2022 - APR 11, 2022

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Tire size and tire pressures on the tire placard as well as the certification label may be inaccurate.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : 567 - Certification

Description of the Safety Risk : Inaccurate information on the required labels may result in over or under inflated tires and overloading of the vehicle which could increase the risk of a crash.

Description of the Cause : A change in tire size and tire pressures were made by the incomplete vehicle manufacturer without informing Shyft, the final stage manufacturer, of the change proactively.

Identification of Any Warning that can Occur : Overloading of the vehicle could occur without warning.

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Pending more information.

Description of Remedy :

Description of Remedy Program : Vehicles subject to this recall are within their respective warranty periods. No reimbursement plan is expected to be needed as incorrect labels would have been replaced without charge.

How Remedy Component Differs from Recalled Component : Labels with correct information would include information that matches the as built tire configuration on the incomplete vehicle.

Identify How/When Recall Condition was Corrected in Production : Pending

Recall Schedule :

Description of Recall Schedule : Shyft does not utilize dealers.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : MAY 27, 2022 - MAY 27, 2022

* NR - Not Reported