

May 20, 2021

Via E-Mail and FedEx

Steven Cliff
Acting Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
West Building
Washington, D.C. 20590

Re: Petition for Determination of Inconsequential Noncompliance:

Dear Dr. Cliff:

On behalf of Vermeer Manufacturing Company (Vermeer), we are submitting the enclosed Petition for Determination of Inconsequential Noncompliance pursuant to 49 U.S.C. §§ 30118(d) and 30120(h) and 49 C.F.R. §§ 556.1-556.9, for an exemption from the notice and remedy requirements, on the ground that the noncompliance to which this petition relates is inconsequential to motor vehicle safety.

We appreciate your consideration of this petition. Please contact me with any questions.

Sincerely,



R. Nicholas Englund

RNE:krb
Enclosures

cc: Otto Matheke (NHTSA OVSC)
Claudia Covell (NHTSA OVSC)
Amina Fisher (NHTSA OCVSC)

Vermeer Manufacturing Company
Petition for Determination of Inconsequential Noncompliance
NHTSA No. 21V296

May 20, 2021

Vermeer Manufacturing Company (Vermeer) submits this Petition for Determination of Inconsequential Noncompliance pursuant to the National Traffic and Motor Vehicle Safety Act (Safety Act), 49 U.S.C. §§ 30118(d) and 30120(h) and 49 C.F.R. Part 556, for an exemption from the notice and remedy requirements of 49 U.S.C. §§ 30118 and 30120, on the ground that the noncompliance to which this petition relates is inconsequential to motor vehicle safety.

I. Background

Vermeer Manufacturing Company is an Iowa corporation with its office at 1210 Vermeer Road, Pella, Iowa 50219.

Vermeer determined that a population of 1,308 work trailers manufactured by its subsidiary, Vermeer MV Solutions, Inc. (including its predecessors in interest, McLaughlin Group, Inc. and Vac-Tron Equipment, LLC) do not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 110, *Tire selection and rims and motor home/recreation vehicle trailer load carrying capacity information for motor vehicles with a GVWR of 4,536 kilograms (10,000 pounds) or less*. See Exhibit No. 1 (Vermeer 573 Noncompliance Report) (the report includes the full list of 70 different trailer models covered by this petition). The subject trailers were manufactured between March 6, 2006 and April 28, 2021. Specifically, the subject trailers are missing the tire placard required by FMVSS 110 S4.3.5. This matter has been assigned NHTSA Recall No. 21V296.

Permanently mounted onto the subject trailers are work equipment, including core saws designed to cut concrete using a revolving core saw bit and vacuum-excavation equipment used in what is referred to as “soft digging.” The vacuum excavator uses a blast of air or water to loosen soil and break up large material. The debris is then extracted using a vacuum hose. These trailers are used by commercial excavation and construction companies and are not used by consumers. Additionally, the gross vehicle weight rating (GVWR) for the suspect trailers ranges between 1,224 kg (2,698 lb.) and 4,538 kg (9,995 lb.). When towed by a light- or medium-duty truck, the gross combination weight (GCW) or gross combination weight rating (GCWR) would likely approach or exceed the threshold for commercial vehicles – 4,536 kg (10,001 lb.) or greater. See 49 CFR 390.5. In short, these are sophisticated, commercial trailers that are used by professional construction companies, not by general public.

II. Discussion

Under the Safety Act, each FMVSS promulgated by the National Highway Traffic Safety Administration (NHTSA) must be “practicable, meet the need for motor vehicle safety, and be stated in objective terms.” 49 U.S.C. § 30111(a). The Safety Act defines “motor vehicle safety” as:

the performance of a motor vehicle or motor vehicle equipment in a way that protects the public against unreasonable risk of accidents occurring because of the design, construction, or performance of a motor vehicle, and against unreasonable risk of death or injury in an accident, and includes nonoperational safety of a motor vehicle.

49 U.S.C. § 30102(a)(9).

The Safety Act exempts manufacturers from the Safety Act's notice and remedy requirements when NHTSA determines that a noncompliance is inconsequential as it relates to motor vehicle safety. *See* 49 U.S.C. §§ 30118(d) and 30120(h). Sections 30118(d) and 30120(h) demonstrate Congress's acknowledgement that there are cases where a vehicle or equipment may fail to meet the requirements of a safety standard, yet the impact on motor vehicle safety is so slight that an exemption from the notice and remedy requirements of the Safety Act is justified.

NHTSA has stated that in determining the question of inconsequentiality "the issue to consider is the consequence to an occupant who is exposed to the consequence of that noncompliance." *General Motors, LLC, Denial of Petition for Decision of Inconsequential Noncompliance*, 85 *Fed. Reg.* 71713, 71716 (Nov. 10, 2020); *see also General Motors Corp.; Ruling on Petition for Determination of Inconsequential Noncompliance*, 69 *Fed. Reg.* 19897, 19900 (Apr. 14, 2004) (the relevant consideration in evaluating an inconsequentiality petition is "whether an occupant who is affected by the noncompliance is *likely to be exposed to a significantly greater risk than an occupant in a compliant vehicle*") (emphasis added); *Cosco Inc.; Denial of Application of Inconsequential Noncompliance*, 64 *Fed. Reg.* 29408, 29409 (Jun. 1, 1999). In evaluating the effect on motor vehicle safety, NHTSA looks to the "specific facts before it in a particular petition." *BMW of North America, LLC; Jaguar Land Rover North America, LLC; and Autoliv, Inc.; Decisions of Petitions for Inconsequential Noncompliance*, 84 *Fed. Reg.* 19994, 19997 (May 7, 2019) (citing *General Motors, LLC., Grant of Petition for Decision of Inconsequential Noncompliance*, 81 *Fed. Reg.* 92963 (Dec. 20, 2016)).

Under FMVSS 110 S4.3.5, each trailer must show the information specified in S4.3(c) through (g) and may show the information specified in S4.3(h) and (i), on a placard permanently affixed proximate to the certification label specified in 49 CFR part 567.

Vermeer believes that the particular facts regarding the noncompliance in these specialty trailers demonstrates that the labeling error is inconsequential to motor vehicle safety. The purpose of the tire placard is informational and not a substantive performance standard and the missing information is readily available to operators from other sources. For sophisticated excavation and construction equipment such as these specialty trailers, operators rely on the instruction and other safety information (such as the tire and rim information) contained in the owner's manual to properly operate the equipment. The owner's manual for these trailers includes the required information for the placard.

Additionally, operators can readily ascertain the tire and rim combination information from the sidewalls of the tire and the rims equipped on new trailers. *See* FMVSS 139 S and FMVSS 110 S4.4.2(e)(1) respectively. Operators can also access tire and rim information

fromMyVermeer.com. With these additional sources of information, operators have ready access to the required information in the tire placard.

NHTSA has granted numerous petitions for inconsequential noncompliance related to missing or incorrect tire placard and tire-and-rim information where the required information was ascertainable from another readily available source.

- 84 Fed. Reg. 25118 (May 30, 2019) (granting Mercedes-Benz petition related to improperly printed tire placards that rendered certain information illegible);
- 84 Fed. Reg. 25117 (May 30, 2019) (granting General Motors' petition related to tire placards that incorrectly stated the spare tire size and cold tire pressure);
- 82 Fed. Reg. 5640 (January 18, 2017) (granting Mercedes-Benz's petition related to tire placards that incorrectly identified the spare tire size);
- 81 Fed. Reg. 88728 (December 8, 2016) (granting Volkswagen's (VW's) petition related to tire placards with the incorrect tire size);
- 81 Fed. Reg. 28935 (May 10, 2016) (granting VW's petition related to tire placards missing the word "none" in the area reserved for spare tire specifications);
- 81 Fed. Reg. 30607 (May 17, 2016) (granting Chrysler Group's petition related to missing rim size information);
- 78 Fed. Reg. 76408 (December 17, 2013) (granting BMW's petition related to certification labels with the incorrect tire and rim information);
- 78 Fed. Reg. 38443 (June 26, 2013) (granting Chrysler Group's petition related to certification labels that incorrectly identified the tire size); and
- 78 Fed. Reg. 38445 (June 26, 2013) (granting Hyundai's petition related to certification labels missing the tire size designation information).

Moreover, these are work trailers used by commercial construction operators who would be experienced with and knowledgeable about these trailers. As NHTSA explained in granting a similar petition for Chrysler Group related to missing tire placard information, it is highly likely that these operators will readily be able to determine the tire and rim size and the appropriate inflation pressures for the load they are operating. *See* 81 Fed. Reg. 30607, 30609 (May 17, 2016) (granting Chrysler's petition). Indeed, many vehicle and trailer combinations would be subject to state or Federal regulations related to commercial vehicles requiring vehicles to be frequently inspected, which would include loading conditions. *See e.g.* 49 CFR 393.75(g) and (i); 49 CFR 396.9(c).

Last, the trailers otherwise comply with FMVSS 110 and Vermeer is not aware of any complaints, claims, or incidents related to the subject noncompliance.

III. Conclusion

The labeling noncompliance at issue here is inconsequential to motor vehicle safety. The required information is readily available from other sources and the Agency has granted many petitions for similar noncompliances. Accordingly, Vermeer respectfully requests that NHTSA exempt it from the notice and remedy requirements of the Safety Act.

Respectfully submitted,

Vermeer Manufacturing Company

Enclosures

EXHIBIT 1



Vermeer Manufacturing Company

Vehicle Report

NHTSA ID: 21V296 Transaction ID: 21-0010049-25924-12 (Amendment 2)

Required fields indicated with *

Your report has been submitted. Your Transaction No. is 21-0010049-25924-12.

Manufacturer: Vermeer Manufacturing Company

1210 VERMEER ROAD EAST
PELLA IA 50219-0200

[Jo Le Milledge](#)
6416218022,

This is a Noncompliance Report. Filing a petition pursuant to [49 CFR 556](#)

Vehicle Information

Vermeer LPMINI 2021

* Model Yr. Start: 2021	* Model Yr. End: 2021	Type: TRAILERS
* Make: Vermeer		Body Style:
* Model: LPMINI		Powertrain:
Production Dates	Begin: 02/25/2021 End: 02/25/2021	Descriptive Information: Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.
VIN Range(s):	Begin: 7NWF16201MK010001 End: 7NWF16201MK010001	
VIN Range(s):	Begin: 1MV4192MCMG010017 End: 1MV4192MTMG010018	

Vac-Tron LPMINI 2014 - 2021

* Model Yr. Start: 2014	* Model Yr. End: 2021	Type: TRAILERS
* Make: Vac-Tron		Body Style:
* Model: LPMINI		Powertrain:
Production Dates	Begin: 07/01/2014 End: 10/07/2020	Descriptive Information: Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.
VIN Range(s):	Begin: 5HZBF1623ELGE1283 End: 5HZF16209MK002011	

Vermeer LPMINIXDT 2021

* Model Yr. Start: 2021	* Model Yr. End: 2021	Type: TRAILERS
* Make: Vermeer		Body Style:
* Model: LPMINIXDT		Powertrain:
Production Dates	Begin: 01/01/2021 End: 02/10/2021	Descriptive Information: Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.
VIN Range(s):	Begin: 7NWH16220MK010002 End: 7NWH16223MK010012	

Vac-Tron LPSDT 2019 - 2021

* **Model Yr. Start:** 2019
 * **Make:** Vac-Tron
 * **Model:** LPSDT

* **Model Yr. End:** 2021

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 02/01/2019
 End: 11/17/2020

VIN Range(s): Begin: 5HZG1621XKK002013 End: 5HZG16213MK002423

Vermeer LPSDT 2021

* **Model Yr. Start:** 2021
 * **Make:** Vermeer
 * **Model:** LPSDT

* **Model Yr. End:** 2021

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 01/18/2021
 End: 04/26/2021

VIN Range(s): Begin: 7NWX16219MK010020 End: 7NWX16219MK010101

Vac-Tron LPSGT 2019 - 2020

* **Model Yr. Start:** 2019
 * **Make:** Vac-Tron
 * **Model:** LPSGT

* **Model Yr. End:** 2020

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 02/01/2019
 End: 07/02/2020

VIN Range(s): Begin: 5HZH16227KK002001 End: 5HZH16223LK002059

Vermeer LPSGT 2021

* **Model Yr. Start:** 2021
 * **Make:** Vermeer
 * **Model:** LPSGT

* **Model Yr. End:** 2021

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 01/11/2021
 End: 03/09/2021

VIN Range(s): Begin: 7NWX16229MK010001 End: 7NWX16212MK010011

Vac-Tron LPXDT 2019 - 2021

* **Model Yr. Start:** 2019* **Model Yr. End:** 2021**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** LPXDT**Powertrain:**

Production Dates Begin: 03/01/2019
 End: 12/05/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZJ16232KK002014 End: 5HZH16223MK000104

Vac-Tron LPMINIXDT 2014 - 2020* **Model Yr. Start:** 2014* **Model Yr. End:** 2020**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** LPMINIXDT**Powertrain:**

Production Dates Begin: 06/01/2014
 End: 11/01/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1621FLME1100 End: 5HZBF1621FLME1100

VIN Range(s): Begin: 5HZH1622XLK000101 End: 5HZH16223LK000103

Vac-Tron LPMINI 2014 - 2021* **Model Yr. Start:** 2014* **Model Yr. End:** 2021**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** LPMINI**Powertrain:**

Production Dates Begin: 07/01/2014
 End: 10/07/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1623ELGE1283 End: 5HZF16209MK002011

Vac-Tron LP573XDT 2015 - 2019* **Model Yr. Start:** 2015* **Model Yr. End:** 2019**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** LP573XDT**Powertrain:**

Production Dates Begin: 11/01/2015
 End: 02/01/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628FLLF1278 End: 5HZBF1621KLBK1146

Vac-Tron LP533SDT 2013 - 2017* **Model Yr. Start:** 2013* **Model Yr. End:** 2017**Type:** TRAILERS

* **Make:** Vac-Tron
 * **Model:** LP533SDT

Production Dates Begin: 01/01/2013
 End: 04/11/2017

Body Style:**Powertrain:****Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1621DLAD1042 End: 5HZBF1628HLDH1200

Vac-Tron LP533SGT 2015

* **Model Yr. Start:** 2015 * **Model Yr. End:** 2015
 * **Make:** Vac-Tron
 * **Model:** LP533SGT

Production Dates Begin: 10/01/2015
 End: 10/01/2015

Type: TRAILERS**Body Style:****Powertrain:****Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628FLKF1259 End: 5HZBF1628FLKF1259

Vac-Tron AIR555SDT 2011 - 2012

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2012
 * **Make:** Vac-Tron
 * **Model:** AIR555SDT

Production Dates Begin: 04/01/2011
 End: 02/01/2012

Type: TRAILERS**Body Style:****Powertrain:****Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF16251LD11384 End: 5HZBF1627CLBC1181

Vac-Tron AIR573SDT 2016 - 2018

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** AIR573SDT

Production Dates Begin: 07/01/2016
 End: 03/25/2018

Type: TRAILERS**Body Style:****Powertrain:****Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1623GLGG1214 End: 5HZBF1626JLCJ1214

Vac-Tron AIRSDT 2019

* **Model Yr. Start:** 2019 * **Model Yr. End:** 2019
 * **Make:** Vac-Tron
 * **Model:** AIRSDT

Type: TRAILERS**Body Style:****Powertrain:****Descriptive Information:**

Production Dates Begin: 06/17/2019
End: 06/17/2019

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZA162V8KK002018 End: 5HZA162V8KK002018

Vac-Tron CS350GT 2012

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2012
* **Make:** Vac-Tron
* **Model:** CS350GT

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 09/01/2012
End: 09/01/2012

VIN Range(s): Begin: 5HZBF1622CLJC1313 End: 5HZBF1622CLJC1313

Vermeer CS418B 2021

* **Model Yr. Start:** 2021 * **Model Yr. End:** 2021
* **Make:** Vermeer
* **Model:** CS418B

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 01/08/2021
End: 04/28/2021

VIN Range(s): Begin: 7NWF131ZXMGO10001 End: 7NWF131Z0MG010010

Vac-Tron CS500DT 2012 - 2016

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2016
* **Make:** Vac-Tron
* **Model:** CS500DT

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 01/01/2012
End: 04/01/2016

VIN Range(s): Begin: 5HZBF1628CLAC1154 End: 5HZBF1624GLDG1147

Vac-Tron CS500GT 2011 - 2015

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2015
* **Make:** Vac-Tron
* **Model:** CS500GT

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant

Production Dates Begin: 07/01/2011
End: 02/01/2015

to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF16231LG11490 End: 5HZBF1625FLBF1154

Vac-Tron LP550SDT 2012

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2012
 * **Make:** Vac-Tron
 * **Model:** LP550SDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 07/01/2012
 End: 07/01/2012

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628CLGC1298 End: 5HZBF1628CLGC1298

Vac-Tron LP555DT 2011 - 2013

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2013
 * **Make:** Vac-Tron
 * **Model:** LP555DT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 08/01/2011
 End: 02/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1625BLHB1555 End: 5HZBF1622DLBD1067

Vac-Tron LP555SDT 2009 - 2013

* **Model Yr. Start:** 2009 * **Model Yr. End:** 2013
 * **Make:** Vac-Tron
 * **Model:** LP555SDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 11/01/2009
 End: 01/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF16279LL91358 End: 5HZBF1625DLAD1027

Vac-Tron LP573GT 2016

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2016
 * **Make:** Vac-Tron
 * **Model:** LP573GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 04/01/2016
 End: 04/01/2016

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy

provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1621GLDG1154 End: 5HZBF1621GLDG1154

Vac-Tron LP573SDT 2015 - 2019

*** Model Yr. Start:** 2015 *** Model Yr. End:** 2019 **Type:** TRAILERS
*** Make:** Vac-Tron **Body Style:**
*** Model:** LP573SDT **Powertrain:**
Production Dates **Descriptive Information:**
 Begin: 12/04/2015 Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.
 End: 01/01/2019

VIN Range(s): Begin: 5HZBF1627FLMF1288 End: 5HZBF1629KLAK1568

Vac-Tron LP573SGT 2015 - 2018

*** Model Yr. Start:** 2015 *** Model Yr. End:** 2018 **Type:** TRAILERS
*** Make:** Vac-Tron **Body Style:**
*** Model:** LP573SGT **Powertrain:**
Production Dates **Descriptive Information:**
 Begin: 12/01/2015 Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.
 End: 06/27/2018

VIN Range(s): Begin: 5HZBF1629FLMF1289 End: 5HZBF1629JLJF1376

McLaughlin CS418B 2016 - 2021

*** Model Yr. Start:** 2016 *** Model Yr. End:** 2021 **Type:** TRAILERS
*** Make:** McLaughlin **Body Style:**
*** Model:** CS418B **Powertrain:**
Production Dates **Descriptive Information:**
 Begin: 05/12/2016 Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.
 End: 11/17/2020

VIN Range(s): Begin: 000000CS041416006 End: 000000CS041416006

VIN Range(s): Begin: 7HWF131Z9KG005006 End: 7HWF131Z4MG005031

McLaughlin V25G 2015 - 2019

*** Model Yr. Start:** 2015 *** Model Yr. End:** 2019 **Type:** TRAILERS
*** Make:** McLaughlin **Body Style:**
*** Model:** V25G **Powertrain:**
Production Dates **Descriptive Information:**
 Begin: 05/27/2015 Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.
 End: 05/07/2018

VIN Range(s): Begin: 0000V5S0527151304 End: 0000V5S0830172722
VIN Range(s): Begin: 7HW6162PXXG005014 End: 7HW6162PXXG005014

McLaughlin VX30 2014 - 2020

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2020
 * **Make:** McLaughlin
 * **Model:** VX30

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 07/23/2014
 End: 01/17/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000V5S072314669 End: 0000V5S0220183018
VIN Range(s): Begin: 7HWY192FXJG005028 End: 7HWY192F4LG005108

McLaughlin VX30G 2014 - 2019

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2019
 * **Make:** McLaughlin
 * **Model:** VX30G

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 09/17/2014
 End: 06/03/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 0000VX5S091714788 End: 0000V5S0222183021
VIN Range(s): Begin: 7HW1152J7JG005003 End: 7HW1152J7KG005052

McLaughlin VX50 2014 - 2021

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2021
 * **Make:** McLaughlin
 * **Model:** VX50

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 06/20/2014
 End: 02/04/2021

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000VX5062014615 End: 0000V5H0922172780
VIN Range(s): Begin: 7HW4192M0KG005019 End: 7HW4192MVMG005655

McLaughlin V250 2008

* **Model Yr. Start:** 2008 * **Model Yr. End:** 2008
 * **Make:** McLaughlin
 * **Model:** V250

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 01/02/2008
 End: 01/02/2008

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 000VT250DVE101107 End: 000VT250DVE101107

McLaughlin V500LEG 2013 - 2014

* Model Yr. Start: 2013 * Model Yr. End: 2014
* Make: McLaughlin
* Model: V500LEG

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 01/15/2013
End: 06/24/2014

Descriptive Information:
Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000V5S011513422 End: 00000V5S062414628

McLaughlin V500LELT 2012 - 2014

* Model Yr. Start: 2012 * Model Yr. End: 2014
* Make: McLaughlin
* Model: V500LELT

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 12/10/2012
End: 01/08/2014

Descriptive Information:
Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000V5S121012348 End: 00000V5S010814312

McLaughlin V500LELTHD 2012 - 2014

* Model Yr. Start: 2012 * Model Yr. End: 2014
* Make: McLaughlin
* Model: V500LELTHD

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 12/06/2012
End: 03/05/2014

Descriptive Information:
Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000V5H120112328 End: 00000V5H030514405

McLaughlin V500LT 2007

* Model Yr. Start: 2007 * Model Yr. End: 2007
* Make: McLaughlin
* Model: V500LT

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 06/10/2007
End: 06/10/2007

Descriptive Information:
Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 0000005D060807866 End: 0000005D060807866

Vermeer CVGT 2021* **Model Yr. Start:** 2021* **Model Yr. End:** 2021**Type:** TRAILERS* **Make:** Vermeer**Body Style:*** **Model:** CVGT**Powertrain:****Production Dates** Begin: 01/15/2021
End: 04/27/2021**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWC162X1MK010001 End: 7NWC162X9MK010022**Vac-Tron CVSGT 2019 - 2021*** **Model Yr. Start:** 2019* **Model Yr. End:** 2021**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** CVSGT**Powertrain:****Production Dates** Begin: 02/01/2019
End: 01/05/2021**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZD162Y7KK002003 End: 5HZD162Y4MK002270**Vermeer LPXDT 2021*** **Model Yr. Start:** 2021* **Model Yr. End:** 2021**Type:** TRAILERS* **Make:** Vermeer**Body Style:*** **Model:** LPXDT**Powertrain:****Production Dates** Begin: 02/10/2021
End: 02/10/2021**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWX1623XMK010017 End: 7NWX1623XMK010017**Vermeer CVSGT 2021*** **Model Yr. Start:** 2021* **Model Yr. End:** 2021**Type:** TRAILERS* **Make:** Vermeer**Body Style:*** **Model:** CVSGT**Powertrain:****Production Dates** Begin: 01/07/2021
End: 04/19/2021**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWD162Y5MK010001 End: 7NWD162YXMK010043**Vac-Tron EV150DT 2016*** **Model Yr. Start:** 2016* **Model Yr. End:** 2016**Type:** TRAILERS

* **Make:** Vac-Tron* **Model:** EV150DT

Production Dates Begin: 04/01/2016
 End: 04/01/2016

VIN Range(s): Begin: 5HZBF1410GLDG3102 End: 5HZBF1410GLDG3102

Body Style:**Powertrain:****Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Vac-Tron EV150GT 2011 - 2019* **Model Yr. Start:** 2011* **Model Yr. End:** 2019**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** EV150GT**Powertrain:**

Production Dates Begin: 08/01/2011
 End: 02/01/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1215BLHB4100 End: 5HZBF141XKLAK3100

Vac-Tron EVGT 2019 - 2021* **Model Yr. Start:** 2019* **Model Yr. End:** 2021**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** EVGT**Powertrain:**

Production Dates Begin: 03/30/2019
 End: 11/30/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZE141ZXKK002001 End: 5HZE141Z6MK002015

Vac-Tron FM150SGT 2006* **Model Yr. Start:** 2006* **Model Yr. End:** 2006**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** FM150SGT**Powertrain:**

Production Dates Begin: 03/01/2006
 End: 03/01/2006

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF12106LC64107 End: 5HZBF12106LC64107

Vac-Tron FM350SDT 2008* **Model Yr. Start:** 2008* **Model Yr. End:** 2008**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** FM350SDT**Powertrain:****Descriptive Information:**

Production Dates Begin: 05/01/2008
End: 05/01/2008

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF172X8LE87131 End: 5HZBF172X8LE87131

Vac-Tron JETTERTLR 2011 - 2018

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2018
* **Make:** Vac-Tron
* **Model:** JETTERTLR

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 11/01/2011
End: 04/30/2018

VIN Range(s): Begin: 5HZBF1629BLLB1625 End: 5HZBF1629BLLB1625
VIN Range(s): Begin: 5HZBF1625JLDJ1269 End: 5HZBF1625JLDJ1269

Vac-Tron LP303GT 2013 - 2017

* **Model Yr. Start:** 2013 * **Model Yr. End:** 2017
* **Make:** Vac-Tron
* **Model:** LP303GT

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 08/01/2013
End: 01/13/2017

VIN Range(s): Begin: 5HZBF1627DLHD1213 End: 5HZBF1622HLAH1118

Vac-Tron LP303XDT 2016

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2016
* **Make:** Vac-Tron
* **Model:** LP303XDT

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates Begin: 11/01/2016
End: 11/01/2016

VIN Range(s): Begin: 5HZBF1629GLLG1285 End: 5HZBF1629GLLG1285

Vac-Tron LP305DT 2011 - 2013

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2013
* **Make:** Vac-Tron
* **Model:** LP305DT

Type: TRAILERS

Body Style:

Powertrain:

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The

Production Dates Begin: 03/01/2011
End: 05/01/2013

machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF16241LC11373 End: 5HZBF1629DLED1169

Vac-Tron LP305GT 2012

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2012
 * **Make:** Vac-Tron
 * **Model:** LP305GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 08/01/2012
 End: 10/01/2012

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF162XCLHC1306 End: 5HZBF1625CLKC1325

Vac-Tron LP333DT 2014

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2014
 * **Make:** Vac-Tron
 * **Model:** LP333DT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 01/01/2014
 End: 04/01/2014

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1627ELAE1124 End: 5HZBF1627ELAE1124
VIN Range(s): Begin: 5HZBF1628ELDE1223 End: 5HZBF1628ELDE1223
VIN Range(s): Begin: 5HZBF1628ELDE1223 End: 5HZBF1628ELDE1223

Vac-Tron LP333GT 2014 - 2015

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2015
 * **Make:** Vac-Tron
 * **Model:** LP333GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 01/01/2014
 End: 05/01/2015

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1627ELAE1155 End: 5HZBF1627ELAE1155
VIN Range(s): Begin: 5HZBF1629FLEF1201 End: 5HZBF1629FLEF1201

Vac-Tron LP355DT 2011 - 2012

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2012
 * **Make:** Vac-Tron
 * **Model:** LP355DT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 08/01/2011
 End: 03/01/2012

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The

machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628BLHB1503 End: 5HZBF1620CLCC1204

Vac-Tron LP355GT 2013

* **Model Yr. Start:** 2013 * **Model Yr. End:** 2013
 * **Make:** Vac-Tron
 * **Model:** LP355GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 05/01/2013
 End: 05/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1622DLED1143 End: 5HZBF1622DLED1143

Vac-Tron LP370XDT 2018

* **Model Yr. Start:** 2018 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** LP370XDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 03/21/2018
 End: 03/21/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1625JLCJ1222 End: 5HZBF1625JLCJ1222

Vac-Tron LP373GT 2015 - 2019

* **Model Yr. Start:** 2015 * **Model Yr. End:** 2019
 * **Make:** Vac-Tron
 * **Model:** LP373GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 12/01/2015
 End: 01/01/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1625FLMF1287 End: 5HZBF1626KLAK1110

Vac-Tron LP373SGT 2016 - 2018

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** LP373SGT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 12/01/2016
 End: 06/05/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy

provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1624GLMG1293 End: 5HZBF1624GLMG1293
VIN Range(s): Begin: 5HZBF1621JLJF1369 End: 5HZBF1621JLJF1369

Vac-Tron AIR373SDT 2017

* **Model Yr. Start:** 2017

* **Model Yr. End:** 2017

Type: TRAILERS

* **Make:** Vac-Tron

Body Style:

* **Model:** AIR373SDT

Powertrain:

Production Dates Begin: 07/10/2017
End: 07/10/2017

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1626HLGH1284 End: 5HZBF1626HLGH1284

Vac-Tron CS530GT 2015

* **Model Yr. Start:** 2015

* **Model Yr. End:** 2015

Type: TRAILERS

* **Make:** Vac-Tron

Body Style:

* **Model:** CS530GT

Powertrain:

Production Dates Begin: 05/01/2015
End: 05/01/2015

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1623FLEF1209 End: 5HZBF1623FLEF1209

Vac-Tron CS555GT 2013

* **Model Yr. Start:** 2013

* **Model Yr. End:** 2013

Type: TRAILERS

* **Make:** Vac-Tron

Body Style:

* **Model:** CS555GT

Powertrain:

Production Dates Begin: 01/01/2013
End: 01/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1625DLAD1044 End: 5HZBF1625DLAD1044

Vac-Tron CS570GT 2016 - 2018

* **Model Yr. Start:** 2016

* **Model Yr. End:** 2018

Type: TRAILERS

* **Make:** Vac-Tron

Body Style:

* **Model:** CS570GT

Powertrain:

Production Dates Begin: 05/01/2016
End: 02/24/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1621JLBJ1151 End: 5HZBF1621JLBJ1151
VIN Range(s): Begin: 5HZBF1419GLEG3103 End: 5HZBF1419GLEG3103

Vac-Tron CS573GT 2018

* **Model Yr. Start:** 2018 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** CS573GT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 02/19/2018
 End: 05/25/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF162XJLBJ1150 End: 5HZBF1628JLEJ1351

Vac-Tron CV570GT 2017 - 2018

* **Model Yr. Start:** 2017 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** CV570GT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 08/07/2017
 End: 04/11/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1626HLHH1319 End: 5HZBF1622JLDJ1228

Vac-Tron CV570SGT 2017 - 2018

* **Model Yr. Start:** 2017 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** CV570SGT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 05/21/2017
 End: 03/08/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1623HLEH1219 End: 5HZBF1628JLCJ1196

Vac-Tron CV573GT 2016 - 2018

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** CV573GT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 10/01/2016
 End: 12/18/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1624GLKG1272 End: 5HZBF1622KLMJ1554

Vac-Tron CV573SGT 2016 - 2019* **Model Yr. Start:** 2016* **Model Yr. End:** 2019**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** CV573SGT**Powertrain:****Production Dates** Begin: 10/01/2016
End: 01/07/2019**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628GLKG1274 End: 5HZBF1629KLAK1120**Vac-Tron CVGT 2019 - 2021*** **Model Yr. Start:** 2019* **Model Yr. End:** 2021**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** CVGT**Powertrain:****Production Dates** Begin: 02/01/2019
End: 12/08/2020**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZC162XXXK002001 End: 5HZC162X4MK002174**Vac-Tron LP373XDT 2017 - 2018*** **Model Yr. Start:** 2017* **Model Yr. End:** 2018**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** LP373XDT**Powertrain:****Production Dates** Begin: 05/07/2017
End: 03/26/2018**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1627HLEH1207 End: 5HZBF1627JLCJ1223**Vac-Tron LP500GT 2011*** **Model Yr. Start:** 2011* **Model Yr. End:** 2011**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** LP500GT**Powertrain:****Production Dates** Begin: 11/01/2011
End: 11/01/2011**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628LLB1616 End: 5HZBF1628LLB1616**Vac-Tron LP500DT 2013**

* **Model Yr. Start:** 2013* **Model Yr. End:** 2013**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** LP500DT**Powertrain:****Production Dates** Begin: 04/01/2013
End: 04/01/2013**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF162XLDD1114 End: 5HZBF162XLDD1114**Number potentially involved:** 1308**Estimated percentage of involved with defect:** 100%**Defect / Noncompliance Description**

For this Defect/Noncompliance:

*** Describe the defect or noncompliance:**

Missing tire placard.

If a noncompliance, provide the applicable FMVSS:
110 - Tire selection and rims**If applicable, provide any further FMVSS affected:****Describe the cause:****This Recall affects all vehicles.**

If applicable, identify the manufacturer of the defective or noncompliant component. If the manufacturer of the component is unknown, provide the information for the company that supplied the subject component.

Component manufacturer

Company Information

Company Name:**Country:****Address 1:****Address 2:****City:****State:****Zip/Postal Code:**

Company Contact Information

First Name:**Last Name:****Position:****Email:****Phone:****Involved Components**

If the defect or noncompliance involves a specific component(s), identify that component(s) below.

Chronology of Defect / Noncompliance Determination**Provide the chronology of events leading up to the defect decision or test data for the noncompliance decision.:**

19-Feb-2021 – Investigation begins. Product Compliance and Product Safety identify need to research what information relating to tires and rims is available for affected vehicles and how that information is presented to end users. Discovered when Product Safety department at Vermeer Corporation took over responsibility for certain aspects of the issuance of Vermeer MV Solutions, Inc. MSOs. 9-Mar-2021 – Product Safety reported that tire size, tire pressure, and rim size are on the VIN plates since 2012. 8-Apr-2021 – Product Compliance met with Product Safety for a status update. 12-Apr-2021 - Product Compliance met with Legal to further discuss investigation. 14-Apr-2021 – Legal began investigation of possible noncompliance. 20-Apr-2021 – Legal determined a noncompliance existed.

Identify the Remedy**Describe the defect/noncompliance remedy program, including the manufacturer's plan for reimbursement.**

Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Describe what distinguishes the remedy component from the recalled component.**Identify and describe how and when the recall condition was corrected in production.****Identify the Recall Schedule****Describe the recall schedule for notifications.:**

Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it

Planned Dealer Notification Begin Date:**Planned Dealer Notification End Date:****Planned Owner Notification Begin Date:**

relates to motor vehicle safety. To be determined, pending the agency's disposition of the above-mentioned Part 556 petition for exemption.

Planned Owner Notification End Date:

Manufacturer's identification code for this recall (if applicable):

Please be reminded that owner notification letters must be mailed no more than 60 days from submission of this report.

Manufacturer Comments to NHTSA Staff

Document Upload

There are 0 documents associated with this report.

Vermeer Manufacturing Company
Amended Petition for Determination of Inconsequential Noncompliance
NHTSA No. 21V296

June 10, 2021

Vermeer Manufacturing Company (Vermeer) submits this Petition for Determination of Inconsequential Noncompliance pursuant to the National Traffic and Motor Vehicle Safety Act (Safety Act), 49 U.S.C. §§ 30118(d) and 30120(h) and 49 C.F.R. Part 556, for an exemption from the notice and remedy requirements of 49 U.S.C. §§ 30118 and 30120, on the ground that the noncompliance to which this petition relates is inconsequential to motor vehicle safety.

I. Background

Vermeer Manufacturing Company is an Iowa corporation with its office at 1210 Vermeer Road, Pella, Iowa 50219.

Vermeer determined that a population of 1,308 work trailers manufactured by its subsidiary, Vermeer MV Solutions, Inc. (including its predecessors in interest, McLaughlin Group, Inc. and Vac-Tron Equipment, LLC) do not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 110, *Tire selection and rims and motor home/recreation vehicle trailer load carrying capacity information for motor vehicles with a GVWR of 4,536 kilograms (10,000 pounds) or less*. See Exhibit No. 1 (Vermeer 573 Noncompliance Report) (the report includes the full list of 70 different trailer models covered by this petition). The subject trailers were manufactured between March 1, 2006 and April 28, 2021.¹ Specifically, the subject trailers are missing the tire placard required by FMVSS 110 S4.3.5. This matter has been assigned NHTSA Recall No. 21V296.

Permanently mounted onto the subject trailers are work equipment, including core saws designed to cut concrete using a revolving core saw bit and vacuum-excavation equipment used in what is referred to as “soft digging.” The vacuum excavator uses a blast of air or water to loosen soil and break up large material. The debris is then extracted using a vacuum hose. These trailers are used by commercial excavation and construction companies and are not used by consumers. Additionally, the gross vehicle weight rating (GVWR) for the suspect trailers ranges between 1,224 kg (2,698 lb.) and 4,538 kg (9,995 lb.). When towed by a light- or medium-duty truck, the gross combination weight (GCW) or gross combination weight rating (GCWR) would likely approach or exceed the threshold for commercial vehicles – 4,536 kg (10,001 lb.) or greater. See 49 CFR 390.5. In short, these are sophisticated, commercial trailers that are used by professional construction companies, not by general public.

II. Discussion

Under the Safety Act, each FMVSS promulgated by the National Highway Traffic Safety Administration (NHTSA) must be “practicable, meet the need for motor vehicle safety, and be

¹ The initial petition submitted on May 20, 2021 identified the manufacturing dates as March 6, 2006 through April 28, 2021. This amended petition corrects the dates as March 1, 2006 through April 28, 2021.

stated in objective terms.” 49 U.S.C. § 30111(a). The Safety Act defines “motor vehicle safety” as:

the performance of a motor vehicle or motor vehicle equipment in a way that protects the public against unreasonable risk of accidents occurring because of the design, construction, or performance of a motor vehicle, and against unreasonable risk of death or injury in an accident, and includes nonoperational safety of a motor vehicle.

49 U.S.C. § 30102(a)(9).

The Safety Act exempts manufacturers from the Safety Act’s notice and remedy requirements when NHTSA determines that a noncompliance is inconsequential as it relates to motor vehicle safety. *See* 49 U.S.C. §§ 30118(d) and 30120(h). Sections 30118(d) and 30120(h) demonstrate Congress’s acknowledgement that there are cases where a vehicle or equipment may fail to meet the requirements of a safety standard, yet the impact on motor vehicle safety is so slight that an exemption from the notice and remedy requirements of the Safety Act is justified.

NHTSA has stated that in determining the question of inconsequentiality “the issue to consider is the consequence to an occupant who is exposed to the consequence of that noncompliance.” *General Motors, LLC, Denial of Petition for Decision of Inconsequential Noncompliance*, 85 *Fed. Reg.* 71713, 71716 (Nov. 10, 2020); *see also General Motors Corp.; Ruling on Petition for Determination of Inconsequential Noncompliance*, 69 *Fed. Reg.* 19897, 19900 (Apr. 14, 2004) (the relevant consideration in evaluating an inconsequentiality petition is “whether an occupant who is affected by the noncompliance is *likely to be exposed to a significantly greater risk than an occupant in a compliant vehicle*”) (emphasis added); *Cosco Inc.; Denial of Application of Inconsequential Noncompliance*, 64 *Fed. Reg.* 29408, 29409 (Jun. 1, 1999). In evaluating the effect on motor vehicle safety, NHTSA looks to the “specific facts before it in a particular petition.” *BMW of North America, LLC; Jaguar Land Rover North America, LLC; and Autoliv, Inc.; Decisions of Petitions for Inconsequential Noncompliance*, 84 *Fed. Reg.* 19994, 19997 (May 7, 2019) (citing *General Motors, LLC., Grant of Petition for Decision of Inconsequential Noncompliance*, 81 *Fed. Reg.* 92963 (Dec. 20, 2016)).

Under FMVSS 110 S4.3.5, each trailer must show the information specified in S4.3(c) through (g) and may show the information specified in S4.3(h) and (i), on a placard permanently affixed proximate to the certification label specified in 49 CFR part 567.

Vermeer believes that the particular facts regarding the noncompliance in these specialty trailers demonstrates that the labeling error is inconsequential to motor vehicle safety. The purpose of the tire placard is informational and not a substantive performance standard and the missing information is readily available to operators from other sources. For sophisticated excavation and construction equipment such as these specialty trailers, operators rely on the instruction and other safety information (such as the tire and rim information) contained in the owner’s manual to properly operate the equipment. The owner’s manual for these trailers includes the required information for the placard.

Additionally, operators can readily ascertain the tire and rim combination information from the sidewalls of the tire and the rims equipped on new trailers. *See* FMVSS 139 S and FMVSS 110 S4.4.2(e)(1) respectively. Operators can also access tire and rim information from MyVermeer.com. With these additional sources of information, operators have ready access to the required information in the tire placard.

NHTSA has granted numerous petitions for inconsequential noncompliance related to missing or incorrect tire placard and tire-and-rim information where the required information was ascertainable from another readily available source.

- 84 Fed. Reg. 25118 (May 30, 2019) (granting Mercedes-Benz petition related to improperly printed tire placards that rendered certain information illegible);
- 84 Fed. Reg. 25117 (May 30, 2019) (granting General Motors' petition related to tire placards that incorrectly stated the spare tire size and cold tire pressure);
- 82 Fed. Reg. 5640 (January 18, 2017) (granting Mercedes-Benz's petition related to tire placards that incorrectly identified the spare tire size);
- 81 Fed. Reg. 88728 (December 8, 2016) (granting Volkswagen's (VW's) petition related to tire placards with the incorrect tire size);
- 81 Fed. Reg. 28935 (May 10, 2016) (granting VW's petition related to tire placards missing the word "none" in the area reserved for spare tire specifications);
- 81 Fed. Reg. 30607 (May 17, 2016) (granting Chrysler Group's petition related to missing rim size information);
- 78 Fed. Reg. 76408 (December 17, 2013) (granting BMW's petition related to certification labels with the incorrect tire and rim information);
- 78 Fed. Reg. 38443 (June 26, 2013) (granting Chrysler Group's petition related to certification labels that incorrectly identified the tire size); and
- 78 Fed. Reg. 38445 (June 26, 2013) (granting Hyundai's petition related to certification labels missing the tire size designation information).

Moreover, these are work trailers used by commercial construction operators who would be experienced with and knowledgeable about these trailers. As NHTSA explained in granting a similar petition for Chrysler Group related to missing tire placard information, it is highly likely that these operators will readily be able to determine the tire and rim size and the appropriate inflation pressures for the load they are operating. *See* 81 Fed. Reg. 30607, 30609 (May 17, 2016) (granting Chrysler's petition). Indeed, many vehicle and trailer combinations would be subject to state or Federal regulations related to commercial vehicles requiring vehicles to be frequently inspected, which would include loading conditions. *See e.g.* 49 CFR 393.75(g) and (i); 49 CFR 396.9(c).

Last, the trailers otherwise comply with FMVSS 110 and Vermeer is not aware of any complaints, claims, or incidents related to the subject noncompliance.

III. Conclusion

The labeling noncompliance at issue here is inconsequential to motor vehicle safety. The required information is readily available from other sources and the Agency has granted many petitions for similar noncompliances. Accordingly, Vermeer respectfully requests that NHTSA exempt it from the notice and remedy requirements of the Safety Act.

Respectfully submitted,

Vermeer Manufacturing Company

Enclosures



Vermeer Manufacturing Company

Vehicle Report

NHTSA ID: 21V296 Transaction ID: 21-0010049-25924-12 (Amendment 2)

Required fields indicated with *

Your report has been submitted. Your Transaction No. is 21-0010049-25924-12.

Manufacturer: Vermeer Manufacturing Company

1210 VERMEER ROAD EAST
PELLA IA 50219-0200

[Jo Le Milledge](#)
6416218022,

This is a Noncompliance Report. Filing a petition pursuant to [49 CFR 556](#)

Vehicle Information

Vermeer LPMINI 2021

* **Model Yr. Start:** 2021 * **Model Yr. End:** 2021 **Type:** TRAILERS
 * **Make:** Vermeer **Body Style:**
 * **Model:** LPMINI **Powertrain:**

Production Dates Begin: 02/25/2021
 End: 02/25/2021

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWF16201MK010001 End: 7NWF16201MK010001
VIN Range(s): Begin: 1MV4192MCMG010017 End: 1MV4192MTMG010018

Vac-Tron LPMINI 2014 - 2021

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2021 **Type:** TRAILERS
 * **Make:** Vac-Tron **Body Style:**
 * **Model:** LPMINI **Powertrain:**

Production Dates Begin: 07/01/2014
 End: 10/07/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1623ELGE1283 End: 5HZF16209MK002011

Vermeer LPMINIXDT 2021

* **Model Yr. Start:** 2021 * **Model Yr. End:** 2021 **Type:** TRAILERS
 * **Make:** Vermeer **Body Style:**
 * **Model:** LPMINIXDT **Powertrain:**

Production Dates Begin: 01/01/2021
 End: 02/10/2021

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWH16220MK010002 End: 7NWH16223MK010012

Vac-Tron LPSDT 2019 - 2021*** Model Yr. Start:** 2019*** Model Yr. End:** 2021**Type:** TRAILERS*** Make:** Vac-Tron**Body Style:***** Model:** LPSDT**Powertrain:****Production Dates** Begin: 02/01/2019
End: 11/17/2020**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZG1621XKK002013 End: 5HZG16213MK002423**Vermeer LPSDT 2021***** Model Yr. Start:** 2021*** Model Yr. End:** 2021**Type:** TRAILERS*** Make:** Vermeer**Body Style:***** Model:** LPSDT**Powertrain:****Production Dates** Begin: 01/18/2021
End: 04/26/2021**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWG16219MK010020 End: 7NWG16219MK010101**Vac-Tron LPSGT 2019 - 2020***** Model Yr. Start:** 2019*** Model Yr. End:** 2020**Type:** TRAILERS*** Make:** Vac-Tron**Body Style:***** Model:** LPSGT**Powertrain:****Production Dates** Begin: 02/01/2019
End: 07/02/2020**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZH16227KK002001 End: 5HZH16223LK002059**Vermeer LPSGT 2021***** Model Yr. Start:** 2021*** Model Yr. End:** 2021**Type:** TRAILERS*** Make:** Vermeer**Body Style:***** Model:** LPSGT**Powertrain:****Production Dates** Begin: 01/11/2021
End: 03/09/2021**Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWH16229MK010001 End: 7NWH16212MK010011**Vac-Tron LPXDT 2019 - 2021**

* **Model Yr. Start:** 2019 * **Model Yr. End:** 2021
 * **Make:** Vac-Tron
 * **Model:** LPXDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 03/01/2019
 End: 12/05/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZJ16232KK002014 End: 5HZH16223MK000104

Vac-Tron LPMINIXDT 2014 - 2020

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2020
 * **Make:** Vac-Tron
 * **Model:** LPMINIXDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 06/01/2014
 End: 11/01/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1621FLME1100 End: 5HZBF1621FLME1100
VIN Range(s): Begin: 5HZH1622XLK000101 End: 5HZH16223LK000103

Vac-Tron LPMINI 2014 - 2021

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2021
 * **Make:** Vac-Tron
 * **Model:** LPMINI

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 07/01/2014
 End: 10/07/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1623ELGE1283 End: 5HZF16209MK002011

Vac-Tron LP573XDT 2015 - 2019

* **Model Yr. Start:** 2015 * **Model Yr. End:** 2019
 * **Make:** Vac-Tron
 * **Model:** LP573XDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 11/01/2015
 End: 02/01/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628FLLF1278 End: 5HZBF1621KLBK1146

Vac-Tron LP533SDT 2013 - 2017

* **Model Yr. Start:** 2013 * **Model Yr. End:** 2017

Type: TRAILERS

* **Make:** Vac-Tron
 * **Model:** LP533SDT

Body Style:
Powertrain:

Production Dates Begin: 01/01/2013
 End: 04/11/2017

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1621DLAD1042 End: 5HZBF1628HLDH1200

Vac-Tron LP533SGT 2015

* **Model Yr. Start:** 2015 * **Model Yr. End:** 2015
 * **Make:** Vac-Tron
 * **Model:** LP533SGT

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 10/01/2015
 End: 10/01/2015

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628FLKF1259 End: 5HZBF1628FLKF1259

Vac-Tron AIR555SDT 2011 - 2012

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2012
 * **Make:** Vac-Tron
 * **Model:** AIR555SDT

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 04/01/2011
 End: 02/01/2012

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF16251LD11384 End: 5HZBF1627CLBC1181

Vac-Tron AIR573SDT 2016 - 2018

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** AIR573SDT

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 07/01/2016
 End: 03/25/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1623GLGG1214 End: 5HZBF1626JLCJ1214

Vac-Tron AIRSDT 2019

* **Model Yr. Start:** 2019 * **Model Yr. End:** 2019
 * **Make:** Vac-Tron
 * **Model:** AIRSDT

Type: TRAILERS
Body Style:
Powertrain:

Descriptive Information:

Production Dates Begin: 06/17/2019
 End: 06/17/2019

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZA162V8KK002018 End: 5HZA162V8KK002018

Vac-Tron CS350GT 2012

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2012
 * **Make:** Vac-Tron
 * **Model:** CS350GT

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 09/01/2012
 End: 09/01/2012

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1622CLJC1313 End: 5HZBF1622CLJC1313

Vermeer CS418B 2021

* **Model Yr. Start:** 2021 * **Model Yr. End:** 2021
 * **Make:** Vermeer
 * **Model:** CS418B

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 01/08/2021
 End: 04/28/2021

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWF131ZXMGO10001 End: 7NWF131ZOMGO10010

Vac-Tron CS500DT 2012 - 2016

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2016
 * **Make:** Vac-Tron
 * **Model:** CS500DT

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 01/01/2012
 End: 04/01/2016

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628CLAC1154 End: 5HZBF1624GLDG1147

Vac-Tron CS500GT 2011 - 2015

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2015
 * **Make:** Vac-Tron
 * **Model:** CS500GT

Type: TRAILERS
Body Style:
Powertrain:

Production Dates Begin: 07/01/2011
 End: 02/01/2015

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant

to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF16231LG11490 End: 5HZBF1625FLBF1154

Vac-Tron LP550SDT 2012

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2012
 * **Make:** Vac-Tron
 * **Model:** LP550SDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 07/01/2012
 End: 07/01/2012

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628CLGC1298 End: 5HZBF1628CLGC1298

Vac-Tron LP555DT 2011 - 2013

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2013
 * **Make:** Vac-Tron
 * **Model:** LP555DT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 08/01/2011
 End: 02/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1625BLHB1555 End: 5HZBF1622DLBD1067

Vac-Tron LP555SDT 2009 - 2013

* **Model Yr. Start:** 2009 * **Model Yr. End:** 2013
 * **Make:** Vac-Tron
 * **Model:** LP555SDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 11/01/2009
 End: 01/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF16279LL91358 End: 5HZBF1625DLAD1027

Vac-Tron LP573GT 2016

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2016
 * **Make:** Vac-Tron
 * **Model:** LP573GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 04/01/2016
 End: 04/01/2016

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy

provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1621GLDG1154 End: 5HZBF1621GLDG1154

Vac-Tron LP573SDT 2015 - 2019

* **Model Yr. Start:** 2015 * **Model Yr. End:** 2019
 * **Make:** Vac-Tron
 * **Model:** LP573SDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 12/04/2015
 End: 01/01/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1627FLMF1288 End: 5HZBF1629KLAK1568

Vac-Tron LP573SGT 2015 - 2018

* **Model Yr. Start:** 2015 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** LP573SGT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 12/01/2015
 End: 06/27/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1629FLMF1289 End: 5HZBF1629JLJF1376

McLaughlin CS418B 2016 - 2021

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2021
 * **Make:** McLaughlin
 * **Model:** CS418B

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 05/12/2016
 End: 11/17/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 000000CS041416006 End: 000000CS041416006
VIN Range(s): Begin: 7HWF131Z9KG005006 End: 7HWF131Z4MG005031

McLaughlin V25G 2015 - 2019

* **Model Yr. Start:** 2015 * **Model Yr. End:** 2019
 * **Make:** McLaughlin
 * **Model:** V25G

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 05/27/2015
 End: 05/07/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 0000V5S0527151304 End: 0000V5S0830172722
VIN Range(s): Begin: 7HW6162PXKG005014 End: 7HW6162PXKG005014

McLaughlin VX30 2014 - 2020

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2020
 * **Make:** McLaughlin
 * **Model:** VX30

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 07/23/2014
 End: 01/17/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000V5S072314669 End: 0000V5S0220183018
VIN Range(s): Begin: 7HWY192FXJG005028 End: 7HWY192F4LG005108

McLaughlin VX30G 2014 - 2019

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2019
 * **Make:** McLaughlin
 * **Model:** VX30G

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 09/17/2014
 End: 06/03/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 0000VX5S091714788 End: 0000V5S0222183021
VIN Range(s): Begin: 7HWY1152J7JG005003 End: 7HWY1152J7KG005052

McLaughlin VX50 2014 - 2021

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2021
 * **Make:** McLaughlin
 * **Model:** VX50

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 06/20/2014
 End: 02/04/2021

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000VX5062014615 End: 0000V5H0922172780
VIN Range(s): Begin: 7HW4192M0KG005019 End: 7HW4192MVMG005655

McLaughlin V250 2008

* **Model Yr. Start:** 2008 * **Model Yr. End:** 2008
 * **Make:** McLaughlin
 * **Model:** V250

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 01/02/2008
 End: 01/02/2008

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 000VT250DVE101107 End: 000VT250DVE101107

McLaughlin V500LEG 2013 - 2014

* **Model Yr. Start:** 2013 * **Model Yr. End:** 2014
 * **Make:** McLaughlin
 * **Model:** V500LEG

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 01/15/2013
 End: 06/24/2014

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000V5S011513422 End: 00000V5S062414628

McLaughlin V500LELT 2012 - 2014

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2014
 * **Make:** McLaughlin
 * **Model:** V500LELT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 12/10/2012
 End: 01/08/2014

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000V5S121012348 End: 00000V5S010814312

McLaughlin V500LELTHD 2012 - 2014

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2014
 * **Make:** McLaughlin
 * **Model:** V500LELTHD

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 12/06/2012
 End: 03/05/2014

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 00000V5H120112328 End: 00000V5H030514405

McLaughlin V500LT 2007

* **Model Yr. Start:** 2007 * **Model Yr. End:** 2007
 * **Make:** McLaughlin
 * **Model:** V500LT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 06/10/2007
 End: 06/10/2007

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 0000005D060807866 End: 0000005D060807866

Vermeer CVGT 2021

* **Model Yr. Start:** 2021 * **Model Yr. End:** 2021
 * **Make:** Vermeer
 * **Model:** CVGT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 01/15/2021
 End: 04/27/2021

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWC162X1MK010001 End: 7NWC162X9MK010022

Vac-Tron CVSGT 2019 - 2021

* **Model Yr. Start:** 2019 * **Model Yr. End:** 2021
 * **Make:** Vac-Tron
 * **Model:** CVSGT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 02/01/2019
 End: 01/05/2021

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZD162Y7KK002003 End: 5HZD162Y4MK002270

Vermeer LPXDT 2021

* **Model Yr. Start:** 2021 * **Model Yr. End:** 2021
 * **Make:** Vermeer
 * **Model:** LPXDT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 02/10/2021
 End: 02/10/2021

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWX1623XMK010017 End: 7NWX1623XMK010017

Vermeer CVSGT 2021

* **Model Yr. Start:** 2021 * **Model Yr. End:** 2021
 * **Make:** Vermeer
 * **Model:** CVSGT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 01/07/2021
 End: 04/19/2021

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 7NWD162Y5MK010001 End: 7NWD162YXMK010043

Vac-Tron EV150DT 2016

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2016

Type: TRAILERS

* **Make:** Vac-Tron
 * **Model:** EV150DT

Production Dates Begin: 04/01/2016
 End: 04/01/2016

Body Style:**Powertrain:****Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1410GLDG3102 End: 5HZBF1410GLDG3102

Vac-Tron EV150GT 2011 - 2019

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2019
 * **Make:** Vac-Tron
 * **Model:** EV150GT

Production Dates Begin: 08/01/2011
 End: 02/01/2019

Type: TRAILERS**Body Style:****Powertrain:****Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1215BLHB4100 End: 5HZBF141XKLAK3100

Vac-Tron EVGT 2019 - 2021

* **Model Yr. Start:** 2019 * **Model Yr. End:** 2021
 * **Make:** Vac-Tron
 * **Model:** EVGT

Production Dates Begin: 03/30/2019
 End: 11/30/2020

Type: TRAILERS**Body Style:****Powertrain:****Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZE141ZXKK002001 End: 5HZE141Z6MK002015

Vac-Tron FM150SGT 2006

* **Model Yr. Start:** 2006 * **Model Yr. End:** 2006
 * **Make:** Vac-Tron
 * **Model:** FM150SGT

Production Dates Begin: 03/01/2006
 End: 03/01/2006

Type: TRAILERS**Body Style:****Powertrain:****Descriptive Information:**

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF12106LC64107 End: 5HZBF12106LC64107

Vac-Tron FM350SDT 2008

* **Model Yr. Start:** 2008 * **Model Yr. End:** 2008
 * **Make:** Vac-Tron
 * **Model:** FM350SDT

Type: TRAILERS**Body Style:****Powertrain:****Descriptive Information:**

Production Dates Begin: 05/01/2008
 End: 05/01/2008

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF172X8LE87131 End: 5HZBF172X8LE87131

Vac-Tron JETTERTLR 2011 - 2018

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** JETTERTLR

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 11/01/2011
 End: 04/30/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1629BLLB1625 End: 5HZBF1629BLLB1625
VIN Range(s): Begin: 5HZBF1625JLDJ1269 End: 5HZBF1625JLDJ1269

Vac-Tron LP303GT 2013 - 2017

* **Model Yr. Start:** 2013 * **Model Yr. End:** 2017
 * **Make:** Vac-Tron
 * **Model:** LP303GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 08/01/2013
 End: 01/13/2017

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1627DLHD1213 End: 5HZBF1622HLAH1118

Vac-Tron LP303XDT 2016

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2016
 * **Make:** Vac-Tron
 * **Model:** LP303XDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 11/01/2016
 End: 11/01/2016

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1629GLLG1285 End: 5HZBF1629GLLG1285

Vac-Tron LP305DT 2011 - 2013

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2013
 * **Make:** Vac-Tron
 * **Model:** LP305DT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 03/01/2011
 End: 05/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The

machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF16241LC11373 End: 5HZBF1629DLED1169

Vac-Tron LP305GT 2012

* **Model Yr. Start:** 2012 * **Model Yr. End:** 2012
 * **Make:** Vac-Tron
 * **Model:** LP305GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 08/01/2012
 End: 10/01/2012

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF162XCLHC1306 End: 5HZBF1625CLKC1325

Vac-Tron LP333DT 2014

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2014
 * **Make:** Vac-Tron
 * **Model:** LP333DT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 01/01/2014
 End: 04/01/2014

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1627ELAE1124 End: 5HZBF1627ELAE1124
VIN Range(s): Begin: 5HZBF1628ELDE1223 End: 5HZBF1628ELDE1223
VIN Range(s): Begin: 5HZBF1628ELDE1223 End: 5HZBF1628ELDE1223

Vac-Tron LP333GT 2014 - 2015

* **Model Yr. Start:** 2014 * **Model Yr. End:** 2015
 * **Make:** Vac-Tron
 * **Model:** LP333GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 01/01/2014
 End: 05/01/2015

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1627ELAE1155 End: 5HZBF1627ELAE1155
VIN Range(s): Begin: 5HZBF1629FLEF1201 End: 5HZBF1629FLEF1201

Vac-Tron LP355DT 2011 - 2012

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2012
 * **Make:** Vac-Tron
 * **Model:** LP355DT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 08/01/2011
 End: 03/01/2012

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The

machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628BLHB1503 End: 5HZBF1620CLCC1204

Vac-Tron LP355GT 2013

* **Model Yr. Start:** 2013 * **Model Yr. End:** 2013
 * **Make:** Vac-Tron
 * **Model:** LP355GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 05/01/2013
 End: 05/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1622DLED1143 End: 5HZBF1622DLED1143

Vac-Tron LP370XDT 2018

* **Model Yr. Start:** 2018 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** LP370XDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 03/21/2018
 End: 03/21/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1625JLCJ1222 End: 5HZBF1625JLCJ1222

Vac-Tron LP373GT 2015 - 2019

* **Model Yr. Start:** 2015 * **Model Yr. End:** 2019
 * **Make:** Vac-Tron
 * **Model:** LP373GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 12/01/2015
 End: 01/01/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1625FLMF1287 End: 5HZBF1626KLAK1110

Vac-Tron LP373SGT 2016 - 2018

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** LP373SGT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 12/01/2016
 End: 06/05/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy

provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1624GLMG1293 End: 5HZBF1624GLMG1293
VIN Range(s): Begin: 5HZBF1621JLJF1369 End: 5HZBF1621JLJF1369

Vac-Tron AIR373SDT 2017

* **Model Yr. Start:** 2017 * **Model Yr. End:** 2017
 * **Make:** Vac-Tron
 * **Model:** AIR373SDT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 07/10/2017
 End: 07/10/2017

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1626HLGH1284 End: 5HZBF1626HLGH1284

Vac-Tron CS530GT 2015

* **Model Yr. Start:** 2015 * **Model Yr. End:** 2015
 * **Make:** Vac-Tron
 * **Model:** CS530GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 05/01/2015
 End: 05/01/2015

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1623FLEF1209 End: 5HZBF1623FLEF1209

Vac-Tron CS555GT 2013

* **Model Yr. Start:** 2013 * **Model Yr. End:** 2013
 * **Make:** Vac-Tron
 * **Model:** CS555GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 01/01/2013
 End: 01/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1625DLAD1044 End: 5HZBF1625DLAD1044

Vac-Tron CS570GT 2016 - 2018

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** CS570GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 05/01/2016
 End: 02/24/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1621JLBJ1151 End: 5HZBF1621JLBJ1151
VIN Range(s): Begin: 5HZBF1419GLEG3103 End: 5HZBF1419GLEG3103

Vac-Tron CS573GT 2018

* **Model Yr. Start:** 2018 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** CS573GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 02/19/2018
 End: 05/25/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF162XJLBJ1150 End: 5HZBF1628JLEJ1351

Vac-Tron CV570GT 2017 - 2018

* **Model Yr. Start:** 2017 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** CV570GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 08/07/2017
 End: 04/11/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1626HLHH1319 End: 5HZBF1622JLDJ1228

Vac-Tron CV570SGT 2017 - 2018

* **Model Yr. Start:** 2017 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** CV570SGT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 05/21/2017
 End: 03/08/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1623HLEH1219 End: 5HZBF1628JLCJ1196

Vac-Tron CV573GT 2016 - 2018

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** CV573GT

Type: TRAILERS

Body Style:

Powertrain:

Production Dates Begin: 10/01/2016
 End: 12/18/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1624GLKG1272 End: 5HZBF1622KLMJ1554

Vac-Tron CV573SGT 2016 - 2019

* **Model Yr. Start:** 2016 * **Model Yr. End:** 2019
 * **Make:** Vac-Tron
 * **Model:** CV573SGT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 10/01/2016
 End: 01/07/2019

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628GLKG1274 End: 5HZBF1629KLAK1120

Vac-Tron CVGT 2019 - 2021

* **Model Yr. Start:** 2019 * **Model Yr. End:** 2021
 * **Make:** Vac-Tron
 * **Model:** CVGT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 02/01/2019
 End: 12/08/2020

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZC162XXKK002001 End: 5HZC162X4MK002174

Vac-Tron LP373XDT 2017 - 2018

* **Model Yr. Start:** 2017 * **Model Yr. End:** 2018
 * **Make:** Vac-Tron
 * **Model:** LP373XDT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 05/07/2017
 End: 03/26/2018

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1627HLEH1207 End: 5HZBF1627JLCJ1223

Vac-Tron LP500GT 2011

* **Model Yr. Start:** 2011 * **Model Yr. End:** 2011
 * **Make:** Vac-Tron
 * **Model:** LP500GT

Type: TRAILERS**Body Style:****Powertrain:**

Production Dates Begin: 11/01/2011
 End: 11/01/2011

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF1628BLLB1616 End: 5HZBF1628BLLB1616

Vac-Tron LP500DT 2013

* **Model Yr. Start:** 2013* **Model Yr. End:** 2013**Type:** TRAILERS* **Make:** Vac-Tron**Body Style:*** **Model:** LP500DT**Powertrain:**

Production Dates Begin: 04/01/2013
 End: 04/01/2013

Descriptive Information:

Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

VIN Range(s): Begin: 5HZBF162XLDD1114 End: 5HZBF162XLDD1114

Number potentially involved: 1308**Estimated percentage of involved with defect:** 100%**Defect / Noncompliance Description**

For this Defect/Noncompliance:

*** Describe the defect or noncompliance:**

Missing tire placard.

If a noncompliance, provide the applicable FMVSS:

110 - Tire selection and rims

If applicable, provide any further FMVSS affected:**Describe the cause:***** Describe the safety risk:**

Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Identify any warning which can precede or occur:**This Recall affects all vehicles.**

If applicable, identify the manufacturer of the defective or noncompliant component. If the manufacturer of the component is unknown, provide the information for the company that supplied the subject component.

Component manufacturer

Company Information

Company Contact Information

Company Name:**First Name:****Country:****Last Name:****Address 1:****Position:****Address 2:****Email:****City:****Phone:****State:****Zip/Postal Code:****Involved Components**

If the defect or noncompliance involves a specific component(s), identify that component(s) below.

Chronology of Defect / Noncompliance Determination**Provide the chronology of events leading up to the defect decision or test data for the noncompliance decision.:**

19-Feb-2021 – Investigation begins. Product Compliance and Product Safety identify need to research what information relating to tires and rims is available for affected vehicles and how that information is presented to end users. Discovered when Product Safety department at Vermeer Corporation took over responsibility for certain aspects of the issuance of Vermeer MV Solutions, Inc. MSOs. 9-Mar-2021 – Product Safety reported that tire size, tire pressure, and rim size are on the VIN plates since 2012. 8-Apr-2021 – Product Compliance met with Product Safety for a status update. 12-Apr-2021 - Product Compliance met with Legal to further discuss investigation. 14-Apr-2021 – Legal began investigation of possible noncompliance. 20-Apr-2021 – Legal determined a noncompliance existed.

Identify the Remedy**Describe the defect/noncompliance remedy program, including the manufacturer's plan for reimbursement.**

Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Describe what distinguishes the remedy component from the recalled component.**Identify and describe how and when the recall condition was corrected in production.****Identify the Recall Schedule****Describe the recall schedule for notifications.:**

Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it

Planned Dealer Notification Begin Date:**Planned Dealer Notification End Date:****Planned Owner Notification Begin Date:**

relates to motor vehicle safety. To be determined, pending the agency's disposition of the above-mentioned Part 556 petition for exemption.

Planned Owner Notification End Date:

Manufacturer's identification code for this recall (if applicable):

Please be reminded that owner notification letters must be mailed no more than 60 days from submission of this report.

Manufacturer Comments to NHTSA Staff

Document Upload

There are 0 documents associated with this report.

Part 573 Safety Recall Report

21V-296

Manufacturer Name : Vermeer Manufacturing Company**Submission Date :** APR 26, 2021**NHTSA Recall No. :** 21V-296**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Vermeer Manufacturing Company

Address : 1210 VERMEER ROAD EAST

PO BOX 200 PELLA IA 50219-0200

Company phone : 641-628-3141

Population :

Number of potentially involved : 895

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Vac-Tron AIR373SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.

The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 10, 2017 - JUL 10, 2017

VIN Range 1 : Begin : 5HZBF1626HLGH1284 End : 5HZBF1626HLGH1284 Not sequential

Vehicle 2 : 2012-2012 Vac-Tron AIR555SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.

The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2012 - FEB 01, 2012

VIN Range 1 : Begin : 5HZBF1627CLBC1181 End : 5HZBF1627CLBC1181 Not sequential

Vehicle 3 : 2016-2018 Vac-Tron CS570GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2016 - FEB 24, 2018

VIN Range 1 : Begin : 5HZBF1419GLEG3103 End : 5HZBF1419GLEG3103 Not sequential

VIN Range 2 : Begin : 5HZBF1621JLBJ1151 End : 5HZBF1621JLBJ1151 Not sequential

VIN Range 3 : Begin : 5HZBF1621JLBJ1151 End : 5HZBF1621JLBJ1151 Not sequential

Vehicle 4 : 2017-2018 Vac-Tron CV570SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 21, 2017 - MAR 08, 2018

VIN Range 1 : Begin : 5HZBF1623HLEH1219 End : 5HZBF1628JLCJ1196 Not sequential

Vehicle 5 : 2019-2021 Vac-Tron CVGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - DEC 08, 2019

VIN Range 1 : Begin : 5HZC162XXKK002001 End : 5HZC162X4MK002174 Not sequential

Vehicle 6 : 2016-2018 Vac-Tron AIR573SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2016 - MAR 25, 2018

VIN Range 1 : Begin : 5HZBF1623GLGG1214 End : 5HZBF1626JLCJ1214 Not sequential

Vehicle 7 : 2019-2019 Vac-Tron AIRSDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 17, 2019 - JUN 17, 2019

VIN Range 1 : Begin : 5HZA162V8KK002018 End : 5HZA162V8KK002018 Not sequential

Vehicle 8 : 2013-2013 Vac-Tron CS350GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : SEP 01, 2012 - SEP 01, 2012

VIN Range 1 : Begin : 5HZBF1622CLJC1313 End : 5HZBF1622CLJC1313 Not sequential

Vehicle 9 : 2016-2021 Vermeer CS418B

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.

The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 12, 2016 - APR 23, 2021

VIN Range 1 : Begin : 00000CS0414146006 End : 00000CS0414146006 Not sequential

VIN Range 2 : Begin : 000000CS010818022 End : 000000CS042319039 Not sequential

VIN Range 3 : Begin : 7HWF131ZXKG005001 End : 7HWF131Z6MG005032 Not sequential

VIN Range 4 : Begin : 7NWF131ZXMG010001 End : 7NWF131Z0MG010010 Not sequential

Vehicle 10 : 2012-2016 Vac-Tron CS500DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.

The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2012 - APR 01, 2016

VIN Range 1 : Begin : 5HZBF1628CLAC1154 End : 5HZBF1624GLDG1147 Not sequential

Vehicle 11 : 2012-2015 Vac-Tron CS500GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.

The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2012 - FEB 01, 2015

VIN Range 1 : Begin : 5HZBF1627CLAC1100 End : 5HZBF1625FLBF1154 Not sequential

Vehicle 12 : 2015-2015 Vac-Tron CS530GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2015 - MAY 01, 2015

VIN Range 1 : Begin : 5HZBF1623FLEF1209 End : 5HZBF1623FLEF1209 Not sequential

Vehicle 13 : 2013-2013 Vac-Tron CS555GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2013 - JAN 01, 2013

VIN Range 1 : Begin : 5HZBF1625DLAD1044 End : 5HZBF1625DLAD1044 Not sequential

Vehicle 14 : 2018-2018 Vac-Tron CS573GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 19, 2018 - MAY 25, 2018

VIN Range 1 : Begin : 5HZBF162XJLBJ1150 End : 5HZBF1628JLEJ1351 Not sequential

Vehicle 15 : 2018-2018 Vac-Tron CV570GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 07, 2017 - APR 11, 2018

VIN Range 1 : Begin : 5HZBF1626HLHH1319 End : 5HZBF1622JLDJ1228 Not sequential

Vehicle 16 : 2017-2019 Vac-Tron CV573GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2016 - DEC 18, 2018

VIN Range 1 : Begin : 5HZBF1624GLKG1272 End : 5HZBF1622KLMJ1554 Not sequential

Vehicle 17 : 2017-2019 Vac-Tron CV573SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2016 - JAN 07, 2019

VIN Range 1 : Begin : 5HZBF1628GLKG1274 End : 5HZBF1629KLAK1120 Not sequential

Vehicle 18 : 2021-2021 Vermeer CVGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 15, 2021 - APR 23, 2021

VIN Range 1 : Begin : 7NWC162X1MK010001 End : 7NWC162X0MK010023 Not sequential

Vehicle 19 : 2019-2021 Vac-Tron CVSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - JAN 05, 2021

VIN Range 1 : Begin : 5HZD162Y7KK002003 End : 5HZD162Y4MK002270 Not sequential

Vehicle 20 : 2016-2016 Vac-Tron EV150DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2016 - APR 01, 2016

VIN Range 1 : Begin : 5HZBF1410GLDG3102 End : 5HZBF1410GLDG3102 Not sequential

Vehicle 21 : 2012-2019 Vac-Tron EV150GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2011 - FEB 01, 2019

VIN Range 1 : Begin : 5HZBF1215BLHB4100 End : 5HZBF141XKLAK3100 Not sequential

Vehicle 22 : 2019-2021 Vac-Tron EVGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 30, 2019 - NOV 30, 2020

VIN Range 1 : Begin : 5HZE141ZXKK002001 End : 5HZE141Z6MK002015 Not sequential

Vehicle 23 : 2006-2006 Vac-Tron FM150SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 01, 2006 - MAR 01, 2006

VIN Range 1 : Begin : 5HZBF12106LC64107 End : 5HZBF12106LC64107 Not sequential

Vehicle 24 : 2021-2021 Vermeer CVSGT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 07, 2021 - APR 23, 2021

VIN Range 1 : Begin : 7NWD162Y5MK010001 End : 7NWD162Y6MK010038 Not sequential

Vehicle 25 : 2012-2012 Vac-Tron LP355DT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2011 - MAR 01, 2012

VIN Range 1 : Begin : 5HZBF1628BLHB1503 End : 5HZBF1620CLCC1204 Not sequential

Vehicle 26 : 2018-2018 Vac-Tron LP370XDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 21, 2018 - MAR 21, 2018

VIN Range 1 : Begin : 5HZBF1625JLCJ1222 End : 5HZBF1625JLCJ1222 Not sequential

Vehicle 27 : 2017-2018 Vac-Tron LP373XDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 02, 2017 - MAR 26, 2018

VIN Range 1 : Begin : 5HZBF1625HLEH1206 End : 5HZBF1627JLCJ1223 Not sequential

Vehicle 28 : 2013-2013 Vac-Tron LP500DT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2013 - APR 01, 2013

VIN Range 1 : Begin : 5HZBF162XDLDD1114 End : 5HZBF162XDLDD1114 Not sequential

Vehicle 29 : 2008-2008 Vac-Tron FM350SDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2008 - MAY 01, 2008

VIN Range 1 : Begin : 5HZBF172X8LE87131 End : 5HZBF172X8LE87131 Not sequential

Vehicle 30 : 2012-2018 Vac-Tron JETTERTLR

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2011 - APR 30, 2018

VIN Range 1 : Begin : 5HZBF1629BLLB1625 End : 5HZBF1629BLLB1625 Not sequential

VIN Range 2 : Begin : 5HZBF1625JLDJ1269 End : 5HZBF1625JLDJ1269 Not sequential

Vehicle 31 : 2014-2017 Vac-Tron LP303GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2013 - JAN 13, 2017

VIN Range 1 : Begin : 5HZBF1627DLHD1213 End : 5HZBF1622HLAH1118 Not sequential

Vehicle 32 : 2017-2017 Vac-Tron LP303XDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2016 - NOV 01, 2016

VIN Range 1 : Begin : 5HZBF1629GLLG1285 End : 5HZBF1629GLLG1285 Not sequential

Vehicle 33 : 2012-2013 Vac-Tron LP305DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2011 - MAY 01, 2013

VIN Range 1 : Begin : 5HZBF1623BLKB1553 End : 5HZBF1629DLED1169 Not sequential

Vehicle 34 : 2013-2013 Vac-Tron LP305GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2012 - OCT 01, 2012

VIN Range 1 : Begin : 5HZBF162XLHC1306 End : 5HZBF1625CLKC1325 Not sequential

Vehicle 35 : 2014-2014 Vac-Tron LP333DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2014 - APR 01, 2014

VIN Range 1 : Begin : 5HZBF1627ELAE1124 End : 5HZBF1628ELDE1223 Not sequential

Vehicle 36 : 2014-2015 Vac-Tron LP333GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2014 - MAY 01, 2015

VIN Range 1 : Begin : 5HZBF1627ELAE1155 End : 5HZBF1627ELAE1155 Not sequential

VIN Range 2 : Begin : 5HZBF1629FLEF1201 End : 5HZBF1629FLEF1201 Not sequential

Vehicle 37 : 2013-2013 Vac-Tron LP355GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2013 - MAY 01, 2013

VIN Range 1 : Begin : 5HZBF1622DLED1143 End : 5HZBF1622DLED1143 Not sequential

Vehicle 38 : 2016-2016 Vac-Tron LP373GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 01, 2015 - JAN 01, 2019

VIN Range 1 : Begin : 5HZBF1625FLMF1287 End : 5HZBF1626KLAK1110 Not sequential

Vehicle 39 : 2017-2018 Vac-Tron LP373SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 01, 2016 - JUN 05, 2018

VIN Range 1 : Begin : 5HZBF1624GLMG1293 End : 5HZBF1624GLMG1293 Not sequential

VIN Range 2 : Begin : 5HZBF1621JLFJ1369 End : 5HZBF1621JLFJ1369 Not sequential

Vehicle 40 : 2012-2012 Vac-Tron LP500GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2011 - NOV 01, 2011

VIN Range 1 : Begin : 5HZBF1628BLLB1616 End : 5HZBF1628BLLB1616 Not sequential

Vehicle 41 : 2014-2017 Vac-Tron LP533SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2013 - APR 11, 2017

VIN Range 1 : Begin : 5HZBF1621DLAD1042 End : 5HZBF1628HLDH1200 Not sequential

Vehicle 42 : 2016-2016 Vac-Tron LP533SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2015 - OCT 01, 2015

VIN Range 1 : Begin : 5HZBF1628FLKF1259 End : 5HZBF1628FLKF1259 Not sequential

Vehicle 43 : 2012-2013 Vac-Tron LP555DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2011 - FEB 01, 2013

VIN Range 1 : Begin : 5HZBF1625BLHB1555 End : 5HZBF1622DLBD1067 Not sequential

Vehicle 44 : 2010-2013 Vac-Tron LP555SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2009 - JAN 01, 2013

VIN Range 1 : Begin : 5HZBF16279LL91358 End : 5HZBF1625DLAD1027 Not sequential

Vehicle 45 : 2016-2016 Vac-Tron LP573GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2016 - APR 01, 2016

VIN Range 1 : Begin : 5HZBF1621GLDG1154 End : 5HZBF1621GLDG1154 Not sequential

Vehicle 46 : 2014-2021 Vac-Tron LPMINI

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2014 - OCT 07, 2020

VIN Range 1 : Begin : 5HZBF1623ELGE1283 End : 5HZF16209MK002011 Not sequential

Vehicle 47 : 2012-2012 Vac-Tron LP550SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2012 - JUL 01, 2012

VIN Range 1 : Begin : 5HZBF1628CLGC1298 End : 5HZBF1628CLGC1298 Not sequential

Vehicle 48 : 2016-2019 Vac-Tron LP573SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 04, 2015 - JAN 01, 2019

VIN Range 1 : Begin : 5HZBF1627FLMF1288 End : 5HZBF1629KLAK1568 Not sequential

Vehicle 49 : 2016-2018 Vac-Tron LP573SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 01, 2015 - JUN 27, 2018

VIN Range 1 : Begin : 5HZBF1629FLMF1289 End : 5HZBF1629JLFJ1376 Not sequential

Vehicle 50 : 2016-2019 Vac-Tron LP573XDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2015 - FEB 01, 2019

VIN Range 1 : Begin : 5HZBF1628FLLF1278 End : 5HZBF1621KLBK1146 Not sequential

Vehicle 51 : 2014-2021 Vac-Tron LPMINI
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2014 - OCT 07, 2020

VIN Range 1 : Begin : 5HZBF1623ELGE1283 End : 5HZF16209MK002011 Not sequential

Vehicle 52 : 2021-2021 Vermeer LPMINI
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 25, 2021 - FEB 25, 2021

VIN Range 1 : Begin : 7NWF16201MK010001 End : 7NWF16201MK010001 Not sequential

Vehicle 53 : 2021-2021 Vermeer LPSDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 18, 2021 - APR 23, 2021

VIN Range 1 : Begin : 7NWG16219MK010020 End : 7NWG16219MK010101 Not sequential

Vehicle 54 : 2019-2020 Vac-Tron LPXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 01, 2019 - JUL 01, 2021

VIN Range 1 : Begin : 5HZJ16232KK002014 End : 5HZJ16239LK002190 Not sequential

Vehicle 55 : 2014-2021 Vac-Tron LPMINIXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 01, 2014 - DEC 05, 2020

VIN Range 1 : Begin : 5HZBF1621FLME1100 End : 5HZBF1621FLME1100 Not sequential

VIN Range 2 : Begin : 5HZH1622XLK000101 End : 5HZH16223MK000104 Not sequential

Vehicle 56 : 2021-2021 Vermeer LPMINIXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2021 - FEB 10, 2021

VIN Range 1 : Begin : 7NWH16229MK010001 End : 7NWH16223MK010012 Not sequential

Vehicle 57 : 2019-2021 Vac-Tron LPSDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - NOV 17, 2020

VIN Range 1 : Begin : 5HZG1621XKK002013 End : 5HZG16213MK002423 Not sequential

Vehicle 58 : 2019-2020 Vac-Tron LPSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - JUL 02, 2020

VIN Range 1 : Begin : 5HZH16227KK002001 End : 5HZH16223LK002059 Not sequential

Vehicle 59 : 2021-2021 Vermeer LPSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 09, 2021 - MAR 09, 2021

VIN Range 1 : Begin : 7NWH16212MK010011 End : 7NWH16212MK010011 Not sequential

Vehicle 60 : 2021-2021 Vermeer LPXDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 10, 2021 - APR 23, 2021

VIN Range 1 : Begin : 7NWJ1623XMK010017 End : 7NWJ16236MK010063 Not sequential

Description of Noncompliance :

Description of the Noncompliance : Missing tire placard.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

19-Feb-2021 – Investigation begins. Product Compliance and Product Safety identify need to research what information relating to tires and rims is available for affected vehicles and how that information is presented to end users. Discovered when Product Safety department at Vermeer Corporation took over responsibility for certain aspects of the issuance of Vermeer MV Solutions, Inc. MSOs.

9-Mar-2021 – Product Safety reported that tire size, tire pressure, and rim size are on the VIN plates since 2012.

8-Apr-2021 – Product Compliance met with Product Safety for a status update.

12-Apr-2021 - Product Compliance met with Legal to further discuss investigation.

14-Apr-2021 – Legal began investigation of possible noncompliance.

20-Apr-2021 – Legal determined a noncompliance existed.

Description of Remedy :

Description of Remedy Program : Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety. To be determined, pending the agency's disposition of the above-mentioned Part 556 petition for exemption.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported

Part 573 Safety Recall Report

21V-296

Manufacturer Name : Vermeer Manufacturing Company**Submission Date :** MAY 14, 2021**NHTSA Recall No. :** 21V-296**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Vermeer Manufacturing Company

Address : 1210 VERMEER ROAD EAST

PO BOX 200 PELLA IA 50219-0200

Company phone : 641-628-3141

Population :

Number of potentially involved : 1,312

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Vac-Tron AIR373SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.

The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 10, 2017 - JUL 10, 2017

VIN Range 1 : Begin : 5HZBF1626HLGH1284 End : 5HZBF1626HLGH1284 Not sequential

Vehicle 2 : 2011-2012 Vac-Tron AIR555SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.

The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2011 - FEB 01, 2012

VIN Range 1 : Begin : 5HZBF16251LD11384 End : 5HZBF1627CLBC1181 Not sequential

Vehicle 3 : 2016-2018 Vac-Tron AIR573SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2016 - MAR 25, 2018

VIN Range 1 : Begin : 5HZBF1623GLGG1214 End : 5HZBF1626JLCJ1214 Not sequential

Vehicle 4 : 2019-2019 Vac-Tron AIRSDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 17, 2019 - JUN 17, 2019

VIN Range 1 : Begin : 5HZA162V8KK002018 End : 5HZA162V8KK002018 Not sequential

Vehicle 5 : 2012-2012 Vac-Tron CS350GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : SEP 01, 2012 - SEP 01, 2012

VIN Range 1 : Begin : 5HZBF1622CLJC1313 End : 5HZBF1622CLJC1313 Not sequential

Vehicle 6 : 2021-2021 Vermeer CS418B

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 08, 2021 - APR 28, 2021

VIN Range 1 : Begin : 7NWF131ZXMG010001 End : 7NWF131Z0MG010010 Not sequential

Vehicle 7 : 2012-2016 Vac-Tron CS500DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2012 - APR 01, 2016

VIN Range 1 : Begin : 5HZBF1628CLAC1154 End : 5HZBF1624GLDG1147 Not sequential

Vehicle 8 : 2011-2015 Vac-Tron CS500GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2011 - FEB 01, 2015

VIN Range 1 : Begin : 5HZBF16231LG11490 End : 5HZBF1625FLBF1154 Not sequential

Vehicle 9 : 2015-2015 Vac-Tron CS530GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2015 - MAY 01, 2015

VIN Range 1 : Begin : 5HZBF1623FLEF1209 End : 5HZBF1623FLEF1209 Not sequential

Vehicle 10 : 2013-2013 Vac-Tron CS555GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2013 - JAN 01, 2013

VIN Range 1 : Begin : 5HZBF1625DLAD1044 End : 5HZBF1625DLAD1044 Not sequential

Vehicle 11 : 2016-2018 Vac-Tron CS570GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2016 - FEB 24, 2018

VIN Range 1 : Begin : 5HZBF1621JLBJ1151 End : 5HZBF1621JLBJ1151 Not sequential

VIN Range 2 : Begin : 5HZBF1419GLEG3103 End : 5HZBF1419GLEG3103 Not sequential

Vehicle 12 : 2018-2018 Vac-Tron CS573GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 19, 2018 - MAY 25, 2018

VIN Range 1 : Begin : 5HZBF162XJLBJ1150 End : 5HZBF1628JLEJ1351 Not sequential

Vehicle 13 : 2017-2018 Vac-Tron CV570GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 07, 2017 - APR 11, 2018

VIN Range 1 : Begin : 5HZBF1626HLHH1319 End : 5HZBF1622JLDJ1228 Not sequential

Vehicle 14 : 2017-2018 Vac-Tron CV570SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 21, 2017 - MAR 08, 2018

VIN Range 1 : Begin : 5HZBF1623HLEH1219 End : 5HZBF1628JLCJ1196 Not sequential

Vehicle 15 : 2016-2018 Vac-Tron CV573GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2016 - DEC 18, 2018

VIN Range 1 : Begin : 5HZBF1624GLKG1272 End : 5HZBF1622KLMJ1554 Not sequential

Vehicle 16 : 2016-2019 Vac-Tron CV573SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2016 - JAN 07, 2019

VIN Range 1 : Begin : 5HZBF1628GLKG1274 End : 5HZBF1629KLAK1120 Not sequential

Vehicle 17 : 2019-2021 Vac-Tron CVGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - DEC 08, 2020

VIN Range 1 : Begin : 5HZC162XXKK002001 End : 5HZC162X4MK002174 Not sequential

Vehicle 18 : 2021-2021 Vermeer CVGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 15, 2021 - MAY 04, 2021

VIN Range 1 : Begin : 7NWC162X1MK010001 End : 7NWC162X0MK010023 Not sequential

Vehicle 19 : 2019-2021 Vac-Tron CVSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - JAN 05, 2021

VIN Range 1 : Begin : 5HZD162Y7KK002003 End : 5HZD162Y4MK002270 Not sequential

Vehicle 20 : 2021-2021 Vermeer CVSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 07, 2021 - MAY 03, 2021

VIN Range 1 : Begin : 7NWD162Y5MK010001 End : 7NWD162Y9MK010048 Not sequential

Vehicle 21 : 2016-2016 Vac-Tron EV150DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2016 - APR 01, 2016

VIN Range 1 : Begin : 5HZBF1410GLDG3102 End : 5HZBF1410GLDG3102 Not sequential

Vehicle 22 : 2011-2019 Vac-Tron EV150GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2011 - FEB 01, 2019

VIN Range 1 : Begin : 5HZBF1215BLHB4100 End : 5HZBF141XKLAK3100 Not sequential

Vehicle 23 : 2019-2021 Vac-Tron EVGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 30, 2019 - NOV 30, 2020

VIN Range 1 : Begin : 5HZE141ZXKK002001 End : 5HZE141Z6MK002015 Not sequential

Vehicle 24 : 2006-2006 Vac-Tron FM150SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 01, 2006 - MAR 01, 2006

VIN Range 1 : Begin : 5HZBF12106LC64107 End : 5HZBF12106LC64107 Not sequential

Vehicle 25 : 2008-2008 Vac-Tron FM350SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2008 - MAY 01, 2008

VIN Range 1 : Begin : 5HZBF172X8LE87131 End : 5HZBF172X8LE87131 Not sequential

Vehicle 26 : 2011-2018 Vac-Tron JETTERTLR

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2011 - APR 30, 2018

VIN Range 1 : Begin : 5HZBF1629BLLB1625 End : 5HZBF1629BLLB1625 Not sequential

VIN Range 2 : Begin : 5HZBF1625JLDJ1269 End : 5HZBF1625JLDJ1269 Not sequential

Vehicle 27 : 2013-2017 Vac-Tron LP303GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2013 - JAN 13, 2017

VIN Range 1 : Begin : 5HZBF1627DLHD1213 End : 5HZBF1622HLAH1118 Not sequential

Vehicle 28 : 2016-2016 Vac-Tron LP303XDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2016 - NOV 01, 2016

VIN Range 1 : Begin : 5HZBF1629GLLG1285 End : 5HZBF1629GLLG1285 Not sequential

Vehicle 29 : 2011-2013 Vac-Tron LP305DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 01, 2011 - MAY 01, 2013

VIN Range 1 : Begin : 5HZBF16241LC11373 End : 5HZBF1629DLED1169 Not sequential

Vehicle 30 : 2012-2012 Vac-Tron LP305GT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2012 - OCT 01, 2012

VIN Range 1 : Begin : 5HZBF162XCLHC1306 End : 5HZBF1625CLKC1325 Not sequential

Vehicle 31 : 2014-2014 Vac-Tron LP333DT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2014 - APR 01, 2014

VIN Range 1 : Begin : 5HZBF1628ELDE1223 End : 5HZBF1628ELDE1223 Not sequential
VIN Range 2 : Begin : 5HZBF1628ELDE1223 End : 5HZBF1628ELDE1223 Not sequential
VIN Range 3 : Begin : 5HZBF1627ELAE1124 End : 5HZBF1627ELAE1124 Not sequential

Vehicle 32 : 2014-2015 Vac-Tron LP333GT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2014 - MAY 01, 2015

VIN Range 1 : Begin : 5HZBF1627ELAE1155 End : 5HZBF1627ELAE1155 Not sequential
VIN Range 2 : Begin : 5HZBF1629FLEF1201 End : 5HZBF1629FLEF1201 Not sequential

Vehicle 33 : 2011-2012 Vac-Tron LP355DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2011 - MAR 01, 2012

VIN Range 1 : Begin : 5HZBF1628BLHB1503 End : 5HZBF1620CLCC1204 Not sequential

Vehicle 34 : 2013-2013 Vac-Tron LP355GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2013 - MAY 01, 2013

VIN Range 1 : Begin : 5HZBF1622DLED1143 End : 5HZBF1622DLED1143 Not sequential

Vehicle 35 : 2018-2018 Vac-Tron LP370XDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 21, 2018 - MAR 21, 2018

VIN Range 1 : Begin : 5HZBF1625JLCJ1222 End : 5HZBF1625JLCJ1222 Not sequential

Vehicle 36 : 2015-2019 Vac-Tron LP373GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 01, 2015 - JAN 01, 2019

VIN Range 1 : Begin : 5HZBF1625FLMF1287 End : 5HZBF1626KLAK1110 Not sequential

Vehicle 37 : 2016-2018 Vac-Tron LP373SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 01, 2016 - JUN 05, 2018

VIN Range 1 : Begin : 5HZBF1624GLMG1293 End : 5HZBF1624GLMG1293 Not sequential

VIN Range 2 : Begin : 5HZBF1621JLFJ1369 End : 5HZBF1621JLFJ1369 Not sequential

Vehicle 38 : 2017-2018 Vac-Tron LP373XDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 07, 2017 - MAR 26, 2018

VIN Range 1 : Begin : 5HZBF1627HLEH1207 End : 5HZBF1627JLCJ1223 Not sequential

Vehicle 39 : 2013-2013 Vac-Tron LP500DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2013 - APR 01, 2013

VIN Range 1 : Begin : 5HZBF162XDLDD1114 End : 5HZBF162XDLDD1114 Not sequential

Vehicle 40 : 2011-2011 Vac-Tron LP500GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2011 - NOV 01, 2011

VIN Range 1 : Begin : 5HZBF1628BLLB1616 End : 5HZBF1628BLLB1616 Not sequential

Vehicle 41 : 2013-2017 Vac-Tron LP533SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2013 - APR 11, 2017

VIN Range 1 : Begin : 5HZBF1621DLAD1042 End : 5HZBF1628HLDH1200 Not sequential

Vehicle 42 : 2015-2015 Vac-Tron LP533SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2015 - OCT 01, 2015

VIN Range 1 : Begin : 5HZBF1628FLKF1259 End : 5HZBF1628FLKF1259 Not sequential

Vehicle 43 : 2012-2012 Vac-Tron LP550SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2012 - JUL 01, 2012

VIN Range 1 : Begin : 5HZBF1628CLGC1298 End : 5HZBF1628CLGC1298 Not sequential

Vehicle 44 : 2011-2013 Vac-Tron LP555DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2011 - FEB 01, 2013

VIN Range 1 : Begin : 5HZBF1625BLHB1555 End : 5HZBF1622DLBD1067 Not sequential

Vehicle 45 : 2009-2013 Vac-Tron LP555SDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2009 - JAN 01, 2013

VIN Range 1 : Begin : 5HZBF16279LL91358 End : 5HZBF1625DLAD1027 Not sequential

Vehicle 46 : 2016-2016 Vac-Tron LP573GT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2016 - APR 01, 2016

VIN Range 1 : Begin : 5HZBF1621GLDG1154 End : 5HZBF1621GLDG1154 Not sequential

Vehicle 47 : 2015-2019 Vac-Tron LP573SDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 04, 2015 - JAN 01, 2019

VIN Range 1 : Begin : 5HZBF1627FLMF1288 End : 5HZBF1629KLAK1568 Not sequential

Vehicle 48 : 2015-2018 Vac-Tron LP573SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 01, 2015 - JUN 27, 2018

VIN Range 1 : Begin : 5HZBF1629FLMF1289 End : 5HZBF1629JLFJ1376 Not sequential

Vehicle 49 : 2015-2019 Vac-Tron LP573XDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2015 - FEB 01, 2019

VIN Range 1 : Begin : 5HZBF1628FLLF1278 End : 5HZBF1621KLBK1146 Not sequential

Vehicle 50 : 2014-2021 Vac-Tron LPMINI

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2014 - OCT 07, 2020

VIN Range 1 : Begin : 5HZBF1623ELGE1283 End : 5HZF16209MK002011 Not sequential

Vehicle 51 : 2014-2021 Vac-Tron LPMINI

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2014 - OCT 07, 2020

VIN Range 1 : Begin : 5HZBF1623ELGE1283 End : 5HZF16209MK002011 Not sequential

Vehicle 52 : 2021-2021 Vermeer LPMINI

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 25, 2021 - FEB 25, 2021

VIN Range 1 : Begin : 7NWF16201MK010001 End : 7NWF16201MK010001 Not sequential

VIN Range 2 : Begin : 1MV4192MCMG010017 End : 1MV4192MTMG010018 Not sequential

Vehicle 53 : 2014-2020 Vac-Tron LPMINIXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 01, 2014 - NOV 01, 2019

VIN Range 1 : Begin : 5HZBF1621FLME1100 End : 5HZBF1621FLME1100 Not sequential

VIN Range 2 : Begin : 5HZH1622XLK000101 End : 5HZH16223LK000103 Not sequential

Vehicle 54 : 2021-2021 Vermeer LPMINIXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2021 - FEB 10, 2021

VIN Range 1 : Begin : 7NWH16220MK010002 End : 7NWH16223MK010012 Not sequential

Vehicle 55 : 2019-2021 Vac-Tron LPSDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - NOV 17, 2020

VIN Range 1 : Begin : 5HZG1621XKK002013 End : 5HZG16213MK002423 Not sequential

Vehicle 56 : 2021-2021 Vermeer LPSDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 18, 2021 - APR 26, 2021

VIN Range 1 : Begin : 7NWG16219MK010020 End : 7NWG16219MK010101 Not sequential

Vehicle 57 : 2019-2020 Vac-Tron LPSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - JUL 02, 2020

VIN Range 1 : Begin : 5HZH16227KK002001 End : 5HZH16223LK002059 Not sequential

Vehicle 58 : 2021-2021 Vermeer LPSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 11, 2021 - MAR 09, 2021

VIN Range 1 : Begin : 7NWH16229MK010001 End : 7NWH16212MK010011 Not sequential

Vehicle 59 : 2019-2021 Vac-Tron LPXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 01, 2019 - DEC 05, 2020

VIN Range 1 : Begin : 5HZJ16232KK002014 End : 5HZH16223MK000104 Not sequential

Vehicle 60 : 2021-2021 Vermeer LPXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 10, 2021 - APR 29, 2021

VIN Range 1 : Begin : 7NWJ1623XMK010017 End : 7NWJ16236MK010063 Not sequential

Vehicle 61 : 2016-2021 McLaughlin CS418B

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 12, 2016 - NOV 17, 2020

VIN Range 1 : Begin : 000000CS041416006 End : 000000CS041416006 Not sequential

VIN Range 2 : Begin : 7HWF131Z9KG005006 End : 7HWF131Z4MG005031 Not sequential

Vehicle 62 : 2012-2014 McLaughlin V500LELT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 10, 2012 - JAN 08, 2014

VIN Range 1 : Begin : 00000V5S121012348 End : 00000V5S010814312 Not sequential

Vehicle 63 : 2012-2014 McLaughlin V500LELTHD

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 06, 2012 - MAR 05, 2014

VIN Range 1 : Begin : 00000V5H120112328 End : 00000V5H030514405 Not sequential

Vehicle 64 : 2015-2019 McLaughlin V25G

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 27, 2015 - MAY 07, 2018

VIN Range 1 : Begin : 0000V5S0527151304 End : 0000V5S0830172722 Not sequential

VIN Range 2 : Begin : 7HW6162PXKG005014 End : 7HW6162PXKG005014 Not sequential

Vehicle 65 : 2014-2020 McLaughlin VX30

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 23, 2014 - JAN 17, 2020

VIN Range 1 : Begin : 00000V5S072314669 End : 0000V5S0220183018 Not sequential

VIN Range 2 : Begin : 7HWY192FXJG005028 End : 7HWY192F4LG005108 Not sequential

Vehicle 66 : 2014-2019 McLaughlin VX30G
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : SEP 17, 2014 - JUN 03, 2019

VIN Range 1 : Begin : 0000VX5S091714788 End : 0000V5S0222183021 Not sequential
VIN Range 2 : Begin : 7HW1152J7JG005003 End : 7HW1152J7KG005052 Not sequential

Vehicle 67 : 2014-2021 McLaughlin VX50
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 20, 2014 - FEB 04, 2021

VIN Range 1 : Begin : 00000VX5062014615 End : 0000V5H0922172780 Not sequential
VIN Range 2 : Begin : 7HW4192M0KG005019 End : 7HW4192MVMG005655 Not sequential

Vehicle 68 : 2008-2008 McLaughlin V250
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 02, 2008 - JAN 02, 2008

VIN Range 1 : Begin : 000VT250DVE101107 End : 000VT250DVE101107 Not sequential

Vehicle 69 : 2013-2014 McLaughlin V500LEG

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.

The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 15, 2013 - JUN 24, 2014

VIN Range 1 : Begin : 00000V5S011513422 End : 00000V5S062414628 Not sequential

Vehicle 70 : 2007-2007 McLaughlin V500LT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.

The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 10, 2007 - JUN 10, 2007

VIN Range 1 : Begin : 0000005D060807866 End : 0000005D060807866 Not sequential

Description of Noncompliance :

Description of the Noncompliance : Missing tire placard.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

19-Feb-2021 – Investigation begins. Product Compliance and Product Safety identify need to research what information relating to tires and rims is available for affected vehicles and how that information is presented to end users. Discovered when Product Safety department at Vermeer Corporation took over responsibility for certain aspects of the issuance of Vermeer MV Solutions, Inc. MSOs.

9-Mar-2021 – Product Safety reported that tire size, tire pressure, and rim size are on the VIN plates since 2012.

8-Apr-2021 – Product Compliance met with Product Safety for a status update.

12-Apr-2021 - Product Compliance met with Legal to further discuss investigation.

14-Apr-2021 – Legal began investigation of possible noncompliance.

20-Apr-2021 – Legal determined a noncompliance existed.

Description of Remedy :

Description of Remedy Program : Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety. To be determined, pending the agency's disposition of the above-mentioned Part 556 petition for exemption.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported

Part 573 Safety Recall Report

21V-296

Manufacturer Name : Vermeer Manufacturing Company**Submission Date :** MAY 20, 2021**NHTSA Recall No. :** 21V-296**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Vermeer Manufacturing Company

Address : 1210 VERMEER ROAD EAST

PO BOX 200 PELLA IA 50219-0200

Company phone : 641-628-3141

Population :

Number of potentially involved : 1,308

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2021 Vermeer LPMINI

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 25, 2021 - FEB 25, 2021

VIN Range 1 : Begin : 7NWF16201MK010001 End : 7NWF16201MK010001 Not sequentialVIN Range 2 : Begin : 1MV4192MCMG010017 End : 1MV4192MTMG010018 Not sequential

Vehicle 2 : 2014-2021 Vac-Tron LPMINI

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110. The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2014 - OCT 07, 2020

VIN Range 1 : Begin : 5HZBF1623ELGE1283 End : 5HZF16209MK002011 Not sequential

Vehicle 3 : 2021-2021 Vermeer LPMINIXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2021 - FEB 10, 2021

VIN Range 1 : Begin : 7NWH16220MK010002 End : 7NWH16223MK010012 Not sequential

Vehicle 4 : 2019-2021 Vac-Tron LPSDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - NOV 17, 2020

VIN Range 1 : Begin : 5HZG1621XKK002013 End : 5HZG16213MK002423 Not sequential

Vehicle 5 : 2021-2021 Vermeer LPSDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 18, 2021 - APR 26, 2021

VIN Range 1 : Begin : 7NWG16219MK010020 End : 7NWG16219MK010101 Not sequential

Vehicle 6 : 2019-2020 Vac-Tron LPSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - JUL 02, 2020

VIN Range 1 : Begin : 5HZH16227KK002001 End : 5HZH16223LK002059 Not sequential

Vehicle 7 : 2021-2021 Vermeer LPSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 11, 2021 - MAR 09, 2021

VIN Range 1 : Begin : 7NWH16229MK010001 End : 7NWH16212MK010011 Not sequential

Vehicle 8 : 2019-2021 Vac-Tron LPXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 01, 2019 - DEC 05, 2020

VIN Range 1 : Begin : 5HZJ16232KK002014 End : 5HZH16223MK000104 Not sequential

Vehicle 9 : 2014-2020 Vac-Tron LPMINIXDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 01, 2014 - NOV 01, 2019

VIN Range 1 : Begin : 5HZBF1621FLME1100 End : 5HZBF1621FLME1100 Not sequential

VIN Range 2 : Begin : 5HZH1622XLK000101 End : 5HZH16223LK000103 Not sequential

Vehicle 10 : 2014-2021 Vac-Tron LPMINI

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2014 - OCT 07, 2020

VIN Range 1 : Begin : 5HZBF1623ELGE1283 End : 5HZF16209MK002011 Not sequential

Vehicle 11 : 2015-2019 Vac-Tron LP573XDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2015 - FEB 01, 2019

VIN Range 1 : Begin : 5HZBF1628FLLF1278 End : 5HZBF1621KLBK1146 Not sequential

Vehicle 12 : 2015-2015 Vac-Tron CS530GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2015 - MAY 01, 2015

VIN Range 1 : Begin : 5HZBF1623FLEF1209 End : 5HZBF1623FLEF1209 Not sequential

Vehicle 13 : 2013-2013 Vac-Tron CS555GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2013 - JAN 01, 2013

VIN Range 1 : Begin : 5HZBF1625DLAD1044 End : 5HZBF1625DLAD1044 Not sequential

Vehicle 14 : 2016-2018 Vac-Tron CS570GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2016 - FEB 24, 2018

VIN Range 1 : Begin : 5HZBF1621JLBJ1151 End : 5HZBF1621JLBJ1151 Not sequential

VIN Range 2 : Begin : 5HZBF1419GLEG3103 End : 5HZBF1419GLEG3103 Not sequential

Vehicle 15 : 2018-2018 Vac-Tron CS573GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 19, 2018 - MAY 25, 2018

VIN Range 1 : Begin : 5HZBF162XJLBJ1150 **End :** 5HZBF1628JLEJ1351 Not sequential

Vehicle 16 : 2017-2018 Vac-Tron CV570GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 07, 2017 - APR 11, 2018

VIN Range 1 : Begin : 5HZBF1626HLHH1319 **End :** 5HZBF1622JLDJ1228 Not sequential

Vehicle 17 : 2017-2018 Vac-Tron CV570SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 21, 2017 - MAR 08, 2018

VIN Range 1 : Begin : 5HZBF1623HLEH1219 **End :** 5HZBF1628JLCJ1196 Not sequential

Vehicle 18 : 2016-2018 Vac-Tron CV573GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2016 - DEC 18, 2018

VIN Range 1 : Begin : 5HZBF1624GLKG1272 End : 5HZBF1622KLMJ1554 Not sequential

Vehicle 19 : 2016-2019 Vac-Tron CV573SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2016 - JAN 07, 2019

VIN Range 1 : Begin : 5HZBF1628GLKG1274 End : 5HZBF1629KLAK1120 Not sequential

Vehicle 20 : 2019-2021 Vac-Tron CVGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - DEC 08, 2020

VIN Range 1 : Begin : 5HZC162XXKK002001 End : 5HZC162X4MK002174 Not sequential

Vehicle 21 : 2021-2021 Vermeer CVGT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 15, 2021 - APR 27, 2021

VIN Range 1 : Begin : 7NWC162X1MK010001 End : 7NWC162X9MK010022 Not sequential

Vehicle 22 : 2019-2021 Vac-Tron CVSGT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 01, 2019 - JAN 05, 2021

VIN Range 1 : Begin : 5HZD162Y7KK002003 End : 5HZD162Y4MK002270 Not sequential

Vehicle 23 : 2021-2021 Vermeer LPXDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : FEB 10, 2021 - FEB 10, 2021

VIN Range 1 : Begin : 7NWX1623XMK010017 End : 7NWX1623XMK010017 Not sequential

Vehicle 24 : 2021-2021 Vermeer CVSGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 07, 2021 - APR 19, 2021

VIN Range 1 : Begin : 7NWD162Y5MK010001 End : 7NWD162YXMK010043 Not sequential

Vehicle 25 : 2016-2016 Vac-Tron EV150DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2016 - APR 01, 2016

VIN Range 1 : Begin : 5HZBF1410GLDG3102 End : 5HZBF1410GLDG3102 Not sequential

Vehicle 26 : 2011-2019 Vac-Tron EV150GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2011 - FEB 01, 2019

VIN Range 1 : Begin : 5HZBF1215BLHB4100 End : 5HZBF141XKLAK3100 Not sequential

Vehicle 27 : 2019-2021 Vac-Tron EVGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 30, 2019 - NOV 30, 2020

VIN Range 1 : Begin : 5HZE141ZXKK002001 End : 5HZE141Z6MK002015 Not sequential

Vehicle 28 : 2006-2006 Vac-Tron FM150SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 01, 2006 - MAR 01, 2006

VIN Range 1 : Begin : 5HZBF12106LC64107 End : 5HZBF12106LC64107 Not sequential

Vehicle 29 : 2008-2008 Vac-Tron FM350SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2008 - MAY 01, 2008

VIN Range 1 : Begin : 5HZBF172X8LE87131 End : 5HZBF172X8LE87131 Not sequential

Vehicle 30 : 2011-2018 Vac-Tron JETTERTLR
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2011 - APR 30, 2018

VIN Range 1 : Begin : 5HZBF1629BLLB1625 End : 5HZBF1629BLLB1625 Not sequential

VIN Range 2 : Begin : 5HZBF1625JLDJ1269 End : 5HZBF1625JLDJ1269 Not sequential

Vehicle 31 : 2013-2017 Vac-Tron LP303GT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2013 - JAN 13, 2017

VIN Range 1 : Begin : 5HZBF1627DLHD1213 End : 5HZBF1622HLAH1118 Not sequential

Vehicle 32 : 2016-2016 Vac-Tron LP303XDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2016 - NOV 01, 2016

VIN Range 1 : Begin : 5HZBF1629GLLG1285 End : 5HZBF1629GLLG1285 Not sequential

Vehicle 33 : 2011-2013 Vac-Tron LP305DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 01, 2011 - MAY 01, 2013

VIN Range 1 : Begin : 5HZBF16241LC11373 End : 5HZBF1629DLED1169 Not sequential

Vehicle 34 : 2012-2012 Vac-Tron LP305GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2012 - OCT 01, 2012

VIN Range 1 : Begin : 5HZBF162XCLHC1306 End : 5HZBF1625CLKC1325 Not sequential

Vehicle 35 : 2014-2014 Vac-Tron LP333DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2014 - APR 01, 2014

VIN Range 1 : Begin : 5HZBF1627ELAE1124 End : 5HZBF1627ELAE1124 Not sequential

VIN Range 2 : Begin : 5HZBF1628ELDE1223 End : 5HZBF1628ELDE1223 Not sequential

VIN Range 3 : Begin : 5HZBF1628ELDE1223 End : 5HZBF1628ELDE1223 Not sequential

Vehicle 36 : 2014-2015 Vac-Tron LP333GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2014 - MAY 01, 2015

VIN Range 1 : Begin : 5HZBF1627ELAE1155 End : 5HZBF1627ELAE1155 Not sequential

VIN Range 2 : Begin : 5HZBF1629FLEF1201 End : 5HZBF1629FLEF1201 Not sequential

Vehicle 37 : 2011-2012 Vac-Tron LP355DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2011 - MAR 01, 2012

VIN Range 1 : Begin : 5HZBF1628BLHB1503 End : 5HZBF1620CLCC1204 Not sequential

Vehicle 38 : 2013-2013 Vac-Tron LP355GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 01, 2013 - MAY 01, 2013

VIN Range 1 : Begin : 5HZBF1622DLED1143 End : 5HZBF1622DLED1143 Not sequential

Vehicle 39 : 2018-2018 Vac-Tron LP370XDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAR 21, 2018 - MAR 21, 2018

VIN Range 1 : Begin : 5HZBF1625JLCJ1222 End : 5HZBF1625JLCJ1222 Not sequential

Vehicle 40 : 2015-2019 Vac-Tron LP373GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 01, 2015 - JAN 01, 2019

VIN Range 1 : Begin : 5HZBF1625FLMF1287 End : 5HZBF1626KLAK1110 Not sequential

Vehicle 41 : 2016-2018 Vac-Tron LP373SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 01, 2016 - JUN 05, 2018

VIN Range 1 : Begin : 5HZBF1624GLMG1293 End : 5HZBF1624GLMG1293 Not sequential

VIN Range 2 : Begin : 5HZBF1621JLFJ1369 End : 5HZBF1621JLFJ1369 Not sequential

Vehicle 42 : 2017-2017 Vac-Tron AIR373SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 10, 2017 - JUL 10, 2017

VIN Range 1 : Begin : 5HZBF1626HLGH1284 End : 5HZBF1626HLGH1284 Not sequential

Vehicle 43 : 2017-2018 Vac-Tron LP373XDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 07, 2017 - MAR 26, 2018

VIN Range 1 : Begin : 5HZBF1627HLEH1207 End : 5HZBF1627JLCJ1223 Not sequential

Vehicle 44 : 2013-2013 Vac-Tron LP500DT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2013 - APR 01, 2013

VIN Range 1 : Begin : 5HZBF162XDLDD1114 End : 5HZBF162XDLDD1114 Not sequential

Vehicle 45 : 2011-2011 Vac-Tron LP500GT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2011 - NOV 01, 2011

VIN Range 1 : Begin : 5HZBF1628BLLB1616 End : 5HZBF1628BLLB1616 Not sequential

Vehicle 46 : 2013-2017 Vac-Tron LP533SDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2013 - APR 11, 2017

VIN Range 1 : Begin : 5HZBF1621DLAD1042 End : 5HZBF1628HLDH1200 Not sequential

Vehicle 47 : 2015-2015 Vac-Tron LP533SGT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : OCT 01, 2015 - OCT 01, 2015

VIN Range 1 : Begin : 5HZBF1628FLKF1259 End : 5HZBF1628FLKF1259 Not sequential

Vehicle 48 : 2011-2012 Vac-Tron AIR555SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2011 - FEB 01, 2012

VIN Range 1 : Begin : 5HZBF16251LD11384 End : 5HZBF1627CLBC1181 Not sequential

Vehicle 49 : 2016-2018 Vac-Tron AIR573SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2016 - MAR 25, 2018

VIN Range 1 : Begin : 5HZBF1623GLGG1214 End : 5HZBF1626JLCJ1214 Not sequential

Vehicle 50 : 2019-2019 Vac-Tron AIRSDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 17, 2019 - JUN 17, 2019

VIN Range 1 : Begin : 5HZA162V8KK002018 End : 5HZA162V8KK002018 Not sequential

Vehicle 51 : 2012-2012 Vac-Tron CS350GT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : SEP 01, 2012 - SEP 01, 2012

VIN Range 1 : Begin : 5HZBF1622CLJC1313 End : 5HZBF1622CLJC1313 Not sequential

Vehicle 52 : 2021-2021 Vermeer CS418B
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 08, 2021 - APR 28, 2021

VIN Range 1 : Begin : 7NWF131ZXMG010001 End : 7NWF131Z0MG010010 Not sequential

Vehicle 53 : 2012-2016 Vac-Tron CS500DT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 01, 2012 - APR 01, 2016

VIN Range 1 : Begin : 5HZBF1628CLAC1154 End : 5HZBF1624GLDG1147 Not sequential

Vehicle 54 : 2011-2015 Vac-Tron CS500GT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2011 - FEB 01, 2015

VIN Range 1 : Begin : 5HZBF16231LG11490 End : 5HZBF1625FLBF1154 Not sequential

Vehicle 55 : 2012-2012 Vac-Tron LP550SDT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 01, 2012 - JUL 01, 2012

VIN Range 1 : Begin : 5HZBF1628CLGC1298 End : 5HZBF1628CLGC1298 Not sequential

Vehicle 56 : 2011-2013 Vac-Tron LP555DT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : AUG 01, 2011 - FEB 01, 2013

VIN Range 1 : Begin : 5HZBF1625BLHB1555 End : 5HZBF1622DLBD1067 Not sequential

Vehicle 57 : 2009-2013 Vac-Tron LP555SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : NOV 01, 2009 - JAN 01, 2013

VIN Range 1 : Begin : 5HZBF16279LL91358 End : 5HZBF1625DLAD1027 Not sequential

Vehicle 58 : 2016-2016 Vac-Tron LP573GT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : APR 01, 2016 - APR 01, 2016

VIN Range 1 : Begin : 5HZBF1621GLDG1154 End : 5HZBF1621GLDG1154 Not sequential

Vehicle 59 : 2015-2019 Vac-Tron LP573SDT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 04, 2015 - JAN 01, 2019

VIN Range 1 : Begin : 5HZBF1627FLMF1288 End : 5HZBF1629KLAK1568 Not sequential

Vehicle 60 : 2015-2018 Vac-Tron LP573SGT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 01, 2015 - JUN 27, 2018

VIN Range 1 : Begin : 5HZBF1629FLMF1289 End : 5HZBF1629JLFJ1376 Not sequential

Vehicle 61 : 2016-2021 McLaughlin CS418B

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 12, 2016 - NOV 17, 2020

VIN Range 1 : Begin : 000000CS041416006 End : 000000CS041416006 Not sequential

VIN Range 2 : Begin : 7HWF131Z9KG005006 End : 7HWF131Z4MG005031 Not sequential

Vehicle 62 : 2015-2019 McLaughlin V25G

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : MAY 27, 2015 - MAY 07, 2018

VIN Range 1 : Begin : 0000V5S0527151304 End : 0000V5S0830172722 Not sequential

VIN Range 2 : Begin : 7HW6162PXKG005014 End : 7HW6162PXKG005014 Not sequential

Vehicle 63 : 2014-2020 McLaughlin VX30
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUL 23, 2014 - JAN 17, 2020

VIN Range 1 : Begin : 0000V5S072314669 End : 0000V5S0220183018 Not sequential
VIN Range 2 : Begin : 7HWY192FXJG005028 End : 7HWY192F4LG005108 Not sequential

Vehicle 64 : 2014-2019 McLaughlin VX30G
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : SEP 17, 2014 - JUN 03, 2019

VIN Range 1 : Begin : 0000VX5S091714788 End : 0000V5S0222183021 Not sequential
VIN Range 2 : Begin : 7HW1152J7JG005003 End : 7HW1152J7KG005052 Not sequential

Vehicle 65 : 2014-2021 McLaughlin VX50
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 20, 2014 - FEB 04, 2021

VIN Range 1 : Begin : 00000VX5062014615 End : 0000V5H0922172780 Not sequential
VIN Range 2 : Begin : 7HW4192M0KG005019 End : 7HW4192MVMG005655 Not sequential

Vehicle 66 : 2008-2008 McLaughlin V250

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 02, 2008 - JAN 02, 2008

VIN Range 1 : Begin : 000VT250DVE101107 End : 000VT250DVE101107 Not sequential

Vehicle 67 : 2013-2014 McLaughlin V500LEG

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JAN 15, 2013 - JUN 24, 2014

VIN Range 1 : Begin : 00000V5S011513422 End : 00000V5S062414628 Not sequential

Vehicle 68 : 2012-2014 McLaughlin V500LELT

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 10, 2012 - JAN 08, 2014

VIN Range 1 : Begin : 00000V5S121012348 End : 00000V5S010814312 Not sequential

Vehicle 69 : 2012-2014 McLaughlin V500LELTHD
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : DEC 06, 2012 - MAR 05, 2014

VIN Range 1 : Begin : 00000V5H120112328 **End :** 00000V5H030514405 Not sequential

Vehicle 70 : 2007-2007 McLaughlin V500LT
Vehicle Type : TRAILERS
Body Style :
Power Train : NR

Descriptive Information : Using various manufacturing documents and drawings for the models identified above, research identified noncompliance to 49 CFR 571.110.
The machines are not compliant due to a missing tire placard, required pursuant to S4.3.5. Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Production Dates : JUN 10, 2007 - JUN 10, 2007

VIN Range 1 : Begin : 0000005D060807866 **End :** 0000005D060807866 Not sequential

Description of Noncompliance :

Description of the Noncompliance : Missing tire placard.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

19-Feb-2021 – Investigation begins. Product Compliance and Product Safety identify need to research what information relating to tires and rims is available for affected vehicles and how that information is presented to end users. Discovered when Product Safety department at Vermeer Corporation took over responsibility for certain aspects of the issuance of Vermeer MV Solutions, Inc. MSOs.

9-Mar-2021 – Product Safety reported that tire size, tire pressure, and rim size are on the VIN plates since 2012.

8-Apr-2021 – Product Compliance met with Product Safety for a status update.

12-Apr-2021 - Product Compliance met with Legal to further discuss investigation.

14-Apr-2021 – Legal began investigation of possible noncompliance.

20-Apr-2021 – Legal determined a noncompliance existed.

Description of Remedy :

Description of Remedy Program : Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Vermeer MV Solutions, Inc. intends to petition the agency pursuant to 49 CFR 556 for exemption from the notice and remedy provisions of the Safety Act on the grounds this noncompliance is inconsequential as it relates to motor vehicle safety. To be determined, pending the agency's disposition of the above-mentioned Part 556 petition for exemption.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported