OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-750

Manufacturer Name: Forest River, Inc.
Submission Date: OCT 07, 2022
NHTSA Recall No.: 22V-750
Manufacturer Recall No.: 50-1566



Manufacturer Information:

Population:

Manufacturer Name: Forest River, Inc.

Number of potentially involved: 25

Address: 55470 CR 1

Estimated percentage with defect : $100\,\%$

P.O. Box 3030 Elkhart IN 46515-3030

Company phone: 1-800-348-7440

Vehicle Information:

Vehicle 1: 2023-2023 Forest River Inc. Prime Time Avenger AVT32BHSTravel Trailers

Vehicle Type : TRAILERS
Body Style : OTHER
Power Train : NR

Descriptive Information: Since inception of the AVT32BHS to October 5, 2022, is how Forest River identified

the scope of vehicles.

2023 AVENGER AVT32BHS 25

Production Dates: AUG 24, 2022 - OCT 04, 2022

Description of Defect:

Description of the Defect: The rear bunkrooms' flip-up bunks supporting angle brackets may not have

been installed completely into backers in the walls.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the bunk angle support bracket fails to support the bunk, the bunk may fail,

allowing a user to fall from the bunk which may potentially lead to personal

injury.

Description of the Cause: The angle bracket that supports the bunk in the "use" position may not have

been securely installed into a backer in the wall.

Identification of Any Warning None

that can Occur:

Involved Components:

Component Name 1: Bunk Angle Support Bracket

Component Description: Bunk Angle Support Bracket

Component Part Number: N/A

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

On October 5, 2022, during a routine PDI/Corporate Standards inspection it was found that the angle brackets for the bunk ladder may not be installed completely into the backers in the wall. On that same day, the manufacturing plant addressed all of the AVT32BHS in their possession.

On October 6, 2022, Forest Rivers Office of Corporate Compliance was able to identify all vehicles involved.

On October 7, 2022, Forest Rivers Corporate Recall Committee voted to recall

Description of Remedy:

Description of Remedy Program: Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River Dealer or Service Center will need to perform the remedy to install the brackets into the backers in the wall.

What is the Forest River Customer Service Phone Number? (574)

862-1025

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:

Prime Time Avenger Forest River, Inc.

Attn: WARRANTY MANAGER

200 SR 19

Wakarusa, IN 46573

How Remedy Component Differs Component Name - Bunk Angle Support Bracket

from Recalled Component: Part Number - N/A

The Bunk Angle Support Bracket will now be installed into the backer to

provide proper support to the ladder.

Identify How/When Recall Condition On October 5, 2022, the manufacturing plant inspected and remedied all of was Corrected in Production: the AVT32BHS in their possession to ensure the angle brackets were

installed into the backer.

Recall Schedule:

Description of Recall Schedule: Forest River has the utmost urgency in our recalls. Forest River will send

suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement

Letter.

Planned Dealer Notification Date: NOV 16, 2022 - NOV 16, 2022 Planned Owner Notification Date: NOV 16, 2022 - NOV 16, 2022

^{*} NR - Not Reported