

Part 573 Safety Recall Report

22V-889

Manufacturer Name : Chinook Motor Coach, LLC**Submission Date :** DEC 01, 2022**NHTSA Recall No. :** 22V-889**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Chinook Motor Coach, LLC

Number of potentially involved : 10

Address : 1482 North Eel River Cemetery Road
Peru IN 46970

Estimated percentage with defect : 10 %

Company phone : 584-3756

Vehicle Information :

Vehicle 1 : 2020-2022 Chinook Bayside

Vehicle Type : LOW VOLUME VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : On June 29, 2022, our supplier Manchester Tank notified us of a safety defect in a small number of RegO service valves on recreational vehicle LP tanks we purchased. They provided us with our purchase history of total number of affected LP tanks, which is 10 total and indicated a 10% factor of possible valves that might have been on those tanks..

Production Dates : JUN 21, 2021 - JAN 11, 2022

VIN Range 1 : Begin : 1FDRU4XG2JKB25959 End : 1FTRS4UG9LKB78983 ☒ Not sequential**Description of Defect :**

Description of the Defect : The installed LP tank may contain a RegO service valve which have some short threads in the POL outlets.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The short threads do not allow the POL connector to fully seat. This may result in a leak at the connection.

Description of the Cause : NR

Identification of Any Warning : The warning of a leak could include the smell of LP, from the leak of gas at the that can Occur : service valve.

Involved Components :

Component Name 1 : RegO Model 901 Service Valve

Component Description : LP Tank Service Valve

Component Part Number : Model 901C3 and Model 901C5

Supplier Identification :

Component Manufacturer

Name : Manchester Tank

Address : 1000 Corporate Drive
Suite 300 Franklin Tennessee 37067

Country : United States

Chronology :

On June 29, 2022 Chinook received a letter from Frank Lane, VP Product Safety, Manchester Tank outlining this safety defect in their RegO valves that Chinook purchased as described in this information.

Description of Remedy :

Description of Remedy Program : Chinook will notify the owners of the 10 Bayside van motorhomes with the potentially affected LP Tanks. Chinook will have the owners make contact for instruction and help with resolving the issue.

How Remedy Component Differs from Recalled Component : The threads in the POL outlets of the RegO service valves on Manchester LP Tanks have short threads which may result in a leak at the connection. There is a safety bulletin issued by RegQ and Manchester Tank Co. which describes the issue in great detail.

Identify How/When Recall Condition was Corrected in Production : Chinook only purchased 10 of the identified LP tanks and there are no more.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : DEC 07, 2022 - NR

Planned Owner Notification Date : DEC 07, 2022 - NR

* NR - Not Reported