#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 23V-359

Manufacturer Name: Forest River, Inc.
Submission Date: MAY 19, 2023
NHTSA Recall No.: 23V-359
Manufacturer Recall No.: 69-1642



#### **Manufacturer Information:**

Population:

Manufacturer Name: Forest River, Inc.

Number of potentially involved: 6

Address: 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone: 1-800-348-7440

#### **Vehicle Information:**

Vehicle 1: 2023-2023 Forest River Inc. Salem Travel Trailers

Vehicle Type: TRAILERS
Body Style: OTHER
Power Train: NR

Descriptive Information: Using manufacturing records, including employment records, the manufacturing

plant was able to determine the scope.

2023 SALEM

SBF356QB 1 SBF369BL 3 SBF36FL 1 Grand Total - 5

Production Dates: MAY 08, 2023 - MAY 11, 2023

Vehicle 2: 2023-2023 Forest River Inc. Wildwood Travel Trailers

Vehicle Type: TRAILERS Body Style: OTHER Power Train: NR

Descriptive Information: Using manufacturing records, including employment records, the manufacturing

plant was able to determine the scope.

2023

WILDWOOD WBF356QB 1

Production Dates: MAY 08, 2023 - MAY 11, 2023

VIN Range 1 : Begin : NR End : NR Not sequential

### **Description of Defect:**

Description of the Defect: The manufacturing plant may have failed to apply thread sealant on the brass

90° fitting that is used to connect to the furnaces' LPG steel pipe.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Without thread sealant, LP may leak. This condition may lead to a fire causing

personal injury.

Description of the Cause: Manufacturing error.

Identification of Any Warning An operator(s) may notice the smell of LP Gas and/or the LP Gas alarm may

that can Occur: alert the operator(s).

### **Involved Components:**

Component Name 1: Thread Sealant Component Description: Thread Sealant

Component Part Number: N/A

# **Supplier Identification:**

#### **Component Manufacturer**

Name: NR

Address: NR

NR

Country: NR

#### **Chronology:**

On May 12, 2023, during a routine Corporate Standards Inspection, it was found that the manufacturing plant failed to apply thread sealant on the brass 90° fitting that is used to connect to the furnaces' LPG steel pipe.

On May 16, 2023, Forest Rivers Office of Corporate Compliance ("OCC") was notified and opened a research item into the concern.

On May 19, 2023, Forest Rivers Corporate Recall Committee voted to recall.

All vehicles are located on Dealer premises, and none are retail sold. No Owner letter will be issued.

# **Description of Remedy:**

Description of Remedy Program: Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to inspect the brass 90° elbow that connects the rubber LPG gas line to the furnace. If it does not have any thread sealant on the furnace side apply thread sealant to the side of the 90° fitting that goes into the steel tube on the furnace.

> What is the Forest River Customer Service Phone Number? (574) 534-3167

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Salem/Wildwood Forest River. Inc.

Attn: WARRANTY MANAGER

1803 Century Dr. Goshen, IN 46528

How Remedy Component Differs Thread Sealant from Recalled Component: N/A

The fitting will now be sealed properly with thread sealant.

Please send the service invoice to the following address:

was Corrected in Production:

Identify How/When Recall Condition The condition was remedied in the plant the week of May 15, 2023.

#### **Recall Schedule:**

Description of Recall Schedule: Forest River has the utmost urgency in our recalls. Forest River will send

suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement

Letter.

Planned Dealer Notification Date: JUN 28, 2023 - JUN 28, 2023 Planned Owner Notification Date: JUN 28, 2023 - JUN 28, 2023

Part 573 Safety Recall Report	23V-359	Page 4
* NR - Not Reported		
The information contained in this report was submitted		