OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-497

Manufacturer Name: Vanguard National Trailer Corporation

Submission Date: JUL 19, 2023 NHTSA Recall No.: 23V-497 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Vanguard National Trailer Corporation

Address: 289 E. Water Tower Drive

Monon IN 47959

Company phone: 2532000

Population:

Number of potentially involved: 15

Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2023-2024 Vanguard All

Vehicle Type: TRAILERS Body Style: VAN Power Train: NR

Descriptive Information: Units have SAF Holland Tire Pilot Plus tire inflation system installed. This is for new

eletronic controller systems installed on certain customers trailer by order

Production Dates: NOV 30, 2022 - JUN 01, 2023

Description of Defect:

Description of the Defect: Tire Pilot Plus (TPP) system produced on trailers after November 2022 with

the electronic regulator assembly have been determined under specific

conditions to slowly deflate the trailer tires.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: All Tires can deflate while in service/operation

Description of the Cause: Electronic Controller can open the check valves in the tire inflation hoses

causing the tires to lose air pressure and deflate.

Identification of Any Warning No warning notice has been provided by SAF Holland in their field bulletin..

that can Occur:

Involved	Components	:
mvorveu	components	•

Component Name 1: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR NR

Country: NR

Chronology:

NR

Description of Remedy:

Description of Remedy Program: NR
How Remedy Component Differs NR
from Recalled Component:

Identify How/When Recall Condition NR
was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

^{*} NR - Not Reported