

Part 573 Safety Recall Report

24V-317

Manufacturer Name : Coach and Equipment Mfg. Corp.

Submission Date : MAY 10, 2024

NHTSA Recall No. : 24V-317

Manufacturer Recall No. : NR



Manufacturer Information :

Population :

Manufacturer Name : Coach and Equipment Mfg. Corp.

Number of potentially involved : 12

Address : 130 Horizon Park Drive

Estimated percentage with defect : 15 %

Penn Yan NY 14527

Company phone : 1-800-724-8464

Vehicle Information :

Vehicle 1 : 2024-2024 Coach and Equipment Phoenix

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : The recall population was determined from information from the Freedman Seating Company equipment recall 24E026. The recalled buses are installed with Freedman GO-ES Spacesaver Foldaway seats that were built during a certain time frame. This recall affects 12 2024 Coach and Equipment Phoenix model buses.

Production Dates : JAN 11, 2024 - JAN 24, 2024

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : The seat back cushion may become disengaged from the dump mechanism when there is a high load applied to the shoulder portion of the seat belt.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This defect may increase the risk of occupant injury in the event of a vehicle collision or crash.

Description of the Cause : The stop bracket may not be dimensionally correct.

Identification of Any Warning that can Occur : The seat back cushion may start to become disengaged

Involved Components :

Component Name 1 : Freedman GO-ES Spacesaver Foldaway Seat

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Freedman Seating Company

Address : 4545 W Agusta Blvd
Chicago Illinois 60465

Country : United States

Chronology :

Freedman Seating Company equipment Recall 24E026 was received 4/29/2024. There were no warranty claims, field or service report associated with the Freedman recall 24E026.

Description of Remedy :

Description of Remedy Program : The owners/dealers of the recalled vehicles are being sent a link to a Freedman Seating Recall site. The site has an inspection / repair instruction and video. Once the inspections and needed repairs are completed, the owners/dealers are to complete an on-line form for reimbursement of 15 minutes per seat for any seats requiring repair. Coach and Equipment incorporation with the Freedman Seating Company will reimburse any repair costs incurred to remedy the problem addressed in this recall within a reasonable time frame in advance of the notification of the owners and dealers.

How Remedy Component Differs from Recalled Component : The seat back cushions will not come disengaged from the dump mechanism when a high load is applied to the shoulder portion of the seat belt.

Identify How/When Recall Condition was Corrected in Production : The GO-ES Spacesaver Foldaway Seat issue was corrected on 2-1-2024 in production by Freedman Seating..

Recall Schedule :

Description of Recall Schedule : The quarterly reporting will be completed by the Freedman Seating

Company since they are collecting the needed information on their on - line form.

Planned Dealer Notification Date : MAY 13, 2024 - MAY 15, 2024

Planned Owner Notification Date : MAY 13, 2024 - MAY 15, 2024

* NR - Not Reported