The information contained in this report was submitted pursuant to 49 CFR §573

| OMB Control No.: | 2127-0004 |
|------------------|-----------|
| | |

Population :

Part 573 Safety Recall Report

Manufacturer Name :Carparts.com, Inc.Submission Date :JUL 03, 2024NHTSA Recall No. :24E-057Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : Carparts.com, Inc. Address : 2050 W. 190th Street Suite 4000 Torrance CA 90504 Company phone : 866-529-0412

Equipment Information :

| Brand / Trade 1: | МН |
|---------------------------|---|
| Model : | MHD730145 |
| Part No. : | MHD730145 |
| Size : | NR |
| Function : | Tail lamp |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| | |
| | |
| Brand / Trade 2: | МН |
| Model : | MHD730146 |
| Part No. : | MHD730146 |
| Size : | NR |
| Function : | Tail lamp |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| | |



Number of potentially involved : 1,826 Estimated percentage with defect : 100 %

24E-057

| Brand / Trade 3: | |
|---------------------------|---|
| | MHG730125 |
| Size : | MHG730125 |
| Function : | |
| | Third-party laboratory testing revealed that certain automotive lighting products |
| Descriptive mormation . | imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| Brand / Trade 4: | MH |
| Model : | MHG730126 |
| Part No. : | MHG730126 |
| Size : | NR |
| Function : | Tail lamp |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| Brand / Trade 5 : | MH |
| Model : | MHH730117 |
| | MHH730117 |
| Size : | |
| Function : | - |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| | |

The information contained in this report was submitted pursuant to 49 CFR \$573

| Brand / Trade 6: | |
|---------------------------|---|
| | MHH730118 |
| | MHH730118 |
| Size : | |
| Function : | * |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| Brand / Trade 7 : | MH |
| Model : | MHJ730143 |
| Part No. : | MHJ730143 |
| Size : | NR |
| Function : | Tail lamp |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| Brand / Trade 8: | MH |
| Model : | MHJ730144 |
| Part No. : | MHJ730144 |
| Size : | |
| Function : | Tail lamp |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| | |

The information contained in this report was submitted pursuant to 49 CFR \$573

| Brand / Trade 9: | |
|---------------------------|---|
| | MHK100169 |
| | MHK100169 |
| Size : | |
| Function : | Head lamp |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| Brand / Trade 10: | МН |
| Model : | MHK100170 |
| Part No. : | MHK100170 |
| Size : | NR |
| Function : | Head lamp |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| Brand / Trade 11: | МН |
| Model : | MHN100189 |
| Part No. : | MHN100189 |
| Size : | |
| Function : | Head lamp |
| Descriptive Information : | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| | |
| | |
| | |

The information contained in this report was submitted pursuant to 49 CFR §573

| Brand / Trade 12 : 1 | |
|---|---|
| | MHN100190 |
| Size : 1 | MHN100190 |
| Function : 1 | |
| | - |
| i | Third-party laboratory testing revealed that certain automotive lighting products imported by CarParts.com from its vendor, Shanghai Rego Import & Export, may not meet all the minimum requirements under FMVSS 108. |
| Production Dates : | JAN 01, 2024 - FEB 14, 2024 |
| Description of Noncomplianc | :e: |
| | The products may not meet all the minimum performance requirements for lighting under FMVSS 108. Preliminary testing results indicate that the lights |
| EMUCC 1. | at least do not meet all photometry requirements. |
| FMVSS 1 : FMVSS 2 : | 108 - Lamps, reflective devices, and assoc. Equipment |
| | The products may not meet all the minimum performance requirements for lighting under FMVSS 108, which can increase the risk of a crash. |
| Description of the Cause : | The products' fabricating manufacturer has not provided this information to CarParts.com, which is the products' importer of record. |
| Identification of Any Warning that can Occur : | NR |
| involved Components : | |
| Component Name : | NR |
| Component Description : | NR |
| Component Part Number : | NR |
| Supplier Identification : | |
| Component Manufacturer | |
| - | nort 9 Fynort |
| Name : Shanghai Rego Im Address : 8 The Green | port & Export |
| | |

24E-057

5243 Dover Delaware 19901 Country : United States

Chronology :

In or about May 2024, CarParts.com received anonymous reports that certain automotive lighting products supplied by one of its vendors, Shanghai Rego Import & Export, do not comply with FMVSS 108. Upon receiving the first report on or about May 2, 2024, CarParts.com stopped offering the products for sale. CarParts.com also promptly initiated an investigation, including by requesting from Shanghai Rego Import & Export, a certificate of FMVSS compliance, and testing to demonstrate the products' compliance with FMVSS 108, and engaging a third-party laboratory to evaluate the products' compliance with FMVSS 108. On or about May 15, 2024, Shanghai Rego Import & Export provided CarParts.com a "Vendor Certificate of Compliance." which certified that the products met all applicable FMVSS 108 requirements. Shanghai Rego Import & Export provided CarParts.com with testing reports for eight products on or about May 15, 2024, which purported to demonstrate that the products "met the requirements" for certain durability testing. As these reports did not reflect full FMVSS 108 testing requirements, CarParts.com requested additional test reports. On or about June 14, 2024, Shanghai Rego Import & Export provided CarParts.com with four additional test reports (two of which covered the same model numbers), which again purported to demonstrate FMVSS 108 compliance, but did not reflect testing on all required performance metrics of FMVSS 108. Concurrently, CarParts.com engaged a third-party laboratory to perform FMVSS testing on a sample of Shanghai Rego's products. On or about June 24, 2024, the results of that testing demonstrated that the products were not compliant with FMVSS 108.

Description of Remedy :

| Description of Remedy Program : | CarParts.com will offer a refund to purchasers of the recalled products, and will reimburse customers in accordance with CarParts.com's reimbursement plan. |
|---|---|
| How Remedy Component Differs from Recalled Component : | |
| Identify How/When Recall Condition was Corrected in Production : | CarParts.com will not import further products supplied by Shanghai Rego Import & Export. |

Recall Schedule :

| Description of Recall Schedule : | CarParts.com will notify all known purchasers of the recall directly. |
|------------------------------------|---|
| Planned Dealer Notification Date : | JUL 22, 2024 - JUL 22, 2024 |
| Planned Owner Notification Date : | JUL 22, 2024 ⁻ JUL 22, 2024 |

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR Address : NR NR Country : NR Company Phone : NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573