

# Part 573 Safety Recall Report

# 24V-500

**Manufacturer Name :** ARBOC Specialty Vehicles, LLC**Submission Date :** JUL 02, 2024**NHTSA Recall No. :** 24V-500**Manufacturer Recall No. :** NA**Manufacturer Information :**

Manufacturer Name : ARBOC Specialty Vehicles, LLC

Address : 51165 Greenfield Parkway

Middlebury IN 46540

Company phone : 574-825-1720

**Population :**

Number of potentially involved : NR

Estimated percentage with defect : NR

**Vehicle Information :**

Vehicle 1 : 2023-2024 ARBOC SOF, SOI-P, SOM

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

**Descriptive Information :** Our vendor, Freedman Seating Company, notified us of their new Recall 24E026. As instructed, we are filing to report this Recall. They are handling all instructions and reimbursement.

Production Dates : DEC 11, 2023 - FEB 01, 2024

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** Provided from our vendor: Freedman Seating Company (FSC) has decided that a defect which relates to motor vehicle safety exists in certain GO-ES Spacesaver Foldaway Seats manufactured between December 11, 2023 and January 31, 2024. The seat back cushion may become disengaged from the dump mechanism when there is a high load applied to the shoulder portion of the seat belt.

FMVSS 1 : 207 - Seating systems

FMVSS 2 : NR

**Description of the Safety Risk :** Provided from vendor: The seat back cushion may become disengaged from the dump mechanism when there is a high load applied to the shoulder portion of the seat belt.

**Description of the Cause :** Provided from vendor: The seat back cushion may become disengaged from the dump mechanism when there is a high load applied to the shoulder portion of the seat belt.

**Identification of Any Warning that can Occur :** None provided.

**Involved Components :**

Component Name 1 : SEAT, GO ES BV DOUBLE FOLDAWAY STREETSIDE

Component Description : SEAT, GO ES BV DOUBLE FOLDAWAY STREETSIDE W/ 3PT HARNESS (NO grab rails) SPACE SAVER

Component Part Number : 88335

Component Name 2 : SEAT, GO ES BV DOUBLE FOLDAWAY CURBSIDE

Component Description : SEAT, GO ES BV DOUBLE FOLDAWAY CURBSIDE W/ 3PT HARNESS (NO grab rails) SPACE SAVER

Component Part Number : 89316

**Supplier Identification :****Component Manufacturer**

Name : Freedman Seating Company

Address : 4545 W Augusta Blvd

Chicago Illinois 60465

Country : United States

**Chronology :**

5/28/24 We received the letter notifying us about Recall 24E026.

**Description of Remedy :**

Description of Remedy Program : Dealers/Customers are to contact Freedman Seating Company.

How Remedy Component Differs from Recalled Component : Unknown. Freedman Seating Company should be contacted for direction.

Identify How/When Recall Condition was Corrected in Production : There are no buses in production at ARBOC SV that require this Recall to be completed.

**Recall Schedule :**

Description of Recall Schedule : Will mail notifications upon approval from NHTSA.

Planned Dealer Notification Date : JUL 08, 2024 - JUL 12, 2024

Planned Owner Notification Date : JUL 08, 2024 - JUL 12, 2024

\* NR - Not Reported