

Part 573 Safety Recall Report

24V-544

Manufacturer Name : Doosan Portable Power

Submission Date : JUL 19, 2024

NHTSA Recall No. : 24V-544

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Doosan Portable Power

Address : 1293 GLENWAY DRIVE
STATESVILLE NC 28625

Company phone : 8833500

Population :

Number of potentially involved : 24

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2024-2024 Bobcat PG25

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The wheel lug nut torque on the selected serial number range of portable generator model PG25 may not meet engineering specifications. Wheel lug nuts (p/n 35315274) that are not to the proper torque specification may cause vibration, tire wobble, or the wheel(s) could come off during towing, resulting in a crash

Production Dates : JAN 31, 2024 - MAY 31, 2024

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : The wheel lug nut torque on the selected serial number range of portable generator model PG25 may not meet engineering specifications. Wheel lug nuts (p/n 35315274) that are not to the proper torque specification may cause vibration, tire wobble, or the wheel(s) could come off during towing, resulting in a crash

FMVSS 1 : 120 - Wheels and rims- other than passenger cars

FMVSS 2 : NR

Description of the Safety Risk : The wheel lug nut torque on the selected serial number range of portable generator model PG25 may not meet engineering specifications. Wheel lug nuts (p/n 35315274) that are not to the proper torque specification may cause vibration, tire wobble, or the wheel(s) could come off during towing, resulting in a crash

Description of the Cause : NR

Identification of Any Warning that can Occur : vibration, tire wobble

Involved Components :

Component Name 1 : Wheel nut

Component Description : Wheel nut

Component Part Number : 35315274

Supplier Identification :**Component Manufacturer**

Name : Doosan Bobcat North America, Inc.

Address : 1293 GLENWAY DRIVE
STATESVILLE North Carolina 28625

Country : United States

Chronology :

Received report from field on 7/12/2024 that PG25 model generator had loose wheel nuts. We began investigation on 7/12/2024 to investigate issue. Units at the factory were inspected and loose wheel nuts were found. The root cause was investigated and found to be related to move of frame assembly station in January 2024. A report of the affected shipped population was created and report filed with NHTSA

Description of Remedy :

Description of Remedy Program : Issue bulletin to immediately stop towing the trailer and provide instructions to remedy the issue at no charge to the customer

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported