

Part 573 Safety Recall Report

24V-618

Manufacturer Name : Winnebago Towable

Submission Date : AUG 16, 2024

NHTSA Recall No. : 24V-618

Manufacturer Recall No. : CAM0000038



Manufacturer Information :

Manufacturer Name : Winnebago Towable

Address : 201 14th Street
Middlebury IN 46540

Company phone : 825-5250

Population :

Number of potentially involved : 1,201

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2024 Winnebago Minnie

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by print specifications and production records.

Production Dates : JAN 08, 2020 - NOV 06, 2023

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 2 : 2024-2025 Winnebago Access

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by print specifications and production records.

Production Dates : SEP 19, 2023 - JUN 20, 2024

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 3 : 2021-2025 Winnebago Voyage

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by print specifications and production records.

Production Dates : JAN 08, 2020 - MAY 29, 2024

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Description of Defect :

Description of the Defect :	On certain 2024-2025 Access, 2021-2025 Voyage, and 2021-2024 Minnie models there is a non-GFCI protected outlet installed within 6 feet of the sink that serves a countertop surface.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Under certain conditions, lack of proper circuit protection can increase the risk of electrical shock or injury.
Description of the Cause :	Print specifications did not correctly identify the outlet should be GFCI.
Identification of Any Warning that can Occur :	NR

Involved Components :

Component Name 1 :	Recept
Component Description :	Recept - DX 15a
Component Part Number :	10091

Supplier Identification :

Component Manufacturer

Name :	NR
Address :	NR
	NR
Country :	NR

Chronology :

In June 2024, a dealership submitted a claim on an Access unit stating there was a non-GFCI outlet installed within 6 feet of the sink. A complete compliance review was initiated on all WTOW models. It was found that 3 Voyage floorplans and 1 Minnie floorplan were impacted as well.

On August 9, 2024 the Product Safety Committee decided the issue presented an unreasonable risk to motor vehicle safety and was a violation of NFPA 70 551.41. The issue was corrected in production and all engineering prints were updated.

Winnebago is not aware of any customer complaints, accidents, injuries, or property damage because of this condition.

Description of Remedy :

Description of Remedy Program :	Reimbursement requests will follow the general reimbursement plan on file with NHTSA.
How Remedy Component Differs from Recalled Component :	Winnebago will correct the outlet to GFCI for adequate protection.
Identify How/When Recall Condition was Corrected in Production :	The condition was inspected and corrected in production immediately on the affected model series.

Recall Schedule :

Description of Recall Schedule :	Recall schedule will follow the 60 day requirement.
Planned Dealer Notification Date :	AUG 30, 2024 - AUG 30, 2024
Planned Owner Notification Date :	OCT 11, 2024 - OCT 11, 2024

* NR - Not Reported