

Part 573 Safety Recall Report

24V-619

Manufacturer Name : Forest River, Inc.**Submission Date :** AUG 16, 2024**NHTSA Recall No. :** 24V-619**Manufacturer Recall No. :** 420-1832**Manufacturer Information :****Population :**

Manufacturer Name : Forest River, Inc.

Number of potentially involved : 25

Address : 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1 : 2024-2025 Forest River Inc. PUMA PUT39DBT Travel Trailers

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The scope was determined using manufacturing records of the last production run of the affected vehicle.

2024 PUMA PUT39DBT 6

2025 PUMA PUT39DBT 19

Grand Total 25

Production Dates : MAY 23, 2024 - JUL 29, 2024

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The anti-siphon vent may have been installed backward "incorrectly". This may lead to reduced performance when filling and draining the holding tank(s).

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Sewer gas may enter the vehicle, which may lead to personal injury.

Description of the Cause : Manufacturing error.

Identification of Any Warning : The operator may notice poor performance in filling/draining the holding tank that can Occur : (s).

Involved Components :

Component Name 1 : Anti-Siphon/Waterless P-Trap

Component Description : Anti-Siphon/Waterless P-Trap

Component Part Number : N/A

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On August 14, 2024, the manufacturing plant contacted Forest River's Office of Corporate Compliance ("OCC") about the concern.

On August 15, 2024, OCC opened a research item into the concern.

On August 16, 2024, Forest River's Corporate Recall Committee voted to recall

Description of Remedy :

Description of Remedy Program :	Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to remove the anti-siphon vent and replace with a new one that will be installed properly.
	What is the Forest River Customer Service Phone Number? (574) 642-0588
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	Puma ATTN: WARRANTY MANAGER 710 Gerber Street Ligonier, IN 46767
How Remedy Component Differs from Recalled Component :	Affected Component – Anti-Siphon/Waterless P-Trap The anti-siphon vent will now be installed in the proper direction.
Identify How/When Recall Condition was Corrected in Production :	The week of August 14, 2024, the manufacturing plant began fixing all vehicles in production and the holding yard that had the anti-siphon vent installed incorrectly.

Recall Schedule :

Description of Recall Schedule :	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
Planned Dealer Notification Date :	SEP 25, 2024 - SEP 25, 2024
Planned Owner Notification Date :	SEP 25, 2024 - SEP 25, 2024

* NR - Not Reported