

Part 573 Safety Recall Report

24V-622

Manufacturer Name : Northern Lite Mfg

Submission Date : AUG 19, 2024

NHTSA Recall No. : 24V-622

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Northern Lite Mfg

Address : 322 TOTOM AVE

Kelowna 00 V1X5W6

Company phone : 7653702

Population :

Number of potentially involved : 958

Estimated percentage with defect : 90 %

Vehicle Information :

Vehicle 1 : 2022-2024 Northern Lite Campers Truck Campers

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Suburban advised the start of the serial numbers of the affected stoves and shipment to us. Through our quality control manual process we identified each unit containing one of those stoves.

Production Dates : MAR 14, 2022 - MAR 20, 2024

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : The led backlight printed circuit boards are not fully coated which can allow liquid from the cooktop surface to accumulate which could result in a short circuit resulting in the boards failure.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the PCB board fails it can overheat and the polyethylene cover of the lights could melt or possibly ignite causing a fire

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Suburban Slide in Range

Component Description : Suburban Elite cook top stove and oven

Component Part Number : Model 3635

Supplier Identification :

Component Manufacturer

Name : Suburban Manufacturing

Address : 676 Broadway Street
Dayton Tennessee 37321

Country : United States

Chronology :

Advised May 31, 2024 from Suburban they were recalled the Elite series stoves with the white/red back lights
June 3, 2024 looked up all units built with affected serial numbers
June 10, 2024 sent letters to all customers with affected stove and the remedy

Description of Remedy :

Description of Remedy Program : All stoves with the red and white knob backlighting are having all wiring terminated and switch removed so they can no longer be activated and no longer cause a risk.

How Remedy Component Differs from Recalled Component : Suburban is terminating the wiring and removing the switch to deactivate all lighting

Identify How/When Recall Condition was Corrected in Production : Recall is being performed at Suburban authorized service centers free of charge to all consumers

Recall Schedule :

Description of Recall Schedule : We received the recall notification from Suburban and GL Products on May 31, 2024

Planned Dealer Notification Date : AUG 16, 2024 - AUG 17, 2024

Planned Owner Notification Date : AUG 16, 2024 - AUG 17, 2024

* NR - Not Reported