

Part 573 Safety Recall Report

24V-749

Manufacturer Name : Quality Van Sales, Inc.

Submission Date : OCT 04, 2024

NHTSA Recall No. : 24V-749

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Quality Van Sales, Inc.

Address : 349 Old Colony Road

Norton MA 02766

Company phone : 800-408-8550

Population :

Number of potentially involved : 1

Estimated percentage with defect : 15 %

Vehicle Information :

Vehicle 1 : 2023-2023 Ford Transit 350

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : TBD

Production Dates : JAN 01, 2023 - DEC 31, 2023

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Noncompliance :

Description of the Noncompliance : SEAT BACK MAY NOT LOCK IN PLACE PROPERLY

FMVSS 1 : 210 - Seat belt assembly anchorages

FMVSS 2 : NR

Description of the Safety Risk : COULD CAUSE INJURY TO OCCUPANT

Description of the Cause : INCORRECT WELDING PROCESS

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : 2 PLACE GO-ES SAVE FOLDWAY SEAT

Component Description : PASSANGER SEAT

Component Part Number : 88335

Supplier Identification :

Component Manufacturer

Name : FREEDMAN SEATING

Address : 4545 WEST AUGUSTA BLVD
CHICAGO Illinois 60651

Country : United States

Chronology :

DURING AN FMVSS 207/210 TEST THE SEAT WAS UNABLE TO SUSTAIN THE TEST LOAD ON 1/26/2023

Description of Remedy :

Description of Remedy Program : THE RECALL WILL BEGIN ON MAY 2024, THE REMEDY WILL CONSIST OF A VISUAL INSPECTION OF THE SEAT BACK LOCKING FUNTION

How Remedy Component Differs from Recalled Component : THE RECLINER MECHANISM HANDLE WILL BE IN THE SAME POSITION WHEN UP RIGHT

Identify How/When Recall Condition was Corrected in Production : THERE IS QUALITY CHECK IN FINAL PRODUCTION

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported