

Part 573 Safety Recall Report

24V-828

Manufacturer Name : KZRV, L.P.**Submission Date :** NOV 01, 2024**NHTSA Recall No. :** 24V-828**Manufacturer Recall No. :** KZ-2024-001**Manufacturer Information :**

Manufacturer Name : KZRV, L.P.

Address : 0985 N 900W

Shipshewana IN 46565

Company phone : 800-768-4016x154/153

Population :

Number of potentially involved : 14

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2025-2025 KZ RV Sportsmen 303QBSE

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All model year 2025 Sportsmen 303QBSE floor plans produced.

Production Dates : JUL 22, 2024 - OCT 21, 2024

VIN Range 1 : Begin : 4EZTU3120S5076227 End : 4EZTU3228S5107755 ☒ Not sequential**Description of Defect :**

Description of the Defect : The off door side slide out actuator is located too close to the tires.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A potential impact between the tire and the actuator exists which increases the risk of a crash.

Description of the Cause : A change to the frame was made to this floor plan for model year 2025. This floor plan was lengthened which caused a clearance problem between the actuator and the tire on the off door side of the vehicle.

Identification of Any Warning that can Occur : Possible tread damage may be seen on the rear tire on the off door side of the vehicle.

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

10/24/2024 - PDI flags a tire clearance issue on a Sportsmen SE 303QBSE model. Engineering is notified and confirms the issue. All vehicles on the premises are put on hold.
10/25/2024 - Further investigation confirms the potential safety risk.
10/28/2024 - A safety committee meeting is held and the decision is made to issue the recall. No warranty or service issues have been reported to KZ.

Description of Remedy :

Description of Remedy Program : The defect will be corrected by installing taller equalizer suspension components. This will increase the distance between the tire and the actuator. All repairs will be done at no cost to the owner. Any reimbursement will follow the general reimbursement plan that is on file with NHTSA.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Any existing frames will be built with the taller equalizer suspension components. Any new frames will have the actuator relocated to address this issue.

Recall Schedule :

Description of Recall Schedule : KZ RV has the utmost urgency in notifying owners about a recall that affects their vehicle. Letters will be sent out once all the pertinent information has been gathered.

Planned Dealer Notification Date : DEC 30, 2024 - DEC 30, 2024

Planned Owner Notification Date : DEC 30, 2024 - DEC 30, 2024

* NR - Not Reported