

Part 573 Safety Recall Report

24V-847

Manufacturer Name : Forest River, Inc.**Submission Date :** NOV 08, 2024**NHTSA Recall No. :** 24V-847**Manufacturer Recall No. :** 83-1862**Manufacturer Information :****Population :**

Manufacturer Name : Forest River, Inc.

Number of potentially involved : 2,898

Address : 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1 : 2021-2025 Forest River Inc. Impression Fifth Wheels

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The scope was determined since the inception of the manufacturing plant. See attached spreadsheet for model and quantity.
See Attached Spreadsheet for Model and Quantity

Production Dates : SEP 04, 2020 - NOV 05, 2024

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The Solar Charge Line, Front LED Hitch Light and the Pass-Thru Light, might be inconsistently wired to a 50AMP mini-breaker. The solar controller may have the incorrect gauge hardness wires.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The wire(s) connected to the improper mini-breaker could potentially melt, causing a short which could potentially lead to a fire, property damage and/or personal injury.

Description of the Cause : Manufacturing Error

Identification of Any Warning None
that can Occur :

Involved Components :

Component Name 1 : 12V Wiring

Component Description : 12V Wiring

Component Part Number : N/A

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On October 30, 2024, During a routine Corporate Standards Inspection of the manufacturing plant it was discovered that certain 12V wiring may be inconstantly wired.

On October 31, 2024, OCC was informed by the Standards Manager of the concern, a research item was opened.

On November 4, 2024, OCC contacted the manufacturing plant to see if it is believed any vehicles left the facility in this condition.

On November 8, 2024, Forest River's Corporate Committee voted to recall.

Description of Remedy :

Description of Remedy Program :	Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to connect the wire to the proper mini breaker.
	What is the Forest River Customer Service Phone Number? (574) 367-3314
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	Impression 57490 County Road 3 Elkhart, IN 46517
How Remedy Component Differs from Recalled Component :	12V Wiring – the wiring will now be connected to the proper mini-breaker
Identify How/When Recall Condition was Corrected in Production :	The week of November 4, 2024, the manufacturing plant began moving the 12V wiring to the proper mini-breaker.

Recall Schedule :

Description of Recall Schedule :	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
Planned Dealer Notification Date :	DEC 18, 2024 - DEC 18, 2024
Planned Owner Notification Date :	DEC 18, 2024 - DEC 18, 2024

* NR - Not Reported