

# Part 573 Safety Recall Report

## 24V-912

**Manufacturer Name :** Forest River, Inc.**Submission Date :** DEC 06, 2024**NHTSA Recall No. :** 24V-912**Manufacturer Recall No. :** 121-1874**Manufacturer Information :****Population :****Manufacturer Name :** Forest River, Inc.**Number of potentially involved :** 864**Address :** 55470 CR 1**Estimated percentage with defect :** 100 %**P.O. Box** 3030 Elkhart IN 46515-3030**Company phone :** 1-800-348-7440**Vehicle Information :****Vehicle 1 :** 2024-2025 Forest River Inc. Viking Travel Trailers**Vehicle Type :** TRAILERS**Body Style :** OTHER**Power Train :** NR

**Descriptive Information :** The scope was determined by reviewing warranty claims of single LPG tank brackets. This information indicated an increase in claims from July 2023 through December 2023.

2024 VIKING VWT17SBHSAGA 120

2024 VIKING VWT17SFQSAGA 80

2025 VIKING VWT17SBHSAGA 22

2025 VIKING VWT17SFQSAGA 26

**Production Dates :** JUL 24, 2023 - OCT 31, 2024**VIN Range 1 : Begin :**

NR

**End :** NR☐ Not sequential

Vehicle 2 : 2024-2025 Forest River Inc. Clipper Travel Trailers  
Vehicle Type : TRAILERS  
Body Style : UNKNOWN  
Power Train : NR

Descriptive Information :  
The scope was determined by reviewing warranty claims of single LPG tank brackets. This information indicated an increase in claims from July 2023 through December 2023.

2024	CLIPPER	CWT15CBHCADET	41
2024	CLIPPER	CWT17CBHCADET	142
2024	CLIPPER	CWT17CFQCADET	72
2024	CLIPPER	CWT182DBU	9
2024	CLIPPER	CWT18FQ	56
2025	CLIPPER	CWT17CBHCADET	223
2025	CLIPPER	CWT17CFQCADET	66
2025	CLIPPER	CWT18FQ	7

Production Dates : JUL 24, 2023 - OCT 31, 2024  
VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Description of Defect :

Description of the Defect : The weld that attached the leg(s) of the bracket may break, if this condition occurs, the LP tank may become loose from the vehicle.

FMVSS 1 : NR  
FMVSS 2 : NR

Description of the Safety Risk : If the LP tank becomes loose from the vehicle, this condition may lead to property damage, or a crash.

Description of the Cause : Unknown

Identification of Any Warning that can Occur : An operator may notice the LP tank bracket is broken when turning the LP gas on or off.

Involved Components :

Component Name 1 : LP Bottle Bracket, Single Tank  
Component Description : LP Bottle Bracket, Single Tank  
Component Part Number : P/N - 01364-6

Supplier Identification :

Component Manufacturer

Name : Goshen Stamping  
Address : 1025 S 10th St  
Goshen Indiana 46526  
Country : United States

Chronology :

Forest Rivers Office of Corporate Compliance ("OCC") received a Vehicle Owner Questionnaire ("VOQ") #11606604 from NHTSA's Office of Defects Investigations ("ODI"). This led Forest River to review warranty claims and complaints of the "L Bracket" used to mount the LPG Tank. OCC did find a potential trends in warranty claims. 25 Total Claims

On December 6, 2024, Forest River's Corporate Committee voted to recall.

Description of Remedy :

Description of Remedy Program :	Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy. The LP bottle bracket will be inspected for cracks, if found the LP bottle bracket will be replaced.
	What is the Forest River Customer Service Phone Number? (269) 467-8283
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	Viking RV White Pigeon 500 W. Chicago Rd. White Pigeon, MI 49099
How Remedy Component Differs from Recalled Component :	Goshen Stamping - (574) 533-4108 1025 S 10th St Goshen, IN 46526

Affected Component - LP Bottle Bracket, Single Tank  
P/N - 01364-6  
Replacement Component – LP Bottle Bracket, Single Tank  
P/N - 01364-6  
  
Unknown

Identify How/When Recall Condition was Corrected in Production : The warranty claims spike dissipates after December 2023.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : JAN 15, 2025 - JAN 15, 2025  
Planned Owner Notification Date : JAN 15, 2025 - JAN 15, 2025

\* NR - Not Reported