

Part 573 Safety Recall Report

24V-923

Manufacturer Name : Suzuki Motor USA, LLC

Submission Date : DEC 11, 2024

NHTSA Recall No. : 24V-923

Manufacturer Recall No. : 3A05



Manufacturer Information :

Manufacturer Name : Suzuki Motor USA, LLC

Address : 3251 East Imperial Highway
Brea CA 92821-6795

Company phone : 714-996-7040

Population :

Number of potentially involved : 556

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2023-2025 Suzuki AN400

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : The recall population was determined from production records. Models affected with this defect have fuel supply hose assemblies that were improperly installed during original assembly.

Production Dates : SEP 15, 2022 - JUN 20, 2024

VIN Range 1 : Begin : JS1DU11J3P7100009 **End :** JS1DU11J4S7100061

☒ Not sequential

Description of Defect :

Description of the Defect : The fuel supply hose assembly can come into contact with the fuel vapor hose assembly and the fuel supply hose can be abraded. In the worst case, the fuel supply hose can be abraded to a degree that could cause a fuel leak from the hose.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If fuel leaks from the fuel supply hose assembly, the risk of fire is increased.

Description of the Cause : Improper installation caused bending of the metal pipe portion of the hose assembly, placing the fuel supply hose assembly at risk of potential contact with the fuel vapor hose assembly.

Identification of Any Warning that can Occur : If the fuel supply hose assembly is compromised, fuel smell may be detected after a period of vehicle shut off.

Involved Components :

Component Name 1 : Hose comp, Fuel

Component Description : Fuel supply hose

Component Part Number : 15810-19K00

Component Name 2 : Hose, Purge No.2

Component Description : Fuel vapor hose

Component Part Number : 18562-19K10

Supplier Identification :

Component Manufacturer

Name : Suzuki Motor Corporation

Address : 300 Takatsuka-cho
Chuo-ku, Hamamatsu-shi Shizuoka-ken Foreign States 432-8611

Country : Japan

Chronology :

The chronology is provided as a separate document.

Description of Remedy :

Description of Remedy Program : The fuel supply hose assembly and fuel vapor hose assembly will be replaced with new parts. The plan for reimbursing customers who have paid for repairs to remedy the reported condition is attached as a separate document.

How Remedy Component Differs from Recalled Component : The remedy parts are identical to the original production parts. The replacement fuel supply hose assembly will be installed such that improper bending does not occur and proper routing clearance is maintained.

Identify How/When Recall Condition was Corrected in Production : The recall condition was corrected from June 10, 2024, production through the application of additional training for production staff.

Recall Schedule :

Description of Recall Schedule :	The notification schedule shown is the current estimate. Suzuki will provide notification of any schedule changes as necessary.
Planned Dealer Notification Date :	DEC 18, 2024 - DEC 18, 2024
Planned Owner Notification Date :	JAN 10, 2025 - JAN 10, 2025

* NR - Not Reported