

# Part 573 Safety Recall Report

## 24V-947

**Manufacturer Name :** Jaguar Land Rover North America, LLC

**Submission Date :** DEC 19, 2024

**NHTSA Recall No. :** 24V-947

**Manufacturer Recall No. :** N946



### Manufacturer Information :

### Population :

**Manufacturer Name :** Jaguar Land Rover North America, LLC

**Address :** 100 Jaguar Land Rover Way

Mahwah NJ 07495

**Company phone :** 8188500

**Number of potentially involved :** 11,961

**Estimated percentage with defect :** 100 %

### Vehicle Information :

**Vehicle 1 :** 2022-2023 LAND ROVER RANGE ROVER

**Vehicle Type :** LIGHT VEHICLES

**Body Style :** SUV

**Power Train :** NR

**Descriptive Information :** Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2024MY Land Rover Range Rover vehicles built at the Solihull Vehicle Assembly Plant from March 2, 2022 - December 15, 2023. 11,961 Land Rover Range Rover vehicles in the United States and Federalized Territories. The basis for the recall population of Land Rover Range Rover vehicles was determined by matching the at-risk camera serial numbers to VINs using vehicle build records.

**Production Dates :** MAR 02, 2022 - DEC 15, 2023

**VIN Range 1 : Begin :** SALKP9FU2NA003771 **End :** SALKP9E71PA042673

☐ Not sequential

### Description of Defect :

**Description of the Defect :** A concern has been identified where, on certain Range Rover vehicles, water could get into the rear-facing tailgate mounted camera. This water ingress can cause a distorted image, or no image at all, to be displayed on the touchscreen.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** A blurred image or lack of display of the camera image may result in the driver being unaware of objects or pedestrians increasing the risk of an injury and a crash.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

**Involved Components :**

Component Name 1 : Rear camera

Component Description : Rear camera

Component Part Number : L8B2-19H422-AD

**Supplier Identification :****Component Manufacturer**

Name : Robert Bosch Ltd

Address : Robert Bosch Ltd

Millburn Hill Road Coventry Foreign States CV4 7HS

Country : United Kingdom

**Chronology :**

See File "Recall N946 Chronology".

**Description of Remedy :**

Description of Remedy Program : Remedial action is presently being developed and will be advised in due course. There will be no charge to the owners for this repair.  
Any vehicles under warranty will be covered under JLR's new vehicle warranty program, therefore re-imbursement for pre-notice remedies is not applicable. Customers who have paid for a repair of this defect out of warranty will be reimbursed by JLR's reimbursement plan, subject to the usual terms and conditions.

How Remedy Component Differs NR  
from Recalled Component :

Identify How/When Recall Condition NR  
was Corrected in Production :

**Recall Schedule :**

Description of Recall Schedule : Notifications to dealers will occur on January 8, 2025. Distribution of owner notification letters will occur on or before February 14, 2025.

Planned Dealer Notification Date : JAN 08, 2025 - JAN 08, 2025

Planned Owner Notification Date : FEB 14, 2025 - FEB 14, 2025

\* NR - Not Reported