

Part 573 Safety Recall Report

25V-027

Manufacturer Name : Forest River Bus, LLC**Submission Date :** JAN 22, 2025**NHTSA Recall No. :** 25V-027**Manufacturer Recall No. :** 05-1890**Manufacturer Information :**

Manufacturer Name : Forest River Bus, LLC

Address : 2367 Century Drive

Goshen IN 46528

Company phone : (800) 348-7440

Population :

Number of potentially involved : 37

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2023-2024 Forest River Bus LLC Starcraft Starlite Transit Buses

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : 2023

STARCRAFT STARLITE

ST93082

20

2023

STARCRAFT STARLITE

ST93274

9

2024

STARCRAFT STARLITE

ST93274

4

The scope was determined using manufacturing records of the inception of the model, to current date.

Production Dates : FEB 27, 2023 - DEC 06, 2023

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2023-2023 Forest River Bus LLC Starcraft Allstar Transit Buses
Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES
Body Style : OTHER
Power Train : NR

Descriptive Information : 2023
STARCRAFT ALLSTAR
ST93119
4

The scope was determined using manufacturing records of the inception of the model, to current date.

Production Dates : FEB 27, 2023 - JUN 08, 2023

VIN Range 1 : Begin : NR End : NR

Not sequential

Description of Noncompliance :

Description of the Noncompliance : In certain vehicles, the egress handles and labels were not easily accessible as required by FMVSS 217.

FMVSS 1 : 217 - Bus emergency exits and window retention and release

FMVSS 2 : NR

Description of the Safety Risk : If a vehicle rolls over onto the entry door or there is a fire that blocks access to the entry door, the vehicle may pose personal injury to a passenger and/or operator.

Description of the Cause : Engineering error.

Identification of Any Warning that can Occur : None

Involved Components :

Component Name 1 : Egress Window with bottom handle

Component Description : Egress Window with bottom handle

Component Part Number : N/A

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR
NR
Country : NR

Chronology :

On June 17, 2024, Forest River's Office of Corporate Compliance ("OCC") received an email from NHTSA on behalf of a state inspector, which indicated that a transit bus had egress handles and labels were not easily accessible as required by FMVSS 571.217.

On June 20, 2024, OCC opened a research item into the concern and met with the manufacturing plant.

On June 24, 2024, through June 28, 2024, the manufacturing plant and OCC continued to research the concern.

On July 2, 2024, during an emergency meeting, the Corporate Safety Committee voted to recall.

On July 3, 2024, During the final review of the scope, OCC and the Manufacturing Plant determined that the Starcraft Allstar was listed as the recalled model whereas it should have been the Starcraft Starlite only. Further details were able to lower the scope from 100 vehicles to 62 vehicles.

On September 11, 2024, Forest River amended the recall to reflect dealers only within the scope of vehicles.

On January 14, 2025, Forest River noticed a clerical error in the data. Forest River is increasing the scope to 99 vehicles.

On January 21, 2025, Forest River received an email from NHTSA requesting a new recall be filed due to the age of the recall, the additional model being added and increase in population, as well as the notifications were already sent, and reporting had begun on the original population

On January 22, 2024, Forest River file a new recall for the amended population.

Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to replace the existing egress window which has a bottom handle, to an egress window that has a side handle.

What is the Forest River Customer Service Phone Number? (800) 348-7440

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Starcraft Bus
2367 Century Drive
Goshen, IN 46528

How Remedy Component Differs from Recalled Component : Affected Component – Egress Window with bottom handle
The new egress window will have a side handle.

Identify How/When Recall Condition was Corrected in Production : During the conclusion of the research, the manufacturing plant began ordering and installing side handle egress windows during the week of July 2, 2024.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : MAR 03, 2025 - MAR 03, 2025

Planned Owner Notification Date : MAR 03, 2025 - MAR 03, 2025

* NR - Not Reported