

# Part 573 Safety Recall Report

## 25V-043

**Manufacturer Name :** Jayco, Inc.**Submission Date :** JAN 30, 2025**NHTSA Recall No. :** 25V-043**Manufacturer Recall No. :** 9901617**Manufacturer Information :****Population :**

Manufacturer Name : Jayco, Inc.

Number of potentially involved : 412

Address : 903 South Main Street

Estimated percentage with defect : 100 %

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

**Vehicle Information :**

Vehicle 1 : 2025-2025 Jayco Jay Feather Micro

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

**Descriptive Information :** Dicor Corporation provided a list of affected Invision three burner cooktops with model # 410-2030 purchased by Jayco Inc. that are affected by Dicor Corporation recall 24E-105. Jayco Regulatory Compliance Team determined the scope from our production records.

Production Dates : JUN 13, 2024 - JAN 14, 2025

VIN Range 1 : Begin : 1UJBB0AKXS1JM0069 End : 1UJBB0AJXS1JP0051

☒ Not sequential**Description of Defect :**

**Description of the Defect :** Jayco Inc. and Dicor Corporation are recalling certain InVision Three Burner Cooktops, model number 410-2030. The aluminum burner tube may crack and cause a gas leak.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** A gas leak in the presence of an ignition source can increase the risk of a fire.

**Description of the Cause :** Per Dicor recall 24E-105 during manufacture of the center burner tube, it was bent excessively resulting in a fracture of the tube.

**Identification of Any Warning that can Occur :** Per Dicor recall 24E-105 The owner could experience the following as an indicator of the defect:

1. The owner could possibly hear a louder than normal hissing sound or smell Propane odor when the cooktop gas valve is turned to the "on" position.
2. The flame height could seem lower than normal.
3. There could be a flash and whooshing sound when igniting the burner.
4. The control knob of the cooktop could appear to be loose and become

difficult to operate.

Involved Components :

Component Name 1 : Burner Tube

Component Description : Aluminum Burner Tube

Component Part Number : 101067

Supplier Identification :

Component Manufacturer

Name : Dicor Corporation

Address : 2965 Lavanture Place  
Elkhart Indiana 46514

Country : United States

Chronology :

See Dicor Corporation Chronology for Equipment Recall 24E-105 regarding Invison three burner cooktops. On January 6, 2025, Jayco Inc. Compliance team received an OEM customer notification letter via email from Invison in regards to Dicor Corporation recall 24E-105. On January 6, 2025, The Warranty Incident Review Committee (WIRC) discussed the incident and elevated it to CPAC. On January 8, 2025, The Corrective Preventive Action Committee (CPAC) discussed the incident and elevated it to SSC. On January 23, 2025, The Safety Steering Committee (SSC) met and voted to proceed with filing a safety recall with NHTSA and Transport Canada. There are 25 warranty claims associated with this recall.

Description of Remedy :

Description of Remedy Program : Jayco Inc. authorized dealers will replace the center burner tube, free of charge. Repairs made prior to the recall will be reimbursed in accordance with our Recall Reimbursement Plan on file with NHTSA. Jayco Inc. will be reporting the quarterly completion rates to NHTSA.

How Remedy Component Differs from Recalled Component :	An orange dot along with the date and initials of the repair technician has been made next to the serial number on the data plate for remedied units.
Identify How/When Recall Condition was Corrected in Production :	Per Dicor report, all Dicor inventory on hand was remedied and marked. This occurred the week of December 16, 2024. Any affected cooktops in Jayco's production have been inspected and remedied by Dicor / Invision on January 24, 2025.

Recall Schedule :

Description of Recall Schedule :	Jayco Inc. will notify its dealers and affected retail owners.
Planned Dealer Notification Date :	FEB 28, 2025 - FEB 28, 2025
Planned Owner Notification Date :	FEB 28, 2025 - FEB 28, 2025

\* NR - Not Reported