OMB Control No.: 2127-0004

82

Part 573 Safety Recall Report

Manufacturer Name : General Motors, LLC Submission Date : FEB 13, 2025 NHTSA Recall No.: 25V-087 Manufacturer Recall No.: NR

Manufacturer Information :

Manufacturer Name : General Motors, LLC Address: 29427 Louis Chevrolet Road 480-210-2V Warren MI 48093 Company phone : 586-596-1733

Vehicle Information :

Vehicle 1:	2025-2025 Chevrolet Express		
Vehicle Type :			
Body Style :			
Power Train :	NR		
Descriptive Information :	Manufacturing records were used to determine the recall population.		
	Vehicles with driver side doors manufactured outside of the suspect window are no included in this recall.		
	There are 74 Chevrolet	Express vehicles affected by t	this recall.
Production Dates :	DEC 06, 2024 - DEC 10,	2024	
VIN Range 1:	Begin : NR	End: NR	Not sequential
Vehicle 2:	2025-2025 GMC Savan	na	
Vehicle Type :			
Body Style :			
Power Train :	NR		
Descriptive Information :	Manufacturing records were used to determine the recall population.		
	Vehicles with driver side doors manufactured outside of the suspect window are no included in this recall.		
	There are 8 GMC Savana vehicles affected by this recall.		
	There are 8 GMC Savana	a vehicles affected by this rec	all.
Production Dates :	There are 8 GMC Savana DEC 09, 2024 - DEC 09,		all.

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved :

Estimated percentage with defect : 75~%

Population :

25V-087

Description of Defect :

General Motors has decided that a defect which relates to motor vehicle safety may exist in certain 2025 model year Chevrolet Express and GMC Savana vehicles. An impact beam located in the driver's side door may have improper welds at the beam's front connection point to the door.	
NR	
NR	
The beam may not perform as intended in a side-impact crash, increasing the risk of injury to the driver.	
The robot used to perform these welds during assembly malfunctioned due to an electrical failure internal to the weld gun.	
NR	

Involved Components :

Component Name 1: BAR-FRT S/D OTR PNL

Component Description : Impact Beam

Component Part Number : 85023383

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

On December 12, 2024, a GM employee submitted a report to GM's Speak Up for Safety (SUFS) program after discovering cold welds on a driver's side door impact beam during a quality check at GM's Wentzville assembly plant. GM opened a production investigation on December 17, 2024.

GM's investigation defined a suspect build window of vehicles potentially produced with the driver's side door impact beam improperly welded at the front connection to the door assembly. Up to 94 of these suspect vehicles were not contained at GM's assembly plant. 82 of these vehicles are in the US. GM is not aware of any

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

accidents or injuries associated with this condition. On February 6, 2025, GM's Safety Field Action Decision Authority (SFADA) decided to conduct a safety recall. **Description of Remedy :** Description of Remedy Program : Dealers will replace the driver's side door. Pursuant to 577.11, General Motors does not plan to provide notice about reimbursement to owners because owners would not have been aware of the issue prior to this recall. How Remedy Component Differs The impact beam is properly welded on the replacement door. from Recalled Component : Identify How/When Recall Condition The malfunctioning welding robot was replaced on December 11, 2024. was Corrected in Production : Vehicles produced after that time have properly welded impact beams. **Recall Schedule :** Description of Recall Schedule : Dealers will be notified on February 13, 2025. Owner interim notification is estimated to begin on March 31, 2025. GM will provide an estimate for owner notification of an available remedy once that is determined. Planned Dealer Notification Date : FEB 13, 2025 - FEB 13, 2025 Planned Owner Notification Date : MAR 31, 2025 - MAR 31, 2025

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573