OMB Control No.: 2127-0004

Part 573 Safety Recall Report

25V-143

Manufacturer Name: Airstream, Inc.
Submission Date: MAR 05, 2025
NHTSA Recall No.: 25V-143

MATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Manufacturer Information:

Manufacturer Recall No.: NR

Manufacturer Name: Airstream, Inc.

Address: 419 West Pike Street

PO Box 629 Jackson Center OH

45334-0629

Company phone: 937-596-6111

Population:

Number of potentially involved : 648 Estimated percentage with defect : 100%

Vehicle Information:

Vehicle 1: 2021-2025 Airstream MY 2021-2025 33' Classic, MY 2024-2025 30' Classic, MY 2025

28' Classic

Vehicle Type: TRAILERS Body Style: UNKNOWN

Power Train: NR

Descriptive Information: To determine the recall population, we researched the number of Classic travel

trailers produced with sofas that utilized a switch assembled with wires that were not

rated appropriately for the application.

Production Dates: MAR 05, 2021 - FEB 24, 2025

 VIN Range 1 : Begin :
 1STVBYT2XMJ556314
 End :
 1STVBYT21SJ575508

 VIN Range 2 : Begin :
 1STJBYP2XRJ568592
 End :
 1STJBYP29SJ575863

 VIN Range 3 : Begin :
 1STJBYM24SJ574267
 End :
 1STJBYM29SJ575477

☐ Not sequential

Not sequential

■ Not sequential

Description of Defect:

Description of the Defect: The sofa footrest switch does not have a stop limit application and was

manufactured with underrated wires for the application. If the switch is

depressed for extended periods of time, the wires could heat up.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the switch is depressed for an extended period of time, that would cause

the wires to heat up, it may cause a fire, increasing the risk of personal injury and/or property damage. Airstream is unaware of any property damage, or

injuries related to this condition.

Description of the Cause: Underrated wires and the lack of a stop limit device combined with the switch

being depressed for an extended period of time.

Identification of Any Warning A burning smell may occur. that can Occur:

Involved Components:

Component Name 1: Round Switch for Sofa Footrest Component Description: Extend/Retract the Sofa Footrest

Component Part Number: 704729-6070

Supplier Identification:

Component Manufacturer

Name: Midwest Composites

Address: 302 Krein Ave.

Wapakoneta Ohio 45895

Country: United States

Chronology:

1/22/2025 - We were notified of a Classic travel trailer with a thermal event relating to the sofa switch. We requested that the trailer be brought back to Airstream for review.

2/12/2025 - Upon the unit's arrival, Airstream started the investigation with an inspection.

2/14/2025 - We began identifying a remedy for the affected and future production units.

2/18/2025 - Ran query of historical data to determine if other occurrences related to this scenario.

2/19/2025 - We met with Midwest, informed them of the event, and discussed a potential solution.

2/25/2025 - Established the recall population.

2/26/2025 - The safety committee reviewed all known data and determined a recall is warranted. No warranty claims, customer complaints, or injuries have been related to this issue.

2/27/2025 - Airstream implemented the repair process in production.

Description of Remedy:

Description of Remedy Program: Dealers will be instructed to install the reverse relay on the sofa switch

assembly of the affected units. This will be completed at no cost to the customer. Reimbursement will follow the general reimbursement policy

that is on file with NHTSA.

How Remedy Component Differs Airstream Classic units manufactured after February 26, 2025.

from Recalled Component:

Identify How/When Recall Condition The condition was corrected when production implemented the reverse

was Corrected in Production: relay into the sofa switch assembly on 2/27/2025.

Recall Schedule:

Description of Recall Schedule: Airstream has the utmost urgency in notifying owners about a recall that

affects their vehicle. Letters will be sent out once all pertinent

information has been gathered.

Planned Dealer Notification Date : MAY 04, 2025 - MAY 04, 2025 Planned Owner Notification Date : MAY 04, 2025 - MAY 04, 2025

^{*} NR - Not Reported