

Part 573 Safety Recall Report

25V-180

Manufacturer Name : Winnebago Towable

Submission Date : MAR 21, 2025

NHTSA Recall No. : 25V-180

Manufacturer Recall No. : CAM0000042



Manufacturer Information :

Manufacturer Name : Winnebago Towable

Address : 201 14th Street
Middlebury IN 46540

Company phone : 825-5250

Population :

Number of potentially involved : 70

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2025-2025 Winnebago Access

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying the production dates.

Production Dates : APR 18, 2024 - DEC 18, 2024

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 2 : 2025-2025 Winnebago Voyage

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying the production dates.

Production Dates : APR 18, 2024 - DEC 18, 2024

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Description of Noncompliance :

Description of the Noncompliance : Certain Winnebago vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard No. 110, "Tire Selection and Rims." The Federal Identification Label and Tire Loading Information Placard has the incorrect tire inflation listed.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : Misprinted labels could lead to failure to follow proper vehicle loading specifications or tire inflation recommendation which could result in tire failure, increasing the risk of a crash.

Description of the Cause : A typographical error occurred when the 2025 models were entered into the system.

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : LABEL-UNIT FED TIRE 4X6

Component Description : LABEL-UNIT FED TIRE 4X6

Component Part Number : 20174113000

Supplier Identification :

Component Manufacturer

Name : Winnebago of Indiana

Address : 201 14th Street
Middlebury Indiana 46540

Country : United States

Chronology :

In mid-January, Product Safety was notified of an initial claim involving The Federal Identification Label and Tire Loading Information Placard stating the incorrect tire inflation listed and in mid-February Product Safety was notified of a second claim. An investigation was subsequently opened. During the investigation, it was found that 106 units showed the incorrect tire pressure listed. The Product Safety Committee met on March 17, 2025 and determined these vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard No. 110 "Tire Selection and Rims" and a recall was initiated.

Winnebago is aware of 2 claims, 0 injuries, and no property damage as a result of this condition.

Description of Remedy :

Description of Remedy Program : Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How Remedy Component Differs Customers will be provided with a new Federal Identification Label and

from Recalled Component :

Tire Loading Information Placard and installation instructions. The customers will also have the option to utilize a dealer for installation.

Identify How/When Recall Condition was Corrected in Production :

The Federal Identification Label and Tire Loading Information Placard has been corrected in the system.

Recall Schedule :

Description of Recall Schedule :

Recall notifications will follow the 60 day requirement.

Planned Dealer Notification Date :

APR 04, 2025 - APR 04, 2025

Planned Owner Notification Date :

APR 30, 2025 - APR 30, 2025

* NR - Not Reported