

Part 573 Safety Recall Report

25V-183

Manufacturer Name : Keystone RV Company**Submission Date :** MAR 25, 2025**NHTSA Recall No. :** 25V-183**Manufacturer Recall No. :** 25-464**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 70

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2025-2025 Keystone Kodiak 2900FKSP, 308BHSL

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Floor plans using the patio latch with screws

Production Dates : SEP 04, 2024 - FEB 20, 2025

VIN Range 1 : Begin : 4YDTKDP29SJ970381 End : 4YDTKDP25SJ970765 ☒ Not sequential**Description of Defect :**

Description of the Defect : It has been decided that the vehicles in the recall population have a patio latch that may come detached.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Under certain conditions during travel, the travel latch can become detached leading to an increased risk of personal injury.

Description of the Cause : The screws used to hold the latch in place are not sufficient for the weight of the patio.

Identification of Any Warning that can Occur : Latch may become loose and begin to move.

Involved Components :

Component Name 1 : Patio frame with latch bracket attached

Component Description : Support - Deck Frame - 62 x 93 7/8" - LPMWB - Aluminum Powder Coated - Black Component

Component Part Number : 752295

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

- 3/14/2025 – Report was made by email
- 3/14/2025– Investigation opened. All affected units were put on hold and all yard units were inspected. Production fixed all yard units
- 3/14/2025 – Warranty claims for patio latch include 1 claim, claim created start date 3/14/2025 to claim created end date 3/14/2025
- 3/17/2025– Keystone Safety Committee reviewed the information and concluded that the data reviewed indicated a unanimous vote for a voluntary recall. Investigation called for to determine affected unit range.
- 3/20/2025 – Investigation concluded, and scope completed.

Description of Remedy :

- Description of Remedy Program : The remedy is to remove the screws and replace them with bolts and locking nuts. Manufacturer Reimbursement Plan on file as of 10/3/2024. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.
- How Remedy Component Differs from Recalled Component : The bolts and locking nuts replace the screws holding the latching bracket to the frame. Part # 752295 Support - Deck Frame - 62 x 93 7/8" - LPMWB - Aluminum - Powder Coated - Black
- Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected, then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule :	Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.
Planned Dealer Notification Date :	MAY 15, 2025 - MAY 15, 2025
Planned Owner Notification Date :	MAY 15, 2025 - MAY 15, 2025

* NR - Not Reported