

Part 573 Safety Recall Report

25V-230

Manufacturer Name : Forest River, Inc.**Submission Date :** APR 10, 2025**NHTSA Recall No. :** 25V-230**Manufacturer Recall No. :** 203-1917**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Population :

Number of potentially involved : 27

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2025-2025 Forest River Inc. Coachmen Catalina BCAT154RBX Travel Trailers

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The scope was determined using manufacturing records of the last production of this model.

2025 CATALINA BCAT154RBX 27

Grand Total 27

Production Dates : MAR 04, 2025 - MAR 27, 2025

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The waste water holding tank(s) ventilation pipe may not be terminated exterior of the vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Sewer gas may enter the vehicle, which may lead to personal injury.

Description of the Cause : Manufacturing error.

Identification of Any Warning that can Occur : An operator may notice sewer gas smell.

Involved Components :

Component Name 1 : Black Plumbing Vent Pipe

Component Description : Black Plumbing Vent Pipe

Component Part Number : N/A

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On April 7, 2025, the manufacturing plant notified Forest Rivers Office of Corporate Compliance ("OCC") of the concern. The same day OCC opened a research item into the concern.

On April 10, 2025, Forest Rivers Corporate Committee voted to recall.

Description of Remedy :

Description of Remedy Program :	<p>Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to extend the pipe through to the exterior of the vehicle.</p> <p>What is the Forest River Customer Service Phone Number? (574) 825-4995</p> <p>If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:</p> <p>Catalina 423 N Main St. Middlebury, IN 46540</p>
How Remedy Component Differs from Recalled Component :	<p>Affected Component - Black Plumbing Vent Pipe Replacement Component - Black Plumbing Vent Pipe</p> <p>The Black Plumbing Vent Pipe will now exit through the vehicle to eliminate the sewer gas smell.</p>
Identify How/When Recall Condition was Corrected in Production :	<p>The week of April 7, 2025, the manufacturing plant began fixing all vehicles in production and the holding yard that did not have the vent installed incorrectly.</p>

Recall Schedule :

Description of Recall Schedule :	<p>Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.</p>
Planned Dealer Notification Date :	<p>MAY 20, 2025 - MAY 20, 2025</p>
Planned Owner Notification Date :	<p>MAY 20, 2025 - MAY 20, 2025</p>

* NR - Not Reported