

Part 573 Safety Recall Report

25V-263

Manufacturer Name : Forest River, Inc.**Submission Date :** APR 18, 2025**NHTSA Recall No. :** 25V-263**Manufacturer Recall No. :** 504-1919**Manufacturer Information :****Population :**

Manufacturer Name : Forest River, Inc.

Number of potentially involved : 16

Address : 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1 : 2025-2025 Forest River Inc. East to West Bravado BRC33DSF Class C

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : The scope was determined from when a engineering drawing was revised in error, then corrected.

Production Dates : FEB 26, 2025 - MAR 31, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The slideroom end walls and main wall bottom tube(s) are the incorrect gauge, additionally the fasteners are not the correct length to capture both walls of the end walls and main wall.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The slideroom floor may detach from the vehicle in the open position. Additionally, the slideroom floor may not withstand the required seatbelt retention during a crash. This may lead to personal injury.

Description of the Cause : Engineering Error

Identification of Any Warning : An operator may notice the slideroom hard to close as the slide floor hits the that can Occur : main floor of the vehicle when retracted.

Involved Components :

Component Name 1 : Slideroom Floor

Component Description : Slideroom Floor

Component Part Number : N/A

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On April 15, 2025, Forest River's Office of Corporate Compliance ("OCC") was notified by the manufacturing plant of the concern. The plant received a single warranty claim. While reviewing, the manufacturing plant found the entire inventory of vehicles in the holding yard to have the same concern. OCC opened a research item into the concern.

On April 18, 2025, Forest River's Corporate Committee voted to recall.

Description of Remedy :

Description of Remedy Program :	Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to secure the floor. What is the Forest River Customer Service Phone Number? (574) 264-6664 If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address: East to West 3000 County Road 6 West Elkhart, IN 46514
How Remedy Component Differs from Recalled Component :	Affected Component – Slideroom Floor P/N – N/A Replacement Component – 5” Fasteners The floor will now be secured properly.
Identify How/When Recall Condition was Corrected in Production :	During the week of April 15, 2025, the manufacturing plant revised the engineering drawing to reflect the correct gauge tube(s). Additionally, the manufacturing plant started installing longer fasteners to capture both top and bottom tube walls of the slideroom end walls and main wall.

Recall Schedule :

Description of Recall Schedule :	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
Planned Dealer Notification Date :	MAY 28, 2025 - MAY 28, 2025
Planned Owner Notification Date :	MAY 28, 2025 - MAY 28, 2025

* NR - Not Reported