

Part 573 Safety Recall Report

25V-264

Manufacturer Name : Forest River, Inc.**Submission Date :** APR 18, 2025**NHTSA Recall No. :** 25V-264**Manufacturer Recall No. :** 300-1922**Manufacturer Information :****Manufacturer Name :** Forest River, Inc.**Address :** 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440**Population :****Number of potentially involved :** 975**Estimated percentage with defect :** 100 %**Vehicle Information :****Vehicle 1 :** 2024-2025 Forest River Inc. Aurora Travel Trailers**Vehicle Type :** TRAILERS**Body Style :** OTHER**Power Train :** NR**Descriptive Information :** 2024

AURORA

ART28BHS

14

2025

AURORA

ART24RBS

120

2025

AURORA

ART26ATH

37

2025

AURORA

ART28BHS

59

The scope was identified since inception of the manufacturing plant.

Production Dates : APR 26, 2024 - APR 14, 2025**VIN Range 1 : Begin :**

NR

End : NR☐ Not sequential

Vehicle 2 : 2024-2025 Forest River Inc. Coachmen Catalina Travel Trailers
Vehicle Type : TRAILERS
Body Style : OTHER
Power Train : NR

Descriptive Information : The scope was identified since inception of the manufacturing plant.

Production Dates : APR 26, 2024 - APR 14, 2025

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Description of Defect :

Description of the Defect : The front exterior accent lamp wire (16AWG) may be on a 30AMP breaker, whereas it should be on a 10AMP over current device. The awning may be missing the required 15AMP over current protection. The auto-leveling system may be wired to constant hot on a 30AMP mini-breaker.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : 12V wiring may not have over current protection. This condition may lead to a fire and property damage.

2024
CATALINA
CAT263BHCKLE
117
2024
CATALINA
CAT283EPIC
3
2024
CATALINA
CAT293QBCKLE
22
2025
CATALINA
CAT243RBSLE
119
2025
CATALINA
CAT261BH
16
2025
CATALINA
CAT263BHCKLE
161
2025
CATALINA

CAT26TH
55
2025
CATALINA
CAT281QBUNK
19
2025
CATALINA
CAT283EPIC
152
2025
CATALINA
CAT293QBCKLE
80
2025
CATALINA
CAT293TQBCKLE
1

Description of the Cause : Manufacturing Error
Identification of Any Warning that can Occur : None

Involved Components :

Component Name 1 : 12V Wiring
Component Description : 12V Wiring
Component Part Number : N/A

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

On April 15, 2025, Forest River's Office of Corporate Compliance ("OCC") was made aware that during a Corporate Standards Audit of the manufacturing plant, that these concerns had been discovered. OCC opened a research item.

On April 18, 2025, Forest River's Corporate Committee voted to recall.

Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to add over current protection the accent lamps, the awning, and the auto leveling system.

What is the Forest River Customer Service Phone Number? (574)
825-4995

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.
Please send the service invoice to the following address:

Aurora & Catalina
423 N Main St
Middlebury, IN 46540

How Remedy Component Differs from Recalled Component : Affected Component – 12V Wiring
Replacement Component - 10AMP blade fuse for the front accent lamp, 15AMP blade fuse holder in for the awning, and installing the wire to the 30AMP breaker side for the auto leveling.

The over current protection will now be correct for the wiring.

Identify How/When Recall Condition was Corrected in Production : During the week of April 15, 2025, the manufacturing plant changed the wire thickness to 10AWG. in production. Units in the yard were repaired with a 10AMP blade fuse for the front accent lamp. The manufacturing plant began adding a 15AMP blade fuse holder in production for the awning. The manufacturing plant began installing the wire to the 30AMP breaker side in production for the auto-leveling.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull

data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : MAY 28, 2025 - MAY 28, 2025
Planned Owner Notification Date : MAY 28, 2025 - MAY 28, 2025

* NR - Not Reported