

Part 573 Safety Recall Report

25V-281

Manufacturer Name : Grand Design RV, LLC

Submission Date : APR 30, 2025

NHTSA Recall No. : 25V-281

Manufacturer Recall No. : 910050



Manufacturer Information :

Manufacturer Name : Grand Design RV, LLC

Address : 11333 County Road 2
Middlebury IN 46540

Company phone : (574) 825-8000 x2015

Population :

Number of potentially involved : 121

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2024-2025 Momentum 320G, 325G, 344M, 250G, 351MS, 381MS, 392M, 395MS, 397THS, 398M, 399TH, 410TH, 414M, 415G

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined when a letter from MorRyde (the manufacturer of the defective part) notified us of the issue. A search was performed to identify the RVs we use this part on was identified to develop scope.

The recalled product differs from the non recalled product because the product not being recalled either hasn't been built (which they will be built with the new and correct part) or was placed on hold and fixed prior to shipping. T

Grand Design has identified 121 Momentum toy haulers affected by this recall.

Production Dates : MAY 07, 2024 - APR 16, 2025

VIN Range 1 : Begin : 573FM4634RBB02728 **End :** 573FM4220SBB04091 ☒ Not sequential

Description of Defect :

Description of the Defect : This is a bracket that is used on the side of an RV that has a receiver for a removable step assembly to clip into. This receiver is installed using a thread locking fluid to retain the assembly. It was found that there are parts that did not have this thread locking compound installed during assembly.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If this receiver becomes loose while being used, it can disengage from the fastener that is used to assemble it to the bracket and disconnect from the bracket allowing the step assembly to fall from its use location. This has the potential to cause personal injury if the step is being used when this happens.

Description of the Cause : Failure to use thread locking fluid during the MorRyde assembly process.

Identification of Any Warning that can Occur : The receiver on the bracket can be spun which can cause it to unscrew and detach from the installed bracket.

Involved Components :

Component Name 1 : Step Bracket

Component Description : Bracket - Mounting - Step - Folding Patio

Component Part Number : STP57-515

Supplier Identification :

Component Manufacturer

Name : MORryde International, Inc.

Address : 1966 Sterling Avenue
Elkhart Indiana 46516

Country : United States

Chronology :

4/24/2025 - Grand Design is provided a letter from MorRyde notifying of their equipment recall

4/29/2025 - Grand Design determines via purchase orders that the recalled component was used in production

4/30/2025 - Grand Design holds a product review committee meeting and votes to recall

Description of Remedy :

Description of Remedy Program :	Grand Design as the final stage manufacturer will release a Recall Notice (immediately following NHTSA assignment of a recall number) to all Grand Design dealers and Registered owners. Owners will be instructed to take their vehicle to the nearest Grand Design dealer to have their patio steps repaired at no charge. Owner's that have paid to have this service performed will be reimbursed by Grand Design for any expenses incurred relating to the defect.
How Remedy Component Differs from Recalled Component :	The Remedy components will be verified by MorRyde to have the required thread locking fluid.
Identify How/When Recall Condition was Corrected in Production :	Grand Design reviewed stock with MorRyde and quarantined any recalled stock. New stock supplied by MorRyde has been verified to meet their requirements for correction.

Recall Schedule :

Description of Recall Schedule :	Owners of affected vehicles will be notified by First Class mail that their vehicle is affected by this recall. In addition, we will post recall information electronically for consumer access. Dealers will be notified of the recall action (by First Class mail and electronically) and will be supplied with repair information and vehicle identification information.
Planned Dealer Notification Date :	MAY 15, 2025 - MAY 16, 2025
Planned Owner Notification Date :	MAY 22, 2025 - MAY 23, 2025

* NR - Not Reported