



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V320

**Manufacturer Name:** Winnebago Industries, Inc.

**Submission Date:** May 21, 2025

**NHTSA Recall No.:** 25V320

**Manufacturer Recall No.:** 196

### Manufacturer Information

### Population

**Manufacturer Name:** Winnebago Industries, Inc.

**Address:** PO BOX 152  
605 W. Crystal Lake Rd.  
Forest City IA, 50436

**Total number of potentially involved:** 57

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2023-2024 Winnebago Commercial Vehicle

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jan 08, 2024 - Mar 28, 2025

**Number of potentially involved:**

**Descriptive Information:**

The recall population was determined by identifying the production dates after receiving a letter from the manufacture of the recalled component (MORryde) regarding the issue.

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

This is a bracket that is used on the side of an RV that has a receiver for a removable step assembly to clip into. This receiver installed using a thread locking fluid to retain the assembly. It was found that there are parts that did not have this thread locking compound installed during assembly.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

If this receiver becomes loose while being used, it can disengage from the fastener that is used to assemble it to the bracket and disconnect from the bracket allowing the step assembly to fall from its

# Part 573 Safety Recall Report

**25V320**

use location. This has the potential to cause personal injury if the step is being used when this happens.

**Description of the cause:**

Failure to use thread locking fluid during the assembly process.

**Identification of any warning that can occur:**

The receiver on the bracket can be spun which can cause it to unscrew and detach from the installed bracket.

## Component Manufacturer

**Tier of Supplier:****Supplier Type:**

**Name:** MORryde International Inc.

**Address:** 1966 Sterling Avenue  
Elkhart IN, 46540

**Country:** United States

## Involved Components

**Component Name 1:** Step Bracket

**Component Description:** Bracket - Mounting - Step - Folding Patio

**Component Part Number:** STP57-515

## Chronology

Winnebago was notified by MORryde on 4/17/2025 and an internal hold was placed for units on campus. After reviewing purchase orders and build dates, scope was determined. An internal email notifying the Product Safety Committee of the decision to recall was sent 5/14/2025.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Replace, Repair, Inspect

# Part 573 Safety Recall Report

# 25V320

**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside

**Description of remedy program:**

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

**How remedy component differs from recalled component:**

The remedy components will be verified by MORryde to have the required thread locking fluid. Dealers will be instructed to inspect, repair, and replace, if necessary, the clip-on brackets.

**Identify how/when recall condition was corrected in production:**

Winnebago reviewed and quarantined any recalled stock. MORryde is supplying new stock that has been verified to meet their requirements.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

**Description of recall schedule:**

Recall schedule for notifications will be within the 60 day requirement.

**Planned Dealer Notification Date:** Jun 20, 2025 - Jun 20, 2025 ☐ No Dealers

**Planned Interim Owner Notification Date:** ☐ No Owners

**Planned Remedy Owner Notification Date:** Jun 27, 2025 - Jun 27, 2025 ☐ Phased Recall

**Date when VIN will be searchable:**