



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V406

Manufacturer Name: Foretravel, Inc.

Submission Date: Jun 16, 2025

NHTSA Recall No.: 25V406

Manufacturer Recall No.:

Manufacturer Information

Population

Manufacturer Name: Foretravel, Inc.

Address: 1221 N.W. Stallings Drive
Nacogdoches TX, 75964

Total number of potentially involved: 87

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2025 FORETRAVEL REALM PRESIDENTIAL

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Jul 12, 0023 - Dec 11, 0024

Number of potentially involved: 34

Descriptive Information:

Production of doors did not change from previous model year.

Vehicle 2: 2024-2024 FORETRAVEL REALM PRESIDENTIAL

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Jul 29, 0022 - Jan 02, 0024

Number of potentially involved: 41

Descriptive Information:

Production of doors did not change from previous model year.

Vehicle 3: 2026-2026 2026 Foretravel REALM PRESIDENTIAL

Product Category:

Part 573 Safety Recall Report

25V406**Product Type:****Fuel / Propulsion:** Compression Ignition Fuel**Production Dates:** Jun 04, 0024 - Jun 20, 0025**Number of potentially involved:** 12**Descriptive Information:**

Door design did not change from 24 or 25 MY.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Engine Door Vertical Grill Fins may show fatigue at the upper or lower attachment points.

FMVSS1:**FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

Fins could break loose and become projectiles and cause crash or death.

Description of the cause:

Engine vibration on vertical fins and no stress relief at cut lines

Identification of any warning that can occur:

Vertical fins can show cracks or cracking at upper and lower attachment points

Component Manufacturer

Tier of Supplier:**Supplier Type:** OEM**Name:** Foretravel INC.**Address:** 1221 NW Stallings Dr.
Nacogdoches TX, 75964**Country:** United States

Involved Components

Part 573 Safety Recall Report

25V406**Component Name 1:****Component Description:** Vertical finned doors**Component Part Number:** 162187D6 Support w/Relief 162188 D6 Support wo/Relief 162189 P6 Support w/ Relief**Component Name 2:** Driver(D6) or Passenger(P6) vertical finned doors**Component Description:** Vertical finned doors**Component Part Number:** 162190 P6 Support wo/relief

Chronology

Foretravel Motorcoach was made aware of the Driver and Passenger vertical fins on rear kick panels were cracking due to engine vibration and no support panel on the vertical fins on driver and passenger rear kick panels. On or around May 01, 2025 after an inspection Foretravel found there to be no stress reliefs on the panel and vertical fins. With further discussion and inspection Foretravel decided to Recall the involved Model Year coaches 2024, 2025 and some early model 2026 models. For fatigue and stress on vertical fins of rear doors, the vertical fins could become dislodged from the doors and become projectiles and cause a Crash or Death. Foretravel will inspect and install the Center Stiffener horizontally across the grill area to add stability to the individual vertical fins. If fins are missing then the door assembly will have to be replaced. If this occurs, then for Factory paint match the vehicle will have to return to Factory for paint. Unpainted primed doors can be shipped and installed. Then painted at a later date at Factory for customer convenience. All of the repairs will be performed at a no charge to the customer. A Service Bulletin Remedy will be sent to all authorized Service Dealers for necessary remedy action.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair, Replace**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside**Description of remedy program:**

Part 573 Safety Recall Report

25V406

Install center stiffener horizontally across the grill area to add stability to the individual vertical fins.

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Description of reimbursement program:

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

As soon as Service bulletin is complete and dealer letter ready those will be mailed out, and the same for owner notification letters. Will upload for approval if needed.

Planned Dealer Notification Date: Aug 04, 2025 - Aug 08, 2025 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Aug 04, 2025 - Aug 08, 2025 ☐ Phased Recall

Date when VIN will be searchable: