



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V408

Manufacturer Name: Winnebago Towable

Submission Date: Jun 17, 2025

NHTSA Recall No.: 25V408

Manufacturer Recall No.: CAM0000043

Manufacturer Information

Population

Manufacturer Name: Winnebago Towable

Address: 201 14th Street
Middlebury IN, 46540

Total number of potentially involved: 527

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2025 Winnebago Micro Minnie FLX

Product Category: Trailers

Product Type:

Fuel / Propulsion:

Production Dates: Oct 07, 2024 - Apr 07, 2025

Number of potentially involved: 13

Descriptive Information:

The recall population was determined by identifying the production dates.

Vehicle 2: 2025-2025 Winnebago Micro Minnie

Product Category: Trailers

Product Type:

Fuel / Propulsion:

Production Dates: Oct 07, 2024 - Apr 07, 2025

Number of potentially involved: 514

Descriptive Information:

The recall population was determined by identifying the production dates.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Part 573 Safety Recall Report

25V408

On certain Winnebago vehicles the cooktop flame may invert when the furnace is simultaneously running.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

There is potential when the cooktop and furnace are operated at the same time the cooktop burner flame may invert. This could lead to an increased risk of personal injury or fire.

Description of the cause:

The cooktop is installed where it is not sealed completely from the furnace.

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type: OEM

Name: Winnebago of Indiana

Address: 201 14th Street
Middlebury IN, 46567

Country: United States

Involved Components

Component Name 1: Cooktop

Component Description: 2 Burner Cooktop

Component Part Number: 282491

Chronology

In late January a recall was launched on the Winnebago 2025 Minnie model series due to the cooktop flame potentially inverting due to the furnace. On February 11 customer service received a complaint from a dealership on a 2025 Micro Minnie model experiencing the same concern. An investigation was subsequently opened.

Part 573 Safety Recall Report

25V408

During the investigation, the concern was replicated on a unit on campus, which led to production correcting the concern in early April. The Product Safety Committee met June 10, 2025, and decided the issue presented an unreasonable risk to safety and a recall was initiated. Winnebago is aware of 12 claims, 0 injuries, and no property damage as a result of this condition.

Related NHTSA Recall Number: This is an expansion to recall 25V029

Description of Remedy

Remedy Type: Repair

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How remedy component differs from recalled component:

The remedy will involve installing a panel to provide full separation between the cooktop and furnace.

Identify how/when recall condition was corrected in production:

Production began installing a separating shelf / panel to provide full separation between the cooktop and furnace.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Recall notifications will follow the 60 day requirement.

Planned Dealer Notification Date: Jul 18, 2025 - Jul 18, 2025 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Aug 15, 2025 - Aug 15, 2025 ☐ Phased Recall

Date when VIN will be searchable: