



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V464

Manufacturer Name: Forest River, Inc.

Submission Date: Jul 11, 2025

NHTSA Recall No.: 25V464

Manufacturer Recall No.: 48-1954

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 41

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 FOREST RIVER WESTBROOK

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: May 16, 2025 - Jul 08, 2025

Number of potentially involved: 4

Descriptive Information:

The scope was determined since the inception of the models.

Vehicle 2: 2026-2026 FOREST RIVER TRACER

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: May 16, 2025 - Jul 28, 2025

Number of potentially involved: 37

Descriptive Information:

The scope was determined since the inception of the models.

Defect / Noncompliance Description

Part 573 Safety Recall Report

25V464

Description of the defect or noncompliance:

The LP gas hose may be routed incorrectly to the furnace.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the LP gas hose rubs against the furnace edge, it may damage the LP gas hose, which may lead to a leak. This condition may lead to a fire, property damage or injury.

Description of the cause:

Manufacturing error.

Identification of any warning that can occur:

An operator may hear the LP gas alarm and/or smell LP gas.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: 48" LP gas hose

Component Description: 48" LP gas hose

Component Part Number: N/A

Chronology

On July 9, 2025, during a routine Corporate Standards Audit it was discovered that the LP gas hose was routed in a way that caused the hose to be against a sharp edge of the furnace.

Part 573 Safety Recall Report

25V464

On July 10, 2025, Forest River's Office of Corporate Compliance was made aware of the concern and opened a research item.

On July 11, 2025, Forest River's Corporate Committee voted to recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to replace the 48" LP gas hose with a 72" LP gas hose and route it correctly.

What is the Forest River Customer Service Phone Number? (574) 862-1025

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Prime Time Service Facility
200 SR 19 North (Building 2)
Wakarusa, IN 46573

How remedy component differs from recalled component:

Affected Component – 48" LP gas hose
Replacement Component – 72" LP gas hose

The LP gas hose will now be longer and routed correctly to not come in contact with the furnace.

Identify how/when recall condition was corrected in production:

During the week of July 10, 2025, the manufacturing plant installed a longer LP hose allowing for the appropriate clearance to not be damaged by the furnace.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Part 573 Safety Recall Report

25V464

Recall Schedule

Description of recall schedule:

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Aug 20, 2025 - Aug 20, 2025☐ No Dealers**Planned Interim Owner Notification Date:**☐ No Owners**Planned Remedy Owner Notification Date:** Aug 20, 2025 - Aug 20, 2025☐ Phased Recall**Date when VIN will be searchable:**