



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V496

**Manufacturer Name:** Premier Trailer Solutions LLC

**Submission Date:** Jul 31, 2025

**NHTSA Recall No.:** 25V496

**Manufacturer Recall No.:**

### Manufacturer Information

### Population

**Manufacturer Name:** Premier Trailer Solutions  
LLC

**Address:** 6691 West State Road 124  
Decatur IN, 46733

**Total number of potentially involved:** 3

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2024-2024 PREMIER TRALER POLE TRAILER

**Product Category:** Trailers

**Product Type:** Other

**Fuel / Propulsion:**

**Production Dates:** Mar 13, 2024 - Mar 13, 2024

**Number of potentially involved:** 2

**Descriptive Information:**

Lippert Axle determined that the recall population was 100% of the effected units.

The effected units were determined by axle serial numbers.

**Vehicle 2:** 2024-2024 PREMIER TRALER REEL TRAILER

**Product Category:** Trailers

**Product Type:** Other

**Fuel / Propulsion:**

**Production Dates:** Feb 29, 2024 - Feb 29, 2024

**Number of potentially involved:** 1

**Descriptive Information:**

Lippert Axle determined that the recall population was 100% of the effected units.

The effected units were determined by axle serial numbers.

# Part 573 Safety Recall Report

**25V496**

## Defect / Noncompliance Description

**Description of the defect or noncompliance:**

It has been decided that a substituted oil seal from a different vendor was improperly installed and over time will allow oil in the sealed hub to leak on to the braking system.

**FMVSS1:****FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

Under certain conditions during travel, the improperly installed seal may allow the oil to leak leading to an increased risk of vehicle crash.

**Description of the cause:**

The seal was mounted incorrectly.

**Identification of any warning that can occur:**

Visible oil leakage on the wheel.

## Component Manufacturer

**Tier of Supplier:** Tier 1**Supplier Type:** OEM**Name:** Lippert Axle**Address:** PO Box 2888  
Elkhart IN, 46515**Country:** United States

## Involved Components

**Component Name 1:** Hub Oil Seal**Component Description:** HD Oil Seal**Component Part Number:** 276712

## Chronology

# Part 573 Safety Recall Report

# 25V496

3/15/2024 - A representative from Lippert Axle notified us of the defect and gave us a list of the effected axle serial numbers.

3/15/2024 - We notified our customers of the effected units and brought all effected units back to our facility.

3/18/2024 - We began the recall by disassembling the effected axle hubs, removed the old, incorrectly installed seals, then reinstalled new seals correctly and reassembled the hubs. Lastly we added fresh gear oil to each hub.

2/20/2025 - The last of the trailers were remedied and returned to our customers.

0 injuries, warranty claims, field/service reports, or deaths associated with this recall.

**Related NHTSA Recall Number:** 24E021

## Description of Remedy

**Remedy Type:** Replace

**Consumer Advisories:** ☒ Do Not Drive ☐ Park Outside

**Description of remedy program:**

Effected units were disassembled, the hub seal replaced and put in the correct orientation and reassembled. After which fresh gear oil was added.

**How remedy component differs from recalled component:**

The remedy components were no different than the recalled components.  
The remedy components were simply installed in the correct orientation.

**Identify how/when recall condition was corrected in production:**

The recall took effect in production immediately and any effected axles that were not installed were put through the same recall program as axles on finished trailers.

## Reimbursement Plan

**Description of reimbursement program:**

Our customers will not incur any charges or added fees for the recall to be performed on their trailer. We will address any additional customer reimbursement requests on an as needed case by case basis. Lippert Axle reimbursed Premier Trailer Solutions LLC for the full amount of components and labor needed to perform this recall.

**Period of reimbursement:**

The reimbursement for this recall was received by Premier Trailer Solutions LLC within 30 days of the claim being submitted to Lippert Axle.

# Part 573 Safety Recall Report

**25V496****Costs to be reimbursed:**

The costs to be reimbursed to PTS from Lippert Axle is the total cost of the components and labor to perform this recall. Totaling \$1,735.99.

**Address for reimbursement claims:**

6691 W SR 124  
Decatur IN, 46733

## Recall Schedule

**Description of recall schedule:**

The owners of effected trailers were contacted via email within 3 business days of the recall being posted by Lippert Axle.

2/20/2025 - All trailers involved with this recall have been remedied. No Owner Letter Required.

**Planned Dealer Notification Date:**☒ No Dealers**Planned Interim Owner Notification Date:**☒ No Owners**Planned Remedy Owner Notification Date:**☐ Phased Recall**Date when VIN will be searchable:**