



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V547

**Manufacturer Name:** Keystone RV Company

**Submission Date:** Aug 25, 2025

**NHTSA Recall No.:** 25V547

**Manufacturer Recall No.:** 25-472

### Manufacturer Information

### Population

**Manufacturer Name:** Keystone RV Company

**Address:** PO Box 2000  
2642 Hackberry Drive  
Goshen IN, 46527

**Total number of potentially involved:** 148

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2026-2026 KEYSTONE SPRINGDALE

**Product Category:** Trailers

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Jun 25, 2025 - Jul 17, 2025

**Number of potentially involved:** 77

**Descriptive Information:**

Model(s): Springdale 1310RK, Affected model with pivot bunk brackets

**Vehicle 2:** 2026-2026 KEYSTONE HIDEOUT

**Product Category:** Trailers

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** May 23, 2025 - Jul 24, 2025

**Number of potentially involved:** 71

**Descriptive Information:**

Model(s): Hideout 131RK, Affected model with pivot bunk brackets

### Defect / Noncompliance Description

# Part 573 Safety Recall Report

**25V547****Description of the defect or noncompliance:**

It has been decided that the vehicles in the recall population may have defective pivot bunk hardware.

**FMVSS1:****FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

Under certain circumstances during use, the bunk brackets may bend or break, this can lead to an increased risk of personal injury.

**Description of the cause:**

The pivot bunk brackets may have insufficient welds around the extension tube.

**Identification of any warning that can occur:**

Bunk brackets may appear bent or broken.

## Component Manufacturer

**Tier of Supplier:****Supplier Type:****Name:** Rock Run Industries**Address:** 11635 W 600 S  
Millersburg IN, 46543**Country:** United States

## Involved Components

**Component Name 1:** Bracket - Bunk - 2" x 1 3/4" x 3/4" - Black**Component Description:** Bunk bracket for pivot bunk**Component Part Number:** 768063

## Chronology

08/07/2025 – Report was made.

08/07/2025 – Investigation opened. All affected units not shipped were put on hold and inspected and repaired in the yard.

# Part 573 Safety Recall Report

# 25V547

08/18/2025 – There are no warranty claims for this issue at this time.

08/18/2025 – Keystone Safety Committee reviewed the information and concluded that the data reviewed indicated a unanimous vote for a voluntary recall. Investigation called for to determine affected unit range.

08/19/2025 – Investigation concluded, and scope completed.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Replace

**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside

**Description of remedy program:**

The remedy is to replace the bunk brackets with new modified brackets.

**How remedy component differs from recalled component:**

Replacement Bunk brackets have reinforced welds. Bunk brackets, Bracket - Bunk - 2" x 1 3/4" x 3/4" - KRV # 768063,

**Identify how/when recall condition was corrected in production:**

Units were quarantined, inspected then repaired as indicated by inspection.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

**Description of recall schedule:**

Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

**Planned Dealer Notification Date:** Oct 14, 2025 - Oct 14, 2025 ☐ No Dealers

**Planned Interim Owner Notification Date:** ☐ No Owners

**Planned Remedy Owner Notification Date:** Oct 14, 2025 - Oct 14, 2025 ☐ Phased Recall

# Part 573 Safety Recall Report

**25V547**

Date when VIN will be searchable: