

## II. Vehicles Involved

Approximately 3,908 MY 2019 Audi A6 and Audi A7 vehicles manufactured between July 27, 2018, and November 6, 2018, are potentially involved.

## III. Noncompliance

Volkswagen explains that the noncompliance is that a small number of the affected vehicles may have a European-specification brake fluid reservoir cap instead of the one required for the North American/United States market as required by paragraph S5.4.3 of FMVSS No. 135. Specifically, the subject brake fluid reservoir caps may not include the required warning label.

## IV. Rule Requirements

Paragraph S5.4.3 of FMVSS 135, includes the requirements relevant to this petition. Each vehicle equipped with hydraulic brakes shall have a brake fluid warning statement that reads as follows, in letters at least 3.2 mm ( $\frac{1}{8}$  inch) high: "WARNING: Clean filler cap before removing. Use only \_\_\_\_\_ fluid from a sealed container." (Inserting the recommended type of brake fluid as specified in 49 CFR 571.116, e.g., "DOT 3." The lettering shall be permanently affixed, engraved, or embossed, located so as to be visible by direct view, either on or within 100 mm (3.94 inches) of the brake fluid reservoir filler plug or cap, and of a color that contrasts with its background, if it is not engraved or embossed.

## V. Summary of Petition

Volkswagen described the subject noncompliance and stated its belief that the noncompliance is inconsequential as it relates to motor vehicle safety.

In support of its petition, Volkswagen submitted the following reasoning:

1. The brake fluid cap shows clearly the specification of brake fluid required.
2. The brake fluid cap conforms to the requirements of ISO9128:2006, which is a requirement of UN-ECE Regulations 13 and 13h.

3. Volkswagen asserts that NHTSA has previously granted the following petitions to accept ISO symbols in the absence of FMVSS labelling.

(a) Jaguar Land Rover petition regarding light vehicle brake systems, re: Brake fluid cap (84 FR 13095, 13098);

(b) Ford petition regarding controls and displays including brake system-related telltales (78 FR 69931, 69932); and

(c) Hyundai petition regarding lower anchorage identification (73 FR 38290, 38291).

4. Volkswagen states that the brake fluid cap provides clear symbols including one for caution and one for

referring to owner manual instructions. The manual indicates the proper brake fluid specification for use in the vehicle.

5. Service to the brake system involving an exchange of the brake fluid is not a standard maintenance activity for an owner/user. Repairs to the brake system, which includes evacuating and refilling the brake fluid, requires basic technical knowledge regarding the brake system and should be performed by a trained technician.

6. Volkswagen has not received any field or customer complaints related to this condition.

7. Volkswagen has not received notification of any accidents or injuries resulting from this issue.

Volkswagen's complete petition and all supporting documents are available by logging onto the Federal Docket Management System (FDMS) website at <https://www.regulations.gov> and by following the online search instructions to locate the docket number as listed in the title of this notice.

Volkswagen concluded by expressing the belief that the subject noncompliance is inconsequential as it relates to motor vehicle safety, and that its petition to be exempted from providing notification of the noncompliance, as required by 49 U.S.C. 30118, and a remedy for the noncompliance, as required by 49 U.S.C. 30120, should be granted.

NHTSA notes that the statutory provisions (49 U.S.C. 30118(d) and 30120(h)) that permit manufacturers to file petitions for a determination of inconsequentiality allow NHTSA to exempt manufacturers only from the duties found in sections 30118 and 30120, respectively, to notify owners, purchasers, and dealers of a defect or noncompliance and to remedy the defect or noncompliance. Therefore, any decision on this petition only applies to the subject vehicles that Volkswagen no longer controlled at the time it determined that the noncompliance existed. However, any decision on this petition does not relieve vehicle distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant vehicles under their control after Volkswagen notified them that the subject noncompliance existed.

**Authority:** (49 U.S.C. 30118, 30120; Delegations of authority at 49 CFR 1.95 and 501.8).

### Otto G. Matheke III,

Director, Office of Vehicle Safety Compliance.

[FR Doc. 2019-17948 Filed 8-20-19; 8:45 am]

**BILLING CODE 4910-59-P**

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA-2019-0040; Notice 1]

### Kia Motors America, Inc, Receipt of Petition for Decision of Inconsequential Noncompliance

**AGENCY:** National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT).

**ACTION:** Receipt of petition.

**SUMMARY:** Kia Motors America, Inc., and Kia Motors Corporation (collectively "Kia"), has determined that certain Model year (MY) 2020 Kia Telluride motor vehicles do not fully comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 110, *Tire Selection and Rims and Motor Home/Recreation Vehicle Trailer Load Carrying Capacity Information for Motor Vehicles with a GVWR of 4,536 kilograms (10,000 pounds) or less*. Kia filed a noncompliance report dated April 12, 2019, and subsequently petitioned NHTSA on April 18, 2019, for a decision that the subject noncompliance is inconsequential as it relates to motor vehicle safety. This notice announces receipt of Kia's petition.

**DATES:** Send comments on or before September 20, 2019.

**ADDRESSES:** Interested persons are invited to submit written data, views, and arguments on this petition. Comments must refer to the docket and notice number cited in the title of this notice and may be submitted by any of the following methods:

- **Mail:** Send comments by mail addressed to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver comments by hand to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590. The Docket Section is open on weekdays from 10 a.m. to 5 p.m. except for Federal Holidays.

- **Electronically:** Submit comments electronically by logging onto the Federal Docket Management System (FDMS) website at <https://www.regulations.gov/>. Follow the online instructions for submitting comments.

- Comments may also be faxed to (202) 493-2251.

Comments must be written in the English language, and be no greater than

15 pages in length, although there is no limit to the length of necessary attachments to the comments. If comments are submitted in hard copy form, please ensure that two copies are provided. If you wish to receive confirmation that comments you have submitted by mail were received, please enclose a stamped, self-addressed postcard with the comments. Note that all comments received will be posted without change to <https://www.regulations.gov>, including any personal information provided.

All comments and supporting materials received before the close of business on the closing date indicated above will be filed in the docket and will be considered. All comments and supporting materials received after the closing date will also be filed and will be considered to the fullest extent possible.

When the petition is granted or denied, notice of the decision will also be published in the **Federal Register** pursuant to the authority indicated at the end of this notice.

All comments, background documentation, and supporting materials submitted to the docket may be viewed by anyone at the address and times given above. The documents may also be viewed on the internet at <https://www.regulations.gov> by following the online instructions for accessing the dockets. The docket ID number for this petition is shown in the heading of this notice.

DOT's complete Privacy Act Statement is available for review in a **Federal Register** notice published on April 11, 2000 (65 FR 19477-78).

#### SUPPLEMENTARY INFORMATION:

##### I. Overview

Kia has determined that certain MY 2020 Kia Telluride motor vehicles do not fully comply with paragraphs S4.3.3 of FMVSS No. 110, *Tire Selection and Rims and Motor Home/Recreation Vehicle Trailer Load Carrying Capacity Information for Motor Vehicles with a GVWR of 4,536 kilograms (10,000 pounds) or less* (49 CFR 571.110). Kia filed a noncompliance report dated April 12, 2019, pursuant to 49 CFR part 573, *Defect and Noncompliance Responsibility and Reports*, and subsequently petitioned NHTSA on April 18, 2019, for an exemption from the notification and remedy requirement of 49 U.S.C Chapter 301 on the basis that this noncompliance is inconsequential as it relates to motor vehicle safety pursuant to 49 U.S.C. 30118(d) and 30120(h) and 49 CFR part 556, *Exemption for Inconsequential Defect or Noncompliance*.

This notice of receipt of Kia's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

##### II. Vehicles Involved

Approximately 8,773 MY 2020 Kia Telluride motor vehicles manufactured between January 10, 2019, and March 27, 2019, are potentially involved.

##### III. Noncompliance

Kia explains that the noncompliance is that the subject vehicles are equipped with Part 567 certification labels that are missing the value for the rim size as required by paragraph S4.3.3 of FMVSS No. 110. Specifically, the subject vehicles are equipped with 7.5Jx20 or 7.5Jx18 rims, however, the part 567 certification labels are missing the "20" or "18" inches after the "7.5Jx." The certification labels also contain a typo. The "i" in "psi" is missing in the section of the label, which identifies the corresponding tire inflation pressure.

##### IV. Rule Requirements

Paragraphs S4.3.3 of FMVSS No. 110 provide the requirements relevant to this petition. Each vehicle must show the size designation and, if applicable, the type designation of rims (not necessarily those on the vehicle) appropriate for the tire and appropriate for use on that vehicle, including the tire installed as original equipment on the vehicle by the vehicle manufacturer, after each GAWR listed on the certification label required by § 567.4 or § 567.5 of this chapter. This information should be in English, letters block capitals and numerals not less than 2.4 millimeters high and in the following format (*Truck Example- Suitable Tire-Rim Choice*):

GVWR: 2,441 kilograms (5381 pounds).

GAWR: Front-1,299 kilograms (2,864 pounds) with P265/70R16 tires, 16x8.0 rims at 248 kPa (36 psi) cold single.

GAWR: Rear-1,299 kilograms (2,864 pounds) with P265/70R16 tires, 16x8.00 rims at 248 kPa (36 psi) cold single.

##### V. Summary of Petition

Kia described the subject noncompliance and stated its belief that the noncompliance is inconsequential as it relates to motor vehicle safety.

In support of its petition, Kia contends that the information missing from the label is a minor omissions without adverse safety implications because the information is readily available from other sources.

1. Kia states that FMVSS No. 110 paragraph S4.3(d) requires that the tire and loading information placard state the tire size designations for the tires installed on the vehicle at the time of first purchase. On the affected vehicles, the FMVSS No. 110 tire and loading label (which is located directly adjacent to the certification label on the "B" pillar), contains the correct tire size dimensions, recommended cold tire inflation pressure, and vehicle capacity weight.

2. Kia also noted that FMVSS No. 110, paragraph S4.3(f), also requires the tire and loading placard to state "See Owner's Manual for Additional Information." The Owner's Manual for the 2020 Telluride provides the wheel rim and tire information, which the owner can easily refer to confirm the correct tire pressure.

3. The consumer can also check the tire rims installed on the vehicle to determine the correct wheel rim size needed. Kia noted that FMVSS No. 110, paragraph S.4.4.2(b), requires each rim to be marked to identify the rim size. The affected vehicles meet the requirements of this section.

4. Kia is not aware of any accidents or injuries related to the omitted tire rim size information or typographical errors on the certification label, nor has it received contact from vehicle owners regarding this issue.

5. Kia says NHTSA has previously granted similar petitions for inconsequential noncompliance with FMVSS No. 110, paragraph S4.3.3, with respect to missing or incorrect information on the certification label. *See e.g., Hyundai-Ki America Technical Center, Inc., Grant of Petition for Decision of Inconsequential Noncompliance*, 78 FR 38445 (June 26, 2013) [granting petition where certification labels on certain MY 2012 Hyundai Veracruz vehicles were missing tire size designation information entirely]; *Chrysler Group, LLC, Grant of Petition for Decision of Inconsequential Noncompliance*, 78 FR 38443 (June 26, 2013) [granting petition where certification labels in certain MY 2011 Chrysler Town and Country and Dodge Grand Caravan vehicles incorrectly identified tire size]; and *BMW of North America, LLC., Grant of Petition for Decision of Inconsequential Noncompliance*, 78 FR 76408 (December 17, 2013) [granting petition where certification labels in certain MGMT7099DMY 2012 X3 SAV vehicles contained incorrect tire and rim information for the tires and rims installed as original equipment].

Kia concludes that the subject noncompliance is inconsequential as it

relates to motor vehicle safety, and that its petition to be exempted from providing notification of the noncompliance, as required by 49 U.S.C. 30118, and a remedy for the noncompliance, as required by 49 U.S.C. 30120, should be granted.

NHTSA notes that the statutory provisions (49 U.S.C. 30118(d) and 30120(h)) that permit manufacturers to file petitions for a determination of inconsequentiality allow NHTSA to exempt manufacturers only from the duties found in sections 30118 and 30120, respectively, to notify owners, purchasers, and dealers of a defect or noncompliance and to remedy the defect or noncompliance. Therefore, any decision on this petition only applies to the subject vehicles that Kia no longer controlled at the time it determined that the noncompliance existed. However, any decision on this petition does not relieve vehicle distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant vehicles under their control after Kia notified them that the subject noncompliance existed.

**Authority:** (49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.95 and 501.8).

**Otto G. Matheke III,**

*Director, Office of Vehicle Safety Compliance.*

[FR Doc. 2019-18030 Filed 8-20-19; 8:45 am]

**BILLING CODE 4910-59-P**

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA-2019-0029; NHTSA-2019-0030; Notice 1]

#### Mack Trucks, Inc., and Volvo Trucks North America, Receipt of Petitions for Decision of Inconsequential Noncompliance

**AGENCY:** National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT).

**ACTION:** Receipt of petitions.

**SUMMARY:** Mack Trucks Inc., (Mack) and Volvo Trucks North America (Volvo) have determined that certain model year (MY) 2014–2019 Mack Trucks and certain MY 2014–2019 Volvo Trucks do not comply with Federal Motor Vehicle Safety Standard (FMVSS) 101, *Controls and Displays*. Both Mack and Volvo filed noncompliance reports dated August 16, 2018, and later amended them on August 23, 2018, and June 2, 2019. Both Mack and Volvo

subsequently petitioned NHTSA on October 9, 2018, and later amended their petition on May 29, 2019, for a decision that the subject noncompliance is inconsequential as it relates to motor vehicle safety. This notice announces receipt of both Mack and Volvo's petitions.

**DATES:** Send comments on or before September 20, 2019.

**ADDRESSES:** Interested persons are invited to submit written data, views, and arguments on this petition. Comments must refer to the docket and notice number cited in the title of this notice and submitted by any of the following methods:

- **Mail:** Send comments by mail addressed to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- **Hand Delivery:** Deliver comments by hand to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590. The Docket Section is open on weekdays from 10 a.m. to 5 p.m. except for Federal Holidays.
- **Electronically:** Submit comments electronically by logging onto the Federal Docket Management System (FDMS) website at <https://www.regulations.gov/>. Follow the online instructions for submitting comments.
- Comments may also be faxed to (202) 493-2251.

Comments must be written in the English language, and be no greater than 15 pages in length, although there is no limit to the length of necessary attachments to the comments. If comments are submitted in hard copy form, please ensure that two copies are provided. If you wish to receive confirmation that comments you have submitted by mail were received, please enclose a stamped, self-addressed postcard with the comments. Note that all comments received will be posted without change to [https://www.regulations.gov](https://www.regulations.gov/), including any personal information provided.

All comments and supporting materials received before the close of business on the closing date indicated above will be filed in the docket and will be considered. All comments and supporting materials received after the closing date will also be filed and will be considered to the fullest extent possible.

When the petition is granted or denied, notice of the decision will also be published in the **Federal Register**

pursuant to the authority indicated at the end of this notice.

All comments, background documentation, and supporting materials submitted to the docket may be viewed by anyone at the address and times given above. The documents may also be viewed on the internet at <https://www.regulations.gov> by following the online instructions for accessing the dockets. The docket ID number for this petition is shown in the heading of this notice.

DOT's complete Privacy Act Statement is available for review in a **Federal Register** notice published on April 11, 2000 (65 FR 19477-78).

#### SUPPLEMENTARY INFORMATION:

##### I. Overview

Mack and Volvo have determined that certain MY 2014–2019 Mack Trucks and MY 2014–2019 Volvo Trucks do not comply with Table 2 of FMVSS 101, *Controls and Displays* (49 CFR 571.101). Both Mack and Volvo filed noncompliance reports dated August 16, 2018, and later amended them on August 23, 2018, and June 2, 2019, pursuant to 49 CFR part 573, *Defect and Noncompliance Responsibility and Reports*. Both Mack and Volvo subsequently petitioned NHTSA on October 9, 2018, and later amended their petitions on May 29, 2019, for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential as it relates to motor vehicle safety, pursuant to 49 U.S.C. 30118(d) and 30120(h) and 49 CFR part 556, *Exemption for Inconsequential Defect or Noncompliance*.

This notice of receipt of Mack's and Volvo's petitions is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of their petitions.

##### II. Vehicles Involved

Approximately 95,000 MY 2014–2019 Mack Anthem, Granite, LR, Pinnacle, TerraPro, and Titan Trucks, manufactured between September 1, 2013, and August 13, 2018, are potentially involved.

Approximately 130,000 MY 2014–2019 Volvo VAH, VHD, VNL, VNM, VNR, VNX, and VT Trucks, manufactured between September 1, 2013, and August 13, 2018, are potentially involved.

##### III. Noncompliance

Mack and Volvo explained that the noncompliance is that the Low Brake Air Pressure telltale for air brake