

Part 573 Safety Recall Report

19V-751

Manufacturer Name : Vac-Tron Equipment, LLC**Submission Date :** OCT 18, 2019**NHTSA Recall No. :** 19V-751**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Vac-Tron Equipment, LLC

Number of potentially involved : NR

Address : 27137 South Hwy 33

Estimated percentage with defect : NR

Okahumpka FL 34762

Company phone : 728-2222

Vehicle Information :

Vehicle 1 : 2015-2019 Vac-Tron LP873SDT Heavy

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All 873 Trailer vacuum excavator models.

Production Dates : JAN 01, 2015 - OCT 18, 2019

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : Under certain loaded conditions and at speeds greater than 40 mph the towed trailer may experience sway.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Potential loss of vehicle control causing an accident.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported