Part 573 Safety Recall Report

Manufacturer Name :	KZRV, L.P.
Submission Date :	JAN 15, 2021
NHTSA Recall No. :	21V-013
Manufacturer Recall No. :	KZ-2021-01

Manufacturer Information :

Manufacturer Name :	KZRV, L.P.
Address :	0985 N 900W
	Shipshewana IN 46565
Company phone :	800-768-4016x154/153

Vehicle Information :

Vehicle 1 : Vehicle Type :	2021-2021 KZ R TRAILERS	V Sportsmen Cl	lassic		
Body Style :					
Power Train :	NR				
Descriptive Information :	Circuits run with	a $14/2$ wire an	re incori	rectly protected by a 20 an	np circuit breaker.
Production Dates :	OCT 07, 2020 - JA	AN 11, 2021			
VIN Range 1:	Begin :	NR	End :	NR	Not sequential
Vehicle 2:	2021-2021 KZ R	V Escape			
Vehicle Type :	TRAILERS				
Body Style :					
Power Train :	NR				
Descriptive Information :	Circuits run with	a 14/2 wire a	re incori	rectly protected by a 20 an	np circuit breaker.
Production Dates :	OCT 07, 2020 - JA	AN 11, 2021			
VIN Range 1:	Begin :	NR	End :	NR	□ Not sequential
Vehicle 3:	2021-2021 KZ R	V Sonic			
Vehicle Type :	TRAILERS				
Body Style :					
Power Train :	NR				
Descriptive Information :	Circuits run with	a 14/2 wire ar	re incor	rectly protected by a 20 an	np circuit breaker.
Production Dates :	OCT 07, 2020 - JA	AN 11, 2021			
VIN Range 1:	Begin :	NR	End :	NR	Not sequential



Number of potentially involved : 806 Estimated percentage with defect : 95 %

Population :

21V-013

Description of Defect :

Description of the Defect :	The microwave circuits are run with $14/2$ wire and connected to a 20 amp circuit breaker instead of a 15 amp circuit breaker.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	If an issue develops, the circuit breaker will not trip and provide adequate protection to the wiring.
Description of the Cause :	Production error.
Identification of Any Warning that can Occur :	None.

Involved Components :

Component Description :NRComponent Part Number :NR	Component Name 1:	NR
Component Part Number : NR	Component Description :	NR
	Component Part Number :	NR

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

1/12/2021 - RVIA performed a code inspection of Plant 4 and found the 14/2 wired microwave circuit is incorrectly protected with a 20 amp circuit breaker. All product from Plant 4 in the yard is placed on hold. 1/13/2021 - All units in the yard are inspected and found to have the same issue. These units have the circuit breakers changed to 15 amp circuit breakers.

1/14/2021 - Investigation finds a change in the wiring occurred in October 2020.

1/15/2021 - A safety committee review determines that a recall should be issued.

Part 573 Safety Recall Report

21V-013

Description of Remedy :	
Description of Remedy Program :	Replace the 20 amp circuit breaker with a 15 amp circuit breaker.
How Remedy Component Differs from Recalled Component :	NR
	All wire circuits are paired with the proper circuit breakers.
was Corrected in Production :	
Recall Schedule :	KZ will notify the dealers and owners of these recreational vehicles by letter. A final copy of the owner letter and dealer repair instructions will be provided to NHTSA.
Recall Schedule :	letter. A final copy of the owner letter and dealer repair instructions will be provided to NHTSA.

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573