

September 28, 2022

Docket Management Facility  
National Highway Traffic Safety Administration  
Room W12-140, West Building, Ground Floor,  
1200 New Jersey Avenue, SE.,  
Washington, DC 20590  
Docket No. NHTSA 2009-0069

**Re: Revision: 2022MY Kia EV6 Parts Marking Locations (49 C.F.R. 541)  
Docket No. NHTSA 2009-0069**

Dear Docket Management Facility,

Pursuant to the requirements specified in 49 C.F.R. Part 541, Federal Motor Vehicle Theft Prevention Standard, the Hyundai-Kia America Technical Center, Inc. ("HATCI") is submitting the required parts marking locations on behalf of the Kia Corporation. HATCI is submitting a revised report to update the parts marking locations for the front fender. This report corrects the report that was submitted on May 5, 2022.

Should you have any questions, please feel free to contact me at (734) 337-2213 or [RWillard@hatci.com](mailto:RWillard@hatci.com).

Sincerely,



---

Ric Willard  
Department Head  
Regulation & Certification Department  
6800 Geddes Rd.  
Superior Township, MI 48198