Part 573 Safety Recall Report

Manufacturer Name :	Forest River, Inc.
Submission Date :	JUN 28, 2024
NHTSA Recall No. :	24V-490
Manufacturer Recall No. :	72-1805

Manufacturer Information :

Manufacturer Name : Forest River, Inc. Address : 55470 CR 1 P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1: 2024-2025 Forest River Inc. Salem Travel Trailers Vehicle Type: TRAILERS Body Style: OTHER Power Train: NR Descriptive Information: 2024 SALEM SMT167RBK 60 2024 SALEM SMT167RBKX 32 2024 SALEM SMT167RBKX 2024 SALEM SMT1797DBK 148 2024 SALEM SMT179DBK 69 2025 SALEM SMT179DBKX 69 2025 SALEM SMT179DBKX 2 Production Dates: JUL 18, 2023 -JUN 27, 2024 VIN Brance Forin : NR					
Body Style :OTHERPower Train :NRDescriptive Information :2024SALEM :SMT167RBK6020242024 :SALEM :SMT167RBKX :322024 :SALEM :SMT167RBKX :322024 :SALEM :SMT167RBKX :322024 :SALEM :SMT179DBK :1482024 :SALEM :SMT179DBK :1482024 :SALEM :SMT179DBKX :692025 :SALEM :SMT179DBKX :692025 :SALEM :SMT179DBKX :2	Vehicle 1:	2024-2025 Fore	st River Inc. Sa	lem Travel Trailers	
Power Train :NRDescriptive Information :2024 SALEM SMT167RBK 60 2024 SALEM SMT167RBKX 32 2024 SALEM SMT167RBKX 32 2024 SALEM SMT179DBK 148 2024 SALEM SMT179DBKX 69 2025 SALEM SMT179DBKX 69 2025 SALEM SMT179DBKX 2Production Dates :JUL 18, 2023 - JUN 27, 2024	Vehicle Type :	TRAILERS			
Descriptive Information :2024 SALEM SMT167RBK 60 2024 SALEM SMT167RBKX 32 2024 SALEM SMT179DBK 148 2024 SALEM SMT179DBKX 69 2025 SALEM SMT179DBKX 69 2025 SALEM SMT179DBKX 2025 SALEM SMT179DBKX 2025 SALEM SMT179DBKX 2025 SALEM SMT179DBKX 2025 SALEM SMT179DBKX 2025Production Dates :UL 18, 2023 - JUN 27, 2024	Body Style :	OTHER			
SALEM SMT167RBK 60 2024 SALEM SMT167RBKX 32 2024 SALEM SMT179DBK 148 2024 SALEM SMT179DBK 148 2024 SALEM SMT179DBKX 69 2025 SALEM SMT179DBKX 2 Production Dates : JUL 18, 2023 - JUN 27, 2024	Power Train :	NR			
2 Production Dates : JUL 18, 2023 - JUN 27, 2024	Descriptive Information :	SALEM SMT167RBK 60 2024 SALEM SMT167RBKX 32 2024 SALEM SMT179DBK 148 2024 SALEM SMT179DBKX 69 2025			
Production Dates : JUL 18, 2023 - JUN 27, 2024					
		2			
VIN Panga 1 · Regin · NP End · NP	Production Dates : JUL 18, 2023 - JUN 27, 2024				
In the sequential not sequential	VIN Range 1:		NR	End: NR	☐ Not sequential



Number of potentially involved : 573 Estimated percentage with defect : 100 %

Population :

24V-490

Part 573 Safety Recall Report

24V-490

Page 2

Vehicle 2 : Vehicle Type : Body Style : Power Train :	TRAILERS OTHER	orest River I	nc. Wildwood Travel 🛛	Frailers	
Descriptive Information :		iodel year 2 K	d by manufacturing re 024 to current.	ecords of when th	e window was
Production Dates :	IIII 18 2023.	IUN 27-203	24		
VIN Range 1:1		NR	End: NR		□ Not sequential
Description of Defect :					
Description of the Defec FMVSS FMVSS	1: NR	hicles may r	not have a secondary r	neans of egress.	
Description of the Safety Ris Description of the Caus	to the entr	y door, the	onto the entry door or vehicle may pose pers		
Identification of Any Warning that can Occur :					
Involved Components :					

The information contained in this report was submitted pursuant to 49 CFR $\S573$

Part 573 Safety Recall Report

Component Name 1 : Egress Window Component Description : Egress Window

Component Part Number : N/A

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

On June 26, 2024, during a routine Corporate Standards Audit, it was discovered that manufacturing was not installing a secondary means of egress. The same day, the Corporate Standards Manager notified Forest River's Office of Corporate Compliance ("OCC"). OCC opened a research item.

On June 28, 2024, Forest River's Corporate Recall Committee voted to recall.

The information contained in this report was submitted pursuant to 49 CFR §573

Description of Remedy :	
Description of Remedy Program :	Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to install an egress window.
	What is the Forest River Customer Service Phone Number? (574) 534-3167
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	Salem & Wildwood Forest River, Inc. Attn: WARRANTY MANAGER 1803 Century Drive Goshen, IN 46528
	Affected Component – Egress Window The vehicle will now be equipped with an egress window for a secondary means of escape.
·	During the week of June 26, 2024, the manufacturing plant stopped shipping the model and began installing a secondary means of egress.
Recall Schedule :	
	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
Planned Dealer Notification Date : Planned Owner Notification Date :	

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573