# **Part 573 Safety Recall Report**

Manufacturer Name :	Forest River, Inc.
Submission Date :	AUG 22, 2024
NHTSA Recall No. :	24V-629
Manufacturer Recall No. :	69-1833

### **Manufacturer Information :**

Manufacturer Name : Forest River, Inc. Address : 55470 CR 1 P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

### **Vehicle Information :**

Vehicle 1 : Vehicle Type :		t River Inc. Sale	em SBF325RL Fifth Wheels	
Body Style :				
Power Train :				
Descriptive Information :	The scope is deter 2024 SALEM SBF325RL 53 2025 SALEM SBF325RL 9	rmined by the i	nception of the model, to cur	rent date.
		10.1.4.0004		
Production Dates : VIN Range 1 : 2			End: NR	☐ Not sequential
			End : NR	☐ Not sequential



OMB Control No.: 2127-0004



Number of potentially involved : 132 Estimated percentage with defect : 100 %

**Population :** 

# Part 573 Safety Recall Report

Page 2

Vehicle Type : 7 Body Style : Power Train : 1 Descriptive Information : 7	TRAILERS OTHER NR		ldwood WBF325RL Fifth W	
Production Dates :				
VIN Range 1:B	legin : N	R	End: NR	☐ Not sequential
Description of Defect : Description of the Defect FMVSS 1 FMVSS 2 Description of the Safety Risk Description of the Cause Identification of Any Warnin that can Occur	<ul> <li>I: NR</li> <li>2: NR</li> <li>4: If the tire contaction lead to loss of version of the tire contaction of</li></ul>	cts the chass ehicle contro	-	
Involved Components :				
Component Name 1:	Slideout Head			
Component Description :	Slideout Head			
Component Part Number :	N/A			
Supplier Identification :			as submitted pursuant to 49 CFF	

#### **Component Manufacturer**

Name : NR Address : NR NR Country : NR

#### Chronology :

On August 13, 2024, Forest River's Office of Corporate Compliance ("OCC") was notified by the manufacturing plant of a single vehicle in which the tire may contact a chassis component.

On August 14, 2024, OCC opened a research item into the concern. OCC asked the division to get the dimension between the tire and the chassis components. Additionally, OCC asked the division to reach out to dealers with stock inventory to inspect for a possible concern.

Between August 16 through August 20, the manufacturing plant began receiving data points back from multiple dealers.

On August 22, 2024, Forest Rivers Corporate Committee voted to recall.

### **Description of Remedy :**

- •	
Description of Remedy Program :	The remedy for this recall is under development. An amendment will be filed once the remedy is available.
	What is the Forest River Customer Service Phone Number? (574) 534-3167
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	Salem/Wildwood
	Forest River, Inc.
	Attn: WARRANTY MANAGER
	1803 Century Drive Goshen, IN 46528
	GUSHCH, IN 40320
How Remedy Component Differs	Affected Component – Axle Hangers
The information	contained in this report was submitted pursuant to 49 CFR §573

from Recalled Component :	The new axle hangers and riser kit will now allow the desired distance between the tires and the chassis components under a full jounce of the vehicle.
	The week of August 19, 2024, the manufacturing plant had a riser installed, lifting the vehicle 3 inches, allowing clearance of the tire and chassis components.
Recall Schedule :	
	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
	suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573