

Part 573 Safety Recall Report

24V-883

Manufacturer Name : Forest River, Inc.**Submission Date :** NOV 22, 2024**NHTSA Recall No. :** 24V-883**Manufacturer Recall No. :** 20-1873**Manufacturer Information :****Population :**

Manufacturer Name : Forest River, Inc.

Number of potentially involved : 2

Address : 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1 : 2025-2025 Forest River Inc. Cedar Creek CRT40RDE Fifth Wheels

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The scope was determined since the inception of the model.

2025 CEDAR CREEK CRT40RDE 2

Grand Total

Production Dates : OCT 11, 2024 - NOV 19, 2024

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The axles and tire may be inadequate for the vehicle.

FMVSS 1 : 120 - Wheels and rims- other than passenger cars

FMVSS 2 : NR

Description of the Safety Risk : Axle and tires not adequately sized for the vehicle may result in a wheel off.
This condition may lead to a crash.

Description of the Cause : Engineering Error

Identification of Any Warning : None
that can Occur :**Involved Components :**

Component Name 1 : Axle: 6,000 lbs.

Component Description : Axle: 6,000 lbs.

Component Part Number : N/A

Component Name 2 : Tire: ST235/80R16/E

Component Description : Tire: ST235/80R16/E

Component Part Number : N/A

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On November 21, 2024, the manufacturing plant and engineering contacted Forest River's Office of Corporate Compliance ("OCC") regarding a concern of the axle and tire capacity. A warranty report was not run for this concern.

On November 22, 2024, Forest River's Corporate Committee voted to recall. The 2 affected vehicles are located at Dealers. None are retail sold. Therefore there will not be an owner notification for this recall.

Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to replace both 6,000lb axles and ST235/80R16/E tires with 7,000lb axles and ST235/85R16/G tires.

What is the Forest River Customer Service Phone Number? (260) 593-4000

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:

Cedar Creek
501 Hawpatch Dr.
Topeka, IN 46571

How Remedy Component Differs from Recalled Component : Affected Component - Axle: 6,000 lbs.
Affected Component – Tire: ST235/80R16/E
The axles will now be adequate for the vehicle. 7,000lb axles and ST235/80R16/G tires will be installed on this model.

Identify How/When Recall Condition was Corrected in Production : The week of November 21, 2024, the manufacturing plant put a hold on the yard and began changing the axles and tires to the appropriate size.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : DEC 31, 2024 - DEC 31, 2024

Planned Owner Notification Date : NR - NR

* NR - Not Reported