

# Part 573 Safety Recall Report

## 25V-171

**Manufacturer Name :** Thor Motor Coach**Submission Date :** MAR 25, 2025**NHTSA Recall No. :** 25V-171**Manufacturer Recall No. :** RC000325**Manufacturer Information :****Population :**

Manufacturer Name : Thor Motor Coach

Number of potentially involved : 4,251

Address : PO Box 1486

Estimated percentage with defect : 100 %

701 County Road 15 Elkhart IN 46515

Company phone : 877-500-1020

**Vehicle Information :**

Vehicle 1 : 2023-2026 Thor Motor Coach Axis

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 &amp; E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : MAR 06, 2023 - MAR 05, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 2 : 2023-2026 Thor Motor Coach Chateau

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 &amp; E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : FEB 27, 2023 - MAR 11, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 3 : 2023-2025 Thor Motor Coach Coleman

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 &amp; E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : MAY 22, 2023 - MAR 11, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 4 : 2023-2025 Thor Motor Coach Echelon

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : FEB 08, 2023 - FEB 20, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 5 : 2025-2025 Thor Motor Coach Eddie Bauer

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : FEB 19, 2024 - MAR 10, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 6 : 2023-2026 Thor Motor Coach Four Winds

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : FEB 23, 2023 - MAR 11, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 7 : 2023-2025 Thor Motor Coach Freedom Elite

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : FEB 08, 2023 - FEB 28, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 8 : 2025-2025 Thor Motor Coach Freedom Traveler

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : SEP 09, 2024 - MAR 11, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 9 : 2023-2025 Thor Motor Coach Geneva

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : FEB 08, 2023 - MAR 10, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 10 : 2024-2025 Thor Motor Coach Magnitude

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : AUG 22, 2023 - OCT 22, 2024

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 11 : 2023-2025 Thor Motor Coach Outlaw

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : MAR 06, 2023 - FEB 26, 2025

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 12 : 2025-2025 Thor Motor Coach Pasadena  
Vehicle Type :  
Body Style :  
Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : DEC 13, 2024 - FEB 13, 2025

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 13 : 2023-2025 Thor Motor Coach Quantum  
Vehicle Type :  
Body Style :  
Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : FEB 23, 2023 - MAR 10, 2025

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Vehicle 14 : 2023-2025 Thor Motor Coach Vegas  
Vehicle Type :  
Body Style :  
Power Train : NR

Descriptive Information : All vehicles built on the Ford E350 & E450 chassis are included in this recall. Vehicles produced after this date have a correct wiring harness installed.

Production Dates : MAR 06, 2023 - MAR 11, 2025

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

Description of Defect :

Description of the Defect : The slideout may have the ability to operate without the Park Brake engaged.  
FMVSS 1 : NR  
FMVSS 2 : NR

Description of the Safety Risk : The slideout could deploy while the vehicle is in motion which could lead to obstructed view and potentially lead to an accident, property damage, and/or personal injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : With the engine running, the transmission in park, and the parking brake disengaged, attempt to cycle the slideout rooms. If the slideout moves then the wire harness is miswired. Do not push the slideout button while the vehicle is in motion.

Involved Components :

Component Name 1 : Park Brake harness

Component Description : Ford Park Brake harness

Component Part Number : 0526855

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

- 3/10 – TMC wire harness department identified the park brake wire harness pinning was incorrect for the E350 & E450 products.
- 3/11 – TMC engineering drafted and published an updated print for production.
- 3/11 – TMC engineering generated a product scope based on the release of the incorrect print.
- 3/14 – TMC safety committee voted for a recall to correct all affected products

Description of Remedy :

- Description of Remedy Program : TMC will replace the incorrect park brake harness free of charge to owners. Reimbursement will follow the general reimbursement plan on file with NHTSA.
- How Remedy Component Differs from Recalled Component : The Park Brake harness (TMC p/n 0526855) should be wired/pinned in a manner that will not allow the slideout to operate while the Park Brake is disengaged.
- Identify How/When Recall Condition was Corrected in Production : The wire harness department discovered the incorrect park brake harness production on 3/10/2025. Starting on 3/11/2025 engineering drafted and published an updated print to correct the defect.

Recall Schedule :

Description of Recall Schedule : Thor Motor Coach has the utmost urgency in notifying owners about a

recall that affects their vehicle. Letters will be sent out once all pertinent information has been gathered.

Planned Dealer Notification Date : MAY 05, 2025 - MAY 05, 2025

Planned Owner Notification Date : MAY 05, 2025 - MAY 05, 2025

\* NR - Not Reported