

U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report

25V321

Manufacturer Name: Keystone RV Company

Submission Date: May 15, 2025

NHTSA Recall No.: 25V321

Manufacturer Recall No.: 25-468

Manufacturer Information

Population

Manufacturer Name: Keystone RV Company

Address: PO Box 2000

2642 Hackberry Drive Goshen IN, 46527 Total number of potentially involved: 248

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2024-2025 Keystone Voltage 4135, 4225

Product Category: Trailers

Product Type:

Fuel / Propulsion:

Production Dates: May 20, 2024 - Apr 15, 2025

Number of potentially involved:

Descriptive Information:

Affected models. Voltage unit count 35

Vehicle 2: 2025-2025 Keystone Springdale 266DECK

Product Category: Trailers

Product Type: Fuel / Propulsion:

Production Dates: Aug 27, 2024 - Dec 11, 2024

Number of potentially involved:

Descriptive Information:

Affected model.

Springdale unit count 12

Vehicle 3: 2025-2025 Keystone Retreat, 391FSRL, 39FSRL

25V321

Product Category: Trailers

Product Type:

Fuel / Propulsion:

Production Dates: Jul 17, 2024 - Feb 20, 2025

Number of potentially involved:

Descriptive Information:

Affected models. Retreat unit count 29

Vehicle 4: 2025-2025 Keystone Residence 401FLFT, 401FSRL, 40FLFT, 40FSRL

Product Category: Trailers

Product Type: Fuel / Propulsion:

Production Dates: Jun 06, 2024 - Feb 21, 2025

Number of potentially involved:

Descriptive Information:

Affected models.

Residence unit count 41.

Vehicle 5: 2024-2024 Keystone Raptor

Product Category: Trailers

Product Type: Fuel / Propulsion:

Production Dates: May 14, 2024 - May 29, 2024

Number of potentially involved:

Descriptive Information:

All models.

Raptor unit count 26

Vehicle 6: 2025-2025 Keystone Hideout 26PATIO

Product Category: Trailers

Product Type: Fuel / Propulsion:

Production Dates: Aug 26, 2024 - Dec 02, 2024

25V321

Number of potentially involved:

Descriptive Information:

Affected model. Hideout unit count 19.

Vehicle 7: 2024-2025 Keystone Fuzion

Product Category: Trailers

Product Type:

Fuel / Propulsion:

Production Dates: May 08, 2024 - Dec 05, 2024

Number of potentially involved:

Descriptive Information:

All models.

Fuzion unit count 86

Defect / Noncompliance Description

Description of the defect or noncompliance:

It has been decided that the vehicles in the recall population may have steps that can detach while in use.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Under certain conditions during use the receiver may come loose and disengage from the bracket leading to an increased risk of personal injury,

Description of the cause:

The receiver for the step was not installed with the required thread locking compound.

Identification of any warning that can occur:

The step receiver will become loose.

Component Manufacturer

Tier of Supplier:

25V321

Supplier Type:

Name: MorRyde

Address: 1966 Sterling Avenue

Elkhart, IN, 46516

Country: United States

Involved Components

Component Name 1: Step

Component Description: Step-Entrance - 4 Step - Clip On - 23.5" Tread - Front Mount - Patio - New

Clip On

Component Part Number: 713012

Component Name 2: Step

Component Description: Step - 19 1/2" Tread - Tall - 3 Step - Front Mount - w/2 Wall Plates - For

Patio Ramp Door - Skid

Component Part Number: 729754

Component Name 3: Ramp Door

Component Description: Garage - Ramp Door - 93.845" x 97.423" - Side Exit - Swing Around - 2.0 -

No Brackets - Black - Designed for Patio Railing Kit

Component Part Number: 645991

Component Name 4: Ramp Door

Component Description: Garage - Ramp Door - 90"W x 82"H - For Rear Patio - Hydrosafe - White

Component Part Number: 747728

Component Name 5: Ramp Door

Component Description: Garage - Ramp Door - Polar White - 93.595" x 97.423" - w/Patio - Zero

Gravity - Weatherproof Core

Component Part Number: 701281

Chronology

4/21/2025 – Report was made email from Vendor. 4/23/2025 – Investigation opened. All affected units had left the facility. All stock parts were inspected and corrected. 4/23/2025 – Warranty claims for step

25V321

detaching include 0 claims. 05/07/2025 – Keystone Safety Committee reviewed the information and concluded that the data reviewed indicated a unanimous vote for a voluntary recall. Investigation called for to determine affected unit range. 05/13/2025 – Investigation concluded and scope completed.

Related NHTSA Recall Number:
Description of Remedy
Remedy Type:
Consumer Advisories: Do Not Drive Park Outside
Description of remedy program:
The remedy is installing a new bracket and hardware. Manufacturer Reimbursement Plan on file as of 10/3/2024. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.
How remedy component differs from recalled component:
The remedy components will be verified to have the required thread locking fluid. Clip on Bracket STP57-515 / STP-641
Identify how/when recall condition was corrected in production:
Parts were quarantined, inspected then repaired as indicated by inspection.
Reimbursement Plan
Description of reimbursement program:
Period of reimbursement:
Costs to be reimbursed:
Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

25V321

☐ No Dealers
☐ No Owners
Phased Recall