OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 19V-163

Manufacturer Name: LDV, Inc.

**Submission Date:** MAR 04, 2019

NHTSA Recall No.: 19V-163

Manufacturer Recall No.: NR



#### **Manufacturer Information:**

Manufacturer Name: LDV, Inc.

Address: 180 Industrial Drive

**Burlington WI 53105** 

Company phone: 800-558-5986

## **Population:**

Number of potentially involved: Estimated percentage with defect: 100 %

#### **Vehicle Alterer Information:**

Vehicle 1: 2017-2018 Ford F550

Descriptive Information: Please See attached Spreadsheet for Various Makes and Models

Production Dates: FEB 21, 2018 - NOV 30, 2018

#### **Description of Defect:**

Description of the Defect: For the recall population, the brake light may activate if there is a transient

voltage on the brake input line (e.g., without further brake input), but can be returned to normal operation when a brake input is applied and then removed. Whelen determined that the root cause of this condition was tied to transient voltage on the input line creating a false and steady activation of the brake light. The condition is dependent on the specific wiring of the vehicle and other installed equipment. The product functions normally if it is not exposed to these specific conditions, but the condition has the potential to occur in the

entire recall population.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: For the recall population, the brake light may activate if there is a transient

voltage on the brake input line (e.g., without further brake input), but can be

returned to normal operation when a brake input is applied and then

removed.

Description of the Cause: Transient voltage on the input line.

**Identification of Any Warning None** 

that can Occur:

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: Whelen Engineering Co Inc.

Address: 51 Winthrop Rd

Chester CONNECTICUT 06475

**Country: United States** 

## **Chronology:**

NR

#### **Description of Remedy:**

Description of Remedy Program: NR

How Remedy Component Differs NR

from Recalled Component :

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

#### **Purchaser Information:**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name:

Address:

Country:

Company Phone:

<sup>\*</sup> NR - Not Reported