OMB Control No.: 2127-0004

Not sequential

## Part 573 Safety Recall Report

### 19V-395

Manufacturer Name: Forest River, Inc.
Submission Date: MAY 24, 2019
NHTSA Recall No.: 19V-395
Manufacturer Recall No.: 05-1021



#### **Manufacturer Information:**

#### **Population:**

Manufacturer Name: Forest River, Inc.

Number of potentially involved: 2

Address: 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone: 1-800-348-7440

#### **Vehicle Information:**

Vehicle 1: 2018-2019 Forest River Starcraft Bus All Star XL

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style:

Power Train: DIESEL

Descriptive Information: Forest River identified the scope of the recall using the VIN's provided by Cummins,

Inc.

ALL STAR XL - 2

Production Dates: OCT 12, 2017 - JUL 30, 2018

VIN Range 1: Begin: NR End: NR

#### **Description of Defect:**

Description of the Defect: As stated by the defect notice received by Cummins, Inc. per recall 19E020:

"Fuel module options FS90301 and FS90453 contain an electric fuel heater. Internal electrical arcing within the fuel heater may create sufficient heat inside the fuel heater to cause plastic in the fuel heater to melt and potentially

catch fire. It may also cause an engine stall. A fire, if undetected and

uncontained, presents an increased risk of personal injury."

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: As stated by the defect notice received by Cummins, Inc. per recall 19E020:

"An unexpected engine stall may increase the risk of a crash."

Description of the Cause: NR

Identification of Any Warning As stated by the defect notice received by Cummins, Inc. per recall 19E020: "If

that can Occur: this condition exists, melting of the fuel heater may be visible during a service

event, smoke may precede or accompany a fire or the engine may become

The information contained in this report was submitted pursuant to 49 CFR §573

increasingly difficult to start."

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: NR

Address: NR

NR

Country: NR

#### **Chronology:**

On May 20, 2019 Forest River's Office of Corporate Compliance ("OCC") received a recall notice from Cumming, Inc.

On May 22, 2019 Forest River OCC began to identify vehicles affected.

On May 24, 2019 Forest River conducted a pass thru recall submission.

#### **Description of Remedy:**

Description of Remedy Program: What is Cumming, Inc. contact information? Cummins Care at 1-800-

CUMMINS (1-800-286-6467), or visit our website at care.cummins.com

What is the Forest River Customer Service Phone Number? (800)

348-7440

How Remedy Component Differs NR

from Recalled Component :

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull

data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement

Letter.

# **Part 573 Safety Recall Report**

19V-395

Page 3

Planned Dealer Notification Date : JUN 17, 2019 - JUN 17, 2019 Planned Owner Notification Date : JUN 17, 2019 - JUN 17, 2019

\* NR - Not Reported