

Part 573 Safety Recall Report

19V-794

Manufacturer Name : KZRV, L.P.

Submission Date : NOV 05, 2019

NHTSA Recall No. : 19V-794

Manufacturer Recall No. : KZ-2019-02



Manufacturer Information :

Manufacturer Name : KZRV, L.P.

Address : 0985 N 900W

Shipshewana IN 46565

Company phone : 800-768-4016x154/153

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2019-2020 KZ RV Connect

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : These units were produced with an optional flip up rear storage rack which was manufactured by Rock Run.

Production Dates : OCT 16, 2018 - SEP 26, 2019

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : The flip up storage tray was not properly designed for the anticipated loads it may carry. The mounting brackets fail under certain loading scenarios.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The rack and all items on secured to it will detach from the trailer and become scattered on the roadway posing a traffic hazard.

Description of the Cause : The mounting brackets for the storage tray were inadequately designed for the actual loads.

Identification of Any Warning that can Occur : Cracks may be present in the brackets.

Supplier Identification :

Component Manufacturer

Name : Rock Run Repair
Address : 11665 W 600 S
Millersburgh INDIANA 46507
Country : United States

Chronology :

10/24/2019 - A dealer notifies KZ of a bracket failure which resulted in the rack and all materials loaded on it to spill into the roadway while a customer was in transit. The warranty initiates an investigation into similar complaints.

10/31/2019 - The safety committee meets to review the data and the decisions is made to issue a recall.

Description of Remedy :

Description of Remedy Program : Change the existing rack and bracket to a redesigned version.

How Remedy Component Differs from Recalled Component : The bracket has been redesigned.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : KZ will notify the dealers and owners of these recreational vehicles by letter. A final copy of the owner letter and dealer repair instructions will be provided to NHTSA.

Planned Dealer Notification Date : JAN 04, 2020 - JAN 04, 2020

Planned Owner Notification Date : JAN 04, 2020 - JAN 04, 2020

* NR - Not Reported