OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-854

Manufacturer Name: REV Ambulance Group Orlando, INC.

Submission Date: DEC 02, 2019 **NHTSA Recall No.:** 19V-854

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: REV Ambulance Group Orlando, INC.

Address: 2737 N. Forsyth Road

Winter Park FL 32792

Company phone: 800-628-8178

Population:

Number of potentially involved : 4 Estimated percentage with defect : 100%

Vehicle Information:

Vehicle 1: 2018-2019 Wheeled Coach Type 1 Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: Ziamatic Corp. provided serial number suspect, D Cylinder bracket.

Production Dates: MAY 01, 2018 - AUG 01, 2018

Description of Defect:

Description of the Defect: Depending upon how the product has been installed in an ambulance, if the

ambulance is impacted at a very specific angle while traveling at a high speed, the D-cylinder oxygen tank and/or bracket may come loose and become airborne, creating a risk of injury to passengers, or damage to the contents of

the ambulance.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Depending upon how the product has been installed in an ambulance, if the

ambulance is impacted (in a collision) at a very specific angle, while travelling at a high speed, the D-Cylinder oxygen tank and/or bracket may come loose and become airborne, creating a risk of injury to passengers or damage to the

contents of the ambulance.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: Ziamatic Corp

Address: 10 West College Ave

P.O. Box 337 Yardley PENNSYLVANIA 19067

Country: United States

Chronology:

REV Group Orlando, INC received notification during the month of October form Ziamatic recall. Due to unexpected emergency medical leave from the person responsible to submit notice, the filing of this report was delayed until the end of November.

Description of Remedy:

Description of Remedy Program: Ziamatic's recall program includes a commitment to refund the purchase

price paid to each of its customers-distributors or to provide an alternative replacement product (which has a higher retail price) at no additional cost

to the customer-distributors so they may then provide refunds or

replacements to end users. Ziamatic will require the end-users to return the model QR-TDS or model QR-D-S products to Ziamatic as part of the $\,$

recall so that Ziamatic may destroy and discard the recalled products.

How Remedy Component Differs The two recalled products are: (1) a "Quick Release Slide Out D Cylinder

from Recalled Component : Bracket", Model number QR-D-S; and (2) a "Twin Slide Out D Cylinder Bracket with Mounting Stand", model number QR-TDS. Both are bracket

assemblies that are attached to the inside of ambulances to hold D-Cylinder oxygen tanks. The bracket assembly that is being offered by Ziamatic as a replacement for model numbers QR-D-S and QR-TDS is made

of stainless steel, whereas model numbers QR-D-S and QR-TDS are made

of a plastic material.

Identify How/When Recall Condition Since so few of the two products (model QR-D-S and QR-TDS) were sold or was Corrected in Production: put into circulation, Ziamatic decided to permanently discontinue those

products rather than attempt to modify them.

Recall Schedule:

Description of Recall Schedule: We will not be notifying dealers. We will notify owners during the month

of December.

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: DEC 09, 2019 - DEC 31, 2019

Part 573 Safety Recall Report	19V-854	Page 3
* NR - Not Reported		
The information contained in this report was submitte	d pursuant to 49 CFR §573	